

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Oil Co. Inc.  
N.M. DIV-Dist. 2  
1301 W. Grand Avenue  
Artesia, NM 88210

FORM APPROVED  
OMB NO. 1004-0135  
Expires: November 30, 2000

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

5. Lease Serial No. 479142  
If Indian, Allottee or Tribe Name

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Phillips Petroleum Company

3a. Address

4001 Penbrook Street, Odessa, TX 79762

3b. Phone (include area code)  
(915) 368-1488

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UNIT F, 1980' FNL & 1980' FWL OF SEC. 12,  
T-22-S, R-30-E

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

JAMES -E- #14

9. API Well No.

30-015-26646

10. Field and Pool, or Exploratory Area  
CABIN LAKE (DELAWARE)

11. County or Parish, State

EDDY NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- |   |   |  |  |
|---|---|--|--|
| <input type="checkbox"/> Acidize              | <input type="checkbox"/> Deepen           | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off                    |
| <input type="checkbox"/> Alter Casing         | <input type="checkbox"/> Fracture Treat   | <input type="checkbox"/> Reclamation               | <input type="checkbox"/> Well Integrity                    |
| <input type="checkbox"/> Casing Repair        | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete                | <input checked="" type="checkbox"/> Other <u>RE-ENTER,</u> |
| <input type="checkbox"/> Change Plans         | <input type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon       | <u>FISH, &amp; REACTIVATE</u>                              |
| <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back        | <input type="checkbox"/> Water Disposal            | <u>WELL</u>  |

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximated duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

9/16/01 MI RU POOL DDU #682. NIPPLE UP BOP, UNLOAD, TALLY, 2 7/8 WORK STG. PICK UP BIT, DRILL COLLARS & GIH. TAG TOP OF CIBP @ 5750', BREAK CIRC TO PIT, BEGIN DRILLING ON CIBP FOR 30-40 MIN, LOST CIRC. TOOK ALL WATER, TOP OFF PIT & RESUME PUMPING FINALLY GOT CIRC AROUND. PUMPING 4 BPM, GETTING BACK 1 BPM. GETTING WELL CHARGED UP. WAITING ON WATER. SISD.

9/17/01 DRILL ON CIBP, CUT TOP OUT OF PLUG, LOST CIRC RAN OUT OF WATER. NO WATER AVAILABLE. PULL UP ABOVE PERFS & SHUT DOWN, MOVE IN FRAC TANK & FILL UP WITH WATER FROM OUTSIDE SOURCE.

9/18/01 GIT TAG CIBP, BREAK CIRC TO SURFACE, 4 BPM DOWN, 1.5 BPM UP, & START DRILLING UP, TAG TOC AT 7260 & DRILL UP TO TOP OF FISH. CIRC WELL CLEAN. CIRC GETTING BETTER, LOOSING @ 4.5 BBL PER HOUR. WELL IS CHARGED UP. COOH, LAY DOWN BIT & PICK UP MILL SHOE. GIH SHUT DOWN.

9/19/01 SET DOWN ON FISH & BEGIN MILLING, MAKING HOLE, @ 14'. MILL ACTING UP COOH TO CHECK MILL, GOT OUT WITH THE X OVER & TOP OF MILL SHOE. GIH w/MILL & WASH PIPE. SISD.

9/20/01 SET DN ON FISH & START MILLING. MAKING HOLE. MADE 14", MILL ACTING UP COOH & CHECK MILL, GIH w/NEW MILL & WASH PIPE TO 5000'. SISD.

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

L. M. SANDERS

Title

SUPERVISOR, REGULATION/PRODUCTION

Date

10/29/01

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

# **James 'E' #14**

***(Continued)***

**9/23/01** HOLD SAFETY MEETING. GIH w/NEW MILL AND MILL ON FISH, MILLED ABOUT 4-5 HRS, MADE 12" , MILL ACTING UP AND TORQUEING UP. COOH w/TBG & DRILL COLLARS, ETC. SISD.

**9/24/01** GIH w/NEW MILL, & MILL ON FISH. MILL ON FISH 4-5 HRS, MADE 9", MILL ACTING UP, COOH. SISD.

**9/25/01** HOLD SAFETY MEETING. FINISH GOING IN HOLE w/MILL, COLLARS, TBG, ETC. MILL ON FISH. HAD TO RECUT 10", MADE 10". MILL QUIT CUTTING, STARTED TO SPIN & NOT MAKING HOLE. COOH w/TBG, COLLARS, MILL. MILL WORE OUT. GIH w/BOX TAP w/3-3/4-3" TAPERED THREADS. RAN IN ABOVE PERFS & SISD.

**9/26/01** HOLD SAFETY MEETING. GIH w/REST OF TBG TO FISH ON FISH. SET ON & WORKED ON FISH. TAG @ 7297' & WORKED BOX TAP DN TO 7308'. COOH w/TBG & BOX TAP. DID NOT CATCH FISH. GIH w/SHOE, & MILL ON FISH. CUT FROM 798' TO 7308'. CIRCULATE HOLE CLEAN. COOH w/50 JTS, SISD.

**9/27/01** HOLD SAFETY MEETING. FINISH COOH w/TBG, COLLARS, JARS, BUMPER SUB, & SHOE. DID NOT HAVE ANYTHING ON SHOE. GIH w/SHORT CATCH OVERSHOT. TAG w/OVERSHOT @ 7301'. WORKED OVERSHOT DN TO 7302-4'. COOH TBG & OVERSHOT. HAD 2-1/2" PIECE OF OLD SHOE IN OVERSHOT. DID NOT COME OUT w/BOTTOM OF SHOE. GIH w/SHOE. MILL TAG @ 7302' MILL TO 7310', CIRCULATE HOLE CLEAN. COOH ABOVE PERFS. SISD.

**9/30/01** HOLD SAFETY MEETING. GIH w/TBG w/SHOE AND MILL. MADE 10', SHOE ACTING UP. 7310' - 7320' +, -. COOH w/TBG & SHOE. BROUGHT OUT 20' SECTION OF CEMENT CORE. GIH w/BIT & TBG. TAG @ 7360'. DID NOT ROTATE BIT, TAG TOP OF RBP. CIRCULATED HOLE CLEAN, BROUGHT BACK APROX. 5 GAL OF SAND. COOH w/TBB & BIT. SISD.

**10/01/01** HOLD SAFETY MEETING. GIH w/COLLARS, JARS, ON/OFF TOOL. CIRCULATE & WASH SAND OFF RBP @ 7360'. LATCH UP ON RBP & RELEASE RBP. COOH & LAY DN RBP. GIH w/BIT & COLLARS & CLEAN HOLE TO 7668'. START COOH w/TBG. SISD.

**10/2/01** LAY DN DRILL COLLARS. PICK UP RBP & PKR GIH, SET RBP AT 7600', PULL UP & SET PKR AT 7333'. SWAB TEST PERFS; 7394-7404', 7444-7510', 7546-7560'. FLUID AT 1800' FROM SURFACE SWAB BACK 55 WATER, 0 OIL, LAST FLUID LEVEL AT 2900'.

20-01-02 2-10-02

HEO-01