

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

JUL 26 1993

WELL API NO. 30-015-26764
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name East Loving SWD
8. Well No. 1
9. Pool name or Wildcat SWD Del. East Loving Brushy Canyon

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER SWD	
2. Name of Operator Bird Creek Resources, Inc.	
3. Address of Operator 1412 South Boston, Suite 550, Tulsa, OK 74119	
4. Well Location Unit Letter <u>A</u> : <u>1157</u> Feet From The <u>North</u> Line and <u>491</u> Feet From The <u>East</u> Line Section <u>15</u> Township <u>23 South</u> Range <u>28 East</u> NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3001' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/9/93 Kill well w/polymer plug
7/12/93 Dig reserve pit. RU Pride Well Service and begin flow back. NU BOP. Pull 60 jts 2 7/8" fiberglass tbg. RIH w/overshot. Retrieve 3 jts fiberglass tbg. RIH w/overshot and latch on to tbg. Unable to release on/off tool. Back off 2 7/8" fiberglass tbg. POOH. Retrieve 20 jts fiberglass tbg. RIH w/2 7/8" work string and screen into fiberglass tbg RU Jarrel Services. Shot fiberglass tbg. off 1' above on/off tools. POOH. No fiberglass tbg.
7/13/93 RIH w/overshot and catch 2 7/8" fiberglass tbg. POOH and lay down all tbg. RIH w/7" X 23" X 2 7/8" lock set, 2.25 profile nipple, 7" X 2 7/8" on/off tool (nickel plate and 129 jts 2 7/8" ceramakote steel tbg. Set packer @ 4053'. NU wellhead. Pull blanking plug and test all tubulars. OK. Turn on injection system.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE H. Ric Hedges TITLE President DATE 7/20/93
TYPE OR PRINT NAME H. Ric Hedges TELEPHONE NO. (918) 582-7713

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE JUL 29 1993
CONDITIONS OF APPROVAL, IF ANY: