| UNIT N  |  |  | EDDY, NM   |                    |
|---|--|--|--|--------------------|
| CHE   | CK APPROPRIATE BOX(s) T  | O INDICATE NATURE OF NOTIO   | CE. REPORT, OR OTHER DATA  | 4                  |
|   | OF SUBMISSION  |  | OF ACTION  |                    |
|   | Nice of Intent   |  | Change of Plans  |                    |
| ΩΩ  |  | <b>KX</b> Recompletion   | New Construction   |                    |
| E Su  | bsequent Report  | Plugging Back  | Water Shut-Off   |                    |
| 🗌 Fir   | nal Abandonment Notice   | Altering Casing  | Conversion to Injection  |                    |
|   |  | U Other  | (Note: Report results of multiple co   | maktion on Well    |
|   | e locations and measured and true vertical dep<br>SED  | nent details, and give pertinent dates, including estimat<br>sths for all markers and zones pertinent to this work,<br>rations   | •  |                    |
| give subsurface<br>PROPO:<br><u>OPERA</u><br>1. F<br>2. T<br>3. S<br>4. F<br>5. F<br>6. F<br>d<br>D                   | e locations and measured and true vertical dep<br>SED<br><u>TION:</u> Acidize Wolfçamp Perfo<br>RU Halliburton acid trucks and coiled-th<br>TIH w/coiled tbg to 11,568' (bottom of p<br>Spot 5 bbls 20% gelled HCI acid. Displ<br>Pump away spot acid by pumping 5 bbl<br>Flow back well for couple of hours to cl<br>RU and acidize perfs by pumping 5,00   | ouths for all markers and zones pertinent to this work.<br>prations<br>by unit.<br>berfs).<br>lace to spot with 10# brine. TOH w/coiled th<br>ls 10# brine down tbg.<br>ear tbg of wtr.<br>0 gals 20% gelled HCI carrying +/- 100 ball s<br>w/10# brine. Anticipate a treating pressure of | DIST. 2  | cctionally drilled |
| give subsurface<br><u>PROPO:</u><br><u>OPERA</u><br>1. F<br>2. T<br>3. S<br>4. F<br>5. F<br>6. F<br>6. F<br>0<br>7. F | e locations and measured and true vertical dep<br><u>FION:</u> Acidize Wolfçamp Perfo<br>RU Halliburton acid trucks and coiled-th<br>TIH w/coiled tbg to 11,568' (bottom of p<br>Spot 5 bbls 20% gelled HCI acid. Displ<br>Pump away spot acid by pumping 5 bbl<br>Flow back well for couple of hours to cl<br>RU and acidize perfs by pumping 5,00<br>lown tbg at a rate of 5 - 7 BPM. Flush v<br>si. | ouths for all markers and zones pertinent to this work.<br>prations<br>by unit.<br>berfs).<br>lace to spot with 10# brine. TOH w/coiled th<br>ls 10# brine down tbg.<br>ear tbg of wtr.<br>0 gals 20% gelled HCI carrying +/- 100 ball s<br>w/10# brine. Anticipate a treating pressure of | A date of starting any proposed work. If well is dire<br>SEGENVED<br>JUL 2 1 1903<br>UL CON. DIV.<br>DIST. 2<br>Palers | cctionally drilled |