Form 2160 C			·
Form 3160-5 (June 1990)		TED STATES	FORM APPROVED
· · · · · · · · · · · · · · · · · · ·	DEPARTMENT OF THE INTERIOR		Budget Bureau No. 1004-0135 Expires: March 31, 1993
	BUREAU OF	LAND MANAGEMENT	5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS			NM-94651
Do not use this form	for proposals to dri	ill or to deepen or reentry to a different reservoi R PERMIT—" for such proposals	<ol> <li>If Indian, Allottee or Tribe Name</li> <li>r.</li> </ol>
I. Type of Well	SUBMIT	IN TRIPLICATE	7. If Unit or CA, Agreement Designation
Oil Gas Well Well	Other		8. Well Name and No.
2. Name of Operator	-		Cedar Canyon 28 Federal
Pogo Producing Company 3. Address and Telephone No.			9. API Well No.
			30-015-28723
P. O. Box 10340, Midland, TX 79702-7340 (915)682-6822 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			10. Field and Pool, or Exploratory Area
the terminet and	Undes Corral Draw Delaw		
230' FNL & 2510' FWL, Section 28, T24S, R29E			11. County or Parish, State Eddy County, NM
2. CHECK APP	PROPRIATE BOX(s	) TO INDICATE NATURE OF NOTICE, REPO	
TYPE OF SUB	MISSION	TYPE OF ACTION	
Notice of Inten	11		
_			Change of Plans
Subsequent Rep	port	Plugging Back	New Construction
		Casing Repair	Water Shut-Off
Final Abandon:	ment Notice	Altering Casing	Conversion to Injection
		X Other <u>Set Production</u> Casi	ng Dispose Water
	_		(Note: Report results of multiple completion on Well
<ul> <li>Describe Proposed or Completed give subsurface locations as</li> </ul>	d Operations (Clearly state all p and measured and true vertical	ertinent details, and give pertinent dates, including estimated date of startin depths for all markers and zones pertinent to this work.)*	Completion or Recompletion Report and Log form.) ng any proposed work. If well is directionally drilled
	•		
			,
			n an
Schlumberger. Ran 693'. Stage tools KCl + .6% H322 @ rs between stages. .4 pps KCl + .6% H rs between stages.	n 173 jts 4-1/2" © @ 6008' & 3975' 15.6 ppg. Drop . Recovered 40 322 @ 15.6 ppg. . Recov 66 sxs	hole to 7740'. TD reached @ 1945 hr 11.60# J-55 & N-80 LT&C csg. Float '. Howco cmt'd 1st stage w/ 240 sx Cl plug. Float held. Drop bomb & open sxs excess cmt. Cmt 2nd stage w/ 410 Drop plug. Float held. Drop bomb & exces cmt. Cmt 3rd stage w/ 390 sxs 14.1 ppg. Plug down @ 0930 hrs CST	<pre>s CST 12/23/95. Logged we shoe @ 7740'. Float coll "H" + 5 pps Microbond + 2 DV tool @ 6008'. Circulat sx Cl "H" + 5 pps Microbo open DV tool @ 3975'. Ci Cl "C" + 12 pps Cilconite</pre>
Schlumberger. Ran 593'. Stage tools KCl + .6% H322 @ rs between stages. .4 pps KCl + .6% H rs between stages. pps KCl + .3% H3;	n 173 jts 4-1/2" © @ 6008' & 3975' 15.6 ppg. Drop . Recovered 40 1322 @ 15.6 ppg. . Recov 66 sxs 22 + .3% H344 @	' 11.60# J-55 & N-80 LT&C csg. Float '. Howco cmt'd 1st stage w/ 240 sx C1 plug. Float held. Drop bomb & open sxs excess cmt. Cmt 2nd stage w/ 410 Drop plug. Float held. Drop bomb &	<pre>s CST 12/23/95. Logged we shoe @ 7740'. Float coll. "H" + 5 pps Microbond + 2 DV tool @ 6008'. Circulate sx Cl "H" + 5 pps Microbol open DV tool @ 3975'. Ci: Cl "C" + 12 pps Cilconite</pre>
Schlumberger. Ran 693'. Stage tools KCl + .6% H322 @ rs between stages. .4 pps KCl + .6% H rs between stages. pps KCl + .3% H3;	n 173 jts 4-1/2" © @ 6008' & 3975' 15.6 ppg. Drop . Recovered 40 1322 @ 15.6 ppg. . Recov 66 sxs 22 + .3% H344 @	<pre>' 11.60# J-55 &amp; N-80 LT&amp;C csg. Float '. Howco cmt'd 1st stage w/ 240 sx Cl plug. Float held. Drop bomb &amp; open sxs excess cmt. Cmt 2nd stage w/ 410 Drop plug. Float held. Drop bomb &amp; exces cmt. Cmt 3rd stage w/ 390 sxs 14.1 ppg. Plug down @ 0930 hrs CST</pre>	<pre>s CST 12/23/95. Logged we shoe @ 7740'. Float coll "H" + 5 pps Microbond + 2 DV tool @ 6008'. Circulat sx Cl "H" + 5 pps Microbo open DV tool @ 3975'. Ci Cl "C" + 12 pps Cilconite</pre>
Schlumberger. Ran 693'. Stage tools KCl + .6% H322 @ rs between stages. .4 pps KCl + .6% H rs between stages. pps KCl + .3% H3;	n 173 jts 4-1/2" © @ 6008' & 3975' 15.6 ppg. Drop . Recovered 40 1322 @ 15.6 ppg. . Recov 66 sxs 22 + .3% H344 @	<pre>' 11.60# J-55 &amp; N-80 LT&amp;C csg. Float '. Howco cmt'd 1st stage w/ 240 sx Cl plug. Float held. Drop bomb &amp; open sxs excess cmt. Cmt 2nd stage w/ 410 Drop plug. Float held. Drop bomb &amp; exces cmt. Cmt 3rd stage w/ 390 sxs 14.1 ppg. Plug down @ 0930 hrs CST</pre>	<pre>s CST 12/23/95. Logged we shoe @ 7740'. Float coll "H" + 5 pps Microbond + 2 DV tool @ 6008'. Circulat sx Cl "H" + 5 pps Microbo open DV tool @ 3975'. Ci Cl "C" + 12 pps Cilconite</pre>
Schlumberger. Ran 693'. Stage tools KCl + .6% H322 @ rs between stages. .4 pps KCl + .6% H rs between stages pps KCl + .3% H33 's. Set slips & m	n 173 jts 4-1/2" © 6008' & 3975 15.6 ppg. Drop . Recovered 40 1322 @ 15.6 ppg. . Recov 66 sxs 22 + .3% H344 @ nake cut-off. W	<pre>' 11.60# J-55 &amp; N-80 LT&amp;C csg. Float '. Howco cmt'd 1st stage w/ 240 sx Cl plug. Float held. Drop bomb &amp; open sxs excess cmt. Cmt 2nd stage w/ 410 Drop plug. Float held. Drop bomb &amp; exces cmt. Cmt 3rd stage w/ 390 sxs 14.1 ppg. Plug down @ 0930 hrs CST</pre>	<pre>s CST 12/23/95. Logged we shoe @ 7740'. Float coll. "H" + 5 pps Microbond + 2 DV tool @ 6008'. Circulate sx Cl "H" + 5 pps Microbol open DV tool @ 3975'. Ci: Cl "C" + 12 pps Cilconite</pre>
Schlumberger. Ran 693'. Stage tools KCl + .6% H322 @ rs between stages. .4 pps KCl + .6% H rs between stages. pps KCl + .3% H3;	n 173 jts 4-1/2" © 6008' & 3975 15.6 ppg. Drop . Recovered 40 1322 @ 15.6 ppg. . Recov 66 sxs 22 + .3% H344 @ nake cut-off. W	<pre>' 11.60# J-55 &amp; N-80 LT&amp;C csg. Float '. Howco cmt'd 1st stage w/ 240 sx Cl plug. Float held. Drop bomb &amp; open sxs excess cmt. Cmt 2nd stage w/ 410 Drop plug. Float held. Drop bomb &amp; exces cmt. Cmt 3rd stage w/ 390 sxs 14.1 ppg. Plug down @ 0930 hrs CST</pre>	<pre>s CST 12/23/95. Logged we shoe @ 7740'. Float coll. "H" + 5 pps Microbond + 2 DV tool @ 6008'. Circulate sx Cl "H" + 5 pps Microbol open DV tool @ 3975'. Ci: Cl "C" + 12 pps Cilconite</pre>
Schlumberger. Ran 693'. Stage tools KCl + .6% H322 @ rs between stages. .4 pps KCl + .6% H rs between stages pps KCl + .3% H33 's. Set slips & n	n 173 jts 4-1/2" © 6008' & 3975' 15.6 ppg. Drop . Recovered 40 1322 @ 15.6 ppg. . Recov 66 sxs 22 + .3% H344 @ nake cut-off. W	<pre>' 11.60# J-55 &amp; N-80 LT&amp;C csg. Float '. Howco cmt'd 1st stage w/ 240 sx Cl plug. Float held. Drop bomb &amp; open sxs excess cmt. Cmt 2nd stage w/ 410 Drop plug. Float held. Drop bomb &amp; exces cmt. Cmt 3rd stage w/ 390 sxs 14.1 ppg. Plug down @ 0930 hrs CST</pre>	s CST 12/23/95. Logged we shoe @ 7740'. Float coll "H" + 5 pps Microbond + 2 DV tool @ 6008'. Circulate sx Cl "H" + 5 pps Microbon open DV tool @ 3975'. Circulate Cl "C" + 12 pps Cilconite
Schlumberger. Ran 693'. Stage tools KCl + .6% H322 @ rs between stages. .4 pps KCl + .6% H rs between stages pps KCl + .3% H33 's. Set slips & m	n 173 jts 4-1/2" © 6008' & 3975' 15.6 ppg. Drop . Recovered 40 1322 @ 15.6 ppg. . Recov 66 sxs 22 + .3% H344 @ nake cut-off. W	11.60# J-55 & N-80 LT&C csg. Float '. Howco cmt'd 1st stage w/ 240 sx Cl plug. Float held. Drop bomb & open sxs excess cmt. Cmt 2nd stage w/ 410 Drop plug. Float held. Drop bomb & exces cmt. Cmt 3rd stage w/ 390 sxs 14.1 ppg. Plug down @ 0930 hrs CST Weld on wellhead & test to 2500 psi.	s CST 12/23/95. Logged we shoe @ 7740'. Float colla "H" + 5 pps Microbond + 2 DV tool @ 6008'. Circulate sx Cl "H" + 5 pps Microbor open DV tool @ 3975'. Cir Cl "C" + 12 pps Gilsonite 12/25/95. TOC @ 1385'. N
Schlumberger. Ran 693'. Stage tools KCl + .6% H322 @ rs between stages. .4 pps KCl + .6% H rs between stages. pps KCl + .3% H33 's. Set slips & n i hereby certify part the foregoing Signed (This space for Federal or State of Approved by	n 173 jts 4-1/2" © 6008' & 3975' 15.6 ppg. Drop . Recovered 40 1322 @ 15.6 ppg. . Recov 66 sxs 22 + .3% H344 @ nake cut-off. W	11.60# J-55 & N-80 LT&C csg. Float '. Howco cmt'd 1st stage w/ 240 sx Cl plug. Float held. Drop bomb & open sxs excess cmt. Cmt 2nd stage w/ 410 Drop plug. Float held. Drop bomb & exces cmt. Cmt 3rd stage w/ 390 sxs 14.1 ppg. Plug down @ 0930 hrs CST Weld on wellhead & test to 2500 psi.	s CST 12/23/95. Logged well shoe @ 7740'. Float colla "H" + 5 pps Microbond + 2. DV tool @ 6008'. Circulate sx Cl "H" + 5 pps Microbor open DV tool @ 3975'. Cir Cl "C" + 12 pps Gilsonite 12/25/95. TOC @ 1385'. N
Schlumberger. Ran 693'. Stage tools KCl + .6% H322 @ rs between stages. .4 pps KCl + .6% H rs between stages. pps KCl + .3% H32 's. Set slips & m I hereby certify part the foregoing Signed	n 173 jts 4-1/2" © 6008' & 3975' 15.6 ppg. Drop . Recovered 40 1322 @ 15.6 ppg. . Recov 66 sxs 22 + .3% H344 @ nake cut-off. W	<ul> <li>11.60# J-55 &amp; N-80 LT&amp;C csg. Float</li> <li>Howco cmt'd 1st stage w/ 240 sx Cl plug. Float held. Drop bomb &amp; open sxs excess cmt. Cmt 2nd stage w/ 410 Drop plug. Float held. Drop bomb &amp; exces cmt. Cmt 3rd stage w/ 390 sxs 14.1 ppg. Plug down @ 0930 hrs CST Weld on wellhead &amp; test to 2500 psi.</li> <li>Title Senior Operations Engineer -</li> </ul>	s CST 12/23/95. Logged wel shoe @ 7740'. Float colla "H" + 5 pps Microbond + 2. DV tool @ 6008'. Circulate sx Cl "H" + 5 pps Microbor open DV tool @ 3975'. Cir Cl "C" + 12 pps Gilsonite 12/25/95. TOC @ 1385'. N

.