

RECOMMENDED WORK PROCEDUREEASE Section 22 Federal # 2 (continued) WELL NO. _____

ANNULAR FLUID PRIOR TO WORKOVER _____ W/O FLUID TO BE USED _____

WT. (LBS/GAL.) _____	ZONE _____	HYD. PRESS _____	RES. PRESS _____
_____	ZONE _____	HYD. PRESS _____	RES. PRESS _____
_____	ZONE _____	HYD. PRESS _____	RES. PRESS _____

20. Acidize zone w/ 1000 gals 7½% NEFE HCL w/ clay stabilizers @ 3-5 BPM.
21. Flush to bottom perf w/ 25 bbls 2% KCL wtr. Obtain ISIP, 5, 15 & 30 MSIP.
22. Swab well. If unproductive and either of the two lower zones are productive then dump sand on RBP, 592 perfs w/ 2 sx cm per hole (2552). Test 592 to 500 psi. Wash sand off RBP. POH w/ RBP & pkr & tbg. RIH w/ tbg, rods & pump. Release well to production.

If productive then frac procedure to be given by Engineer.

After frac POH w/ pkr (and RBP if in the well). RIH w/ tbg, rods & pump. Release well to production.

* Plug back procedure verbally approved by Bob Pitschke - BLM.

M E. Strobel 11-1-85