

Form 9-3-1
May 1969UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLE
(Other Instructions
reverse side)B-
re-Form approved,
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 061616-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

MAR 27 1980

7. UNIT AGREEMENT NAME

Poker Lake Unit

8. FARM OR LEASE NAME

Poker Lake Unit

9. WELL NO.

44

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 10, T25S, R30E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

OIL ☒ GAS ☐ WELL ☐ OTHER ☐

NAME OF OPERATOR

Perry R. Bass

ADDRESS OF OPERATOR

P.O. Box 2760, Midland, Texas 79702

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface:

2030' FNL & 2180' FEL of Sec 10, T25S, R30E
Eddy County, New MexicoU.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

3303' GL

3317' KB

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

FULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OF ALUMINUM

ABANDON*

SHOOTING OF CEMENTIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Precompletion Report and Log form.)DESCRIBE PLUGS AND COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give saturation locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

1. MI & RU PU. Install BOPE w/double rams (2-3/8" rubber, top; blind, bottom).
2. *RIH w/tbg open ended & spot Howco Lite cmt plug (13.1 ppg-1.24 ft³/sk) as follows: 4037' (PBD) to 3359' (top Delaware lime 3920') with 50 sx.
3. RD PU.
4. RU casing pullers.
5. Run free point (calculated top cement 2800').
6. Shoot off casing at free point & pull up to 608'.
7. Spot same Howco Lite cement plug 608-314' (casing shoe 568') with 50 sx.
8. Spot 10 sx plug at surface.
9. Fill in all cellars and clean location.
10. Install dry hole marker

*Well May have 2-3/8" tbg installed. If not, RIH with 2-3/8" workstring & proceed.

Mike Waygood informed the following is required for plugging:

RECEIVED

1. 100' plug (50' in & out) of 5 1/2" csg. stub.
2. 100' plug at csg. shoe 568' to be set with pipe not bigger than 4 1/2" I.D.
3. 25 sx surface plug

4-10-80

George H. Stewart

MAY 29 1980

O. C. D.

ARTESIA, OFFICE

I hereby certify that the foregoing is true and correct.

DATE

DATE

MAY 28 1980

APPROVED BY

SIGNATURES OF APPROVAL, IF ANY: