

12. RIH w/ retainer on 2-7/8" workstring to 1750'. Set retainer and cement squeeze perfs at 1850'. Circulate cement to surface if possible.
13. POOH laying down 2-7/8" work string to 460'.
14. Spot 25 sack balanced cement plug at 460'. Tag plug.
15. POOH laying down 2-7/8" workstring to 60'. Spot cement plug to surface.
16. ND BOP's. RDMOPU.
17. Cut off all casings 3' below ground level. Weld steel plate on top of casing strings.
18. Backfill and install OCD P&A marker.
19. Clean up location.

JDW  
11/06/2001

