

UNITED STATES OIL AND GAS COMMISSION
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Artesia, NM 88210

DATE
ON

Expires August 31, 1985

clsf

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for each proposal.

1. TYPE OF WELL: ☒ OIL, ☐ GAS, ☐ WATER, ☐ OTHER

2. NAME OF OPERATOR: J.C. Williamson

3. ADDRESS OF OPERATOR: P.O. Box 16, Midland, Texas

4. PERMIT NO.: 30-015-25389

5. DATE OF PERMIT: 2993.5 OR

6. RECEIVED BY: O. C. D. ARTESIA, OFFICE

7. FEB 24 1986

8. LEASE DESIGNATION AND SERIAL NO.: NM 0554499

9. IF INDIAN, ALLOTTEE OR TRIBE NAME:

10. UNIT AGREEMENT NAME: Ross Draw Unit

11. FARM OR LEASE NAME: Ross Draw

12. WELL NO.: 15

13. FIELD AND TOWN OR WILDCAT: East Ross Draw

14. Undesignated Delaware

15. SEC., T., R., M., OR BLM. AND SURVEY OR AREA: Sec. 26-26 S-30E

16. COUNTY OR PARISH: Eddy

17. STATE: NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

1. WATER SHUT-OFF ☐

2. WATER SHUT-IN ☐

3. SHUTTING OR ACIDIZING ☐

4. PAIR WELL ☐

5. OTHER ☐

6. WATER SHUT-IN ☐

7. FRACTURE TREATMENT ☐

8. SHUTTING OR ACIDIZING ☐

9. OTHER: Re-work

10. CEASING WELL ☐

11. ALTERING CASING ☐

12. ABANDONMENT* ☐

(Note: Report results of multiple completion on Well Completion or Incompletion Report and Log form.)

13. Explain in detail the nature of the work, including estimated date of starting and proposed completion. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.

- 1) Coil w/rods and tubing.
- 2) Set retrievable BP @ 6200'
- 3) Shoot Delaware zone @ 5935-6045' w/25 holes
- 4) Acidize zone w/2500 gals. 7 1/2% acid.
- 5) Swab well to test tank to test zone.
- 6) Fracture treat zone w/60,000 gals. gelled KCl water; 120,000# sand @ 45 BPM, 1800# pressure.
- 7) Flow back frac to recover sand and to test zone after shutting well in overnight.
- 8) Swab test well when well stops flowing. Kill well and GHI to retrieve BP.
- 9) Run back tubing and rods to 5300' and put well back on production.

ACCEPTED FOR RECORD

GWD
FEB 19 1986

CARLSBAD, NEW MEXICO

(X) I hereby certify that the foregoing is true and correct.

SIGNED: [Signature]

TITLE: Production

DATE: 02-13-86

(This space for Federal or State office use)

APPROVED BY: [Signature]
CONDITIONS OF APPROVAL, IF ANY:

TITLE:

DATE:

*See Instructions on Reverse Side