Form 3160-5 (July 1989) (Formerly 9-3)	31) DEPA BU	UNITED ST RTMENT OF T REAU OF LAND A	ATES 2 4 1 HE INTERIO	OFFICE FOR NUMERA OF COPIES APTILIAN (Other: Jestractions) R verse alder	1 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	MOST ALTONE AND BELIAL MO. NOGO 3160-4 B. LEARE DEBIGNATION AND BELIAL MO. NM 030454	
(I)o nat		OTICES AND proposals to drill or to plication for perm			6' HA	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
				AREA II		T. UNIT AGREEMENT NAME	
WELL BA			3a. Area Code 6 Ph	Poker Lake			
Char	les B. Gille	espie, Jr.		915-683-1765		Poker Lake Unit	
P.O.	Box 8 M	idland, Texas				76	
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.⁹ See also apace 17 briow.) At surface 						10. PIELO AND POOL, OE WILDCAT Poker Lake Delaware, Sout	
					11. ENC., T., R., M., OR BLE. AND SUBVET OR AREA		
495'	FNL & 660'	FWL				Sec. 34-T24S-R31E	
14. PERMIT NO.			(Show whether ar, #		12. COUFTE ON PARISE 18. STATE		
30015-2		3483.9'					
16.			To Indicate Nat	ture of Notice, Repor		Other Data UBHY REPORT OF:	
	ل ــــا	INTENTION TO:	1	WATER ENUT-OFF		BEPAIR:NO WELL	
TEST WATE FRACTURE T		PTLL OR ALTER C Miltiple Compli	!	PRACTURE TREATMEN	T	ALTERING CABING	
AHOOT OR A	CID128	ABANDON*		BEOUTING OR ACIDIE Snud a		Urface Casing	
REPAIR WEL	.u.	CHANGE PLANE		(Note: Report	results	of multiple completion on Well	
IOther)	THURED OR COMPLET	TED OFERATIONS (Clearly	state all pertioent	dataily and size partings	t dates	ietion Report and Log form.)	
proposed sent to th	work. If well is : is work.)*	directionally drilled, giv	e subsurface locatio	as and measured and tru	e verue	al erplas for all marages and soors perti-	
6/30/91:	Peterson D	rilling Compar	ny Rig #2 spi	udded 12 1/4" ho	ole a	t 9:00 a.m. 6/30/91.	
7/09/91:	get past 4 Class "C" not circul at 65'. F cement dic 50 sx Clas 3 hrs. Ra 3% CaCl -	Drilled 12 1/4" hole to 620'. Ran 12 jts. 8 5/8" 24# J-55 casing - could not get past 424'. Set 8 5/8" casing at 424' KB. Cemented with 500 sx Halliburton Class "C" containing 2% CaCl. Plug down at 12:00 a.m. 7/09/91. Cement did not circulate. Ran temperature survey - top of cement outside 8 5/8" casing at 65'. Ran 1" tubing to 65'. Pumped 50 sx Class "C" containing 3% CaCl - cement did not circulate. Wait on cement 3 hrs. Ran 1" tubing to 65'. Pumped 50 sx Class "C" containing 3% CaCl - cement did not circulate. Wait on cement 3 hrs. Ran 1" tubing to top cement at 60'. Pumped 50 sx Class "C" containing 3% CaCl - cement did not circulate. Wait on cement 3 hrs. Ran 1" tubing to top cement at 50'. Pumped 50 sx Class "C" containing 10 containing 3% CaCl - cement at 60'. Pumped 50 sx Class "C" containing 10 containing 3% CaCl - cement at 60'. Pumped 50 sx Class "C" containing 10 containing 3% CaCl - cement at 60'. Pumped 50 sx Class "C" containing 11 containing 3% CaCl - cement at 60'. Pumped 50 sx Class "C" containing 12 containing 3% CaCl - cement at 60'. Pumped 50 sx Class "C" containing 13 caCl - cement did not circulate. Wait on cement 3 hrs. Ran 1" tubing to 10 top cement at 50'. Pumped 50 sx Class "C" containing 3% CaCl - cement did 10 not circulate - top of cement at 16'. Pumped 15 sx cement - filled to surface.					
7/10/91	Tested 8 9	5/8" casing to	500 # for 3	0 minutes, test	ed ok	<.	
	•					(continued)	
	4	/					
•	tify that the fore	going is trac and corre	Proc	luction Manager		.7/16/91	
BIGNED	Uhr W	1 July	TITLE				
(This space	for Federal or St	ate office use V					
APPROVED CONDITION	BT	L, EF ANT :	TITLE		···		
				on Reverse Side		3 1991 53≲	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department of the