					. Copy			
	n 5-331 y 1963)		NITED STAT MENT OF THE GEOLOGICAL SU	INTERIO	(Other instrume	CATE* on re- 5. 1		proved. Bureau No. 42-RI FION AND SERIAL
	SUNE		ICES AND RE			6.	IF INDIAN, ALLO	OTTEE OR TRIBE N.
					to a different reservoir. sals.)			
1.			ATION FOR FERMIT-	El El	sais.)		UNIT AGREEMEN	TNAME
	OIL X GAS WELL	OTHER		rt ka	, tani ka ing		Poker I	Jake
2. N	NAME OF OPERATOR	D 100 <		١	NG 2 1973	8. 1	FARM OR LEASE	
3. 4	PERRY R.	EASS -		دم به دید در است ا	na na 2000 i Britan		Poker I	Lake Unit
	P. O. BOX	(1178	Monahans, Te	exas 79756	2779 - 10 - 10 - 10 - 10 - 10 - 10 - 10 - 1		11	
4. I S	LOCATION OF WELL (Re See also space 17 below	port location of	learly and in accordan	nce with any Stat	te requirements.*	10.		L, OR WILDCAT
I	At surface -550 -160	5 FSL &	660' FWL of S unit let		•	11.	Corral SEC., T., B., M., SURVEY OR	Canyon (De
							ec. 17, 1	
14. 1	PERMIT NO.		15. ELEVATIONS (Sho			12.		RISH 13. STATE
				DF, 3211			Eddy	N. Mex
16.		Check A	ppropriate Box To	Indicate Natu	ire of Notice, Report	t, or Other	r Data	
	NC	TICE OF INTEN	TION TO:		5	SUBSEQUENT	REPORT OF:	
	TEST WATER SHUT-OFF		PULL OR ALTER CASING	·	WATER SHUT-OFF		REPAIRI	NG WELL
	FRACTURE TREAT Shoot or acidize		MULTIPLE COMPLETE	T I	FRACTURE TREATMENT Shooting or acidizit			NG CASING
	REPAIR WELL		CHANGE PLANS		(Other)			
	(Other)				(Nore: Report Completion or F			
17. 1	DEDCRIDE LIGITORED OF	COMPLETED OPH	ERATIONS (Clearly state	e all pertinent de	tails, and give pertinent	t dates, inclu	iding estimated	date of starting
17. r	proposed work. If nent to this work.)* 8 5/8" OI 4 1/2" OI	well is direction CSA 7541 CSA 3784	, cement circ , top cement	ulated. behind cs	sand measured and true and measured and true ag. @ 2740' 2 shots @ 3715	vertical dep TD PBD	3785'	date of starting rkers and zones p
17. 1	proposed work. If nent to this work.)* 8 5/8" OL 4 1/2" OL Casing P Proposed P & 1) Pull r 2) Spot 1 3) Cut 4 4) Run the 10 ppg 5) Spot 2 6) Spot 3 7) Spot 3 8) Spot 1 9) Salvag 10) Salvag	well is direction OCSA 754 OCSA 3784 Derforation A operation A operation C Sx cem 1/2" csg og. to 50 g salt ge 0 sx cem 0 sx cem	<pre>, cement circ ', top cement ons: 2 shots tions: splace hole w ent @3715' (e @ an est 270 ' below csg c 1 mud. ent @ 2750' (ent @ 2140' (ent @ 30' ext ead and insta</pre>	sulated. behind cs @ 3692' & with 10 ppg st top cer 0'; pull c ut-off (es est top ce est top ce ending to 11 permane well loca	s and measured and true sg. @ 2740 2 shots @ 3715 s salt gel mud. hent plug at 35 sg. at at 2750') an ement plug at 2 ement plug at 2 ement plug at 2 ement plug at 2 ement plug at 3 surface.	vertical dep TD PBD (201) ad displa 6441) 0351) 7001) well ma	ace hole	rkers and zones p with
	proposed work. If nent to this work.)* 8 5/8" OL 4 1/2" OL Casing P Proposed P & 1) Pull r 2) Spot 1 3) Cut 4 4) Run the 10 ppg 5) Spot 2 6) Spot 3 7) Spot 3 8) Spot 1 9) Salvag 10) Salvag	well is direction OCSA 754 OCSA 3784 Derforation A operation A operation Cosx cem Cosx ce	<pre>onally drilled, give sub , cement circ ', top cement ons: 2 shots tions: splace hole w ent @3715' (e @ an est 270 ' below csg c 1 mud. ent @ 2750' (ent @ 2140' (ent @ 30' ext ead and insta attery, clean f the U.S.G.S</pre>	sulated. behind cs @ 3692' & ith 10 ppg st top cer 0'; pull c ut-off (es est top ce est top ce est top ce ending to 11 permane well loca	s and measured and true sg. @ 2740 2 shots @ 3715 s salt gel mud. hent plug at 35 sg. at at 2750') an ement plug at 2 ement plug at 2 ement plug at 2 ement plug at 2 ement plug at 3 surface.	vertical dep TD PBD (201) ad displa 6441) 0351) 7001) well ma	ace hole	rkers and zones p with
18. 1	proposed work. If nent to this work.)* 8 5/8" OL 4 1/2" OL Casing P Proposed P & 1) Pull r 2) Spot 1 3) Cut 4 4) Run the 10 ppg 5) Spot 2 6) Spot 3 7) Spot 3 8) Spot 1 9) Salvag 10) Salvag satisf	well is direction OCSA 754 OCSA 3784 Derforation A operation A operation Cosx cem Cosx ce	<pre>onally drilled, give sub , cement circ ', top cement ons: 2 shots tions: splace hole w ent @3715' (e @ an est 270 ' below csg c 1 mud. ent @ 2750' (ent @ 2140' (ent @ 30' ext ead and insta attery, clean f the U.S.G.S</pre>	sulated. behind cs @ 3692' & ith 10 ppg st top cer 0'; pull c ut-off (es est top ce est top ce est top ce ending to 11 permane well loca	s and measured and true sg. @ 2740 2 shots @ 3715 s salt gel mud. hent plug at 35 sg. at at 2750') an ement plug at 2 ement plug at 2 ement plug at 2 ement plug at 2 ement plug at 3 surface.	vertical dep TD PBD (201) ad displa 6441) 0351) 7001) well ma	ace hole	rkers and zones p with
18. I	Proposed work. If nent to this work.)* 8 5/8" OL 4 1/2" OL Casing P Proposed P & 1) Pull r 2) Spot 1 3) Cut 4 4) Run the 10 ppg 5) Spot 2 6) Spot 3 7) Spot 3 8) Spot 1 9) Salvag 10) Salvag satisf	well is direction OCSA 754 OCSA 3784 Derforation A operation A operation S sx cem 1/2" csg of salt ge 0 sx cem 0 sx cem 0 sx cem 0 sx cem 0 sx cem 1/2" csg 0 sx cem 0 sx cem 0 sx cem 1/2" csg 0 sx cem 0 sx cem 1/2" csg 0 sx cem 0 sx cem 1/2" csg 0 sx cem 1/2" csg 1/2"	<pre>onally drilled, give sul , cement circ ', top cement ons: 2 shots tions: splace hole w ent @3715' (e @ an est 270 ' below csg c l mud. ent @ 2750' (ent @ 2140' (ent @ 30' ext ead and insta attery, clean f the U.S.G.S</pre>	sulated. behind cs @ 3692' & ith 10 ppg st top cer 0'; pull c ut-off (es est top ce est top ce est top ce ending to 11 permane well loca	s and measured and true sg. @ 2740 2 shots @ 3715 s salt gel mud. hent plug at 35 sg. at at 2750') an ement plug at 2 ement plug at 2 ement plug at 2 ement plug at 2 ement plug at 3 surface.	vertical dep TD PBD (201) ad displa 6441) 0351) 7001) well ma	ace hole	rkers and zones p with
	Proposed work. If nent to this work.)* 8 5/8" OL 4 1/2" OL Casing P Proposed P & 1) Pull r 2) Spot 1 3) Cut 4 4) Run the 10 ppg 5) Spot 2 6) Spot 3 7) Spot 3 8) Spot 1 9) Salvag 10) Salvag satisf	well is direction CSA 754 CSA 3784 DCSA 50 CCSA 3784 DCSA 50 CCSA 50 DCSA 50 CCSA 50 DCSA 50 CCSA 50 DCSA 50 CCSA 50 DCSA 50 CCSA 50 DCSA 50 CCSA 50 DCSA 5	s true and correct	sulated. behind cs @ 3692' & ith 10 ppg st top cer 0'; pull c ut-off (es est top ce est top ce est top ce ending to 11 permane well loca	s and measured and true sg. @ 2740 2 shots @ 3715 s salt gel mud. hent plug at 35 sg. at at 2750') an ement plug at 2 ement plug at 2 ement plug at 2 ement plug at 2 ement plug at 3 surface.	vertical dep TD PBD (201) ad displa 6441) 0351) 7001) well ma	ace hole	rkers and zones p with
	Proposed work. If nent to this work.)* 8 5/8" OL 4 1/2" OL Casing P Proposed P & 1) Pull r 2) Spot 1 3) Cut 4 4) Run the 10 ppg 5) Spot 2 6) Spot 3 7) Spot 3 8) Spot 1 9) Salvag 10) Salvag satisf	well is direction CSA 754 CSA 3784 DCSA 50 CCSA 3784 DCSA 50 CCSA 50 DCSA 50 CCSA 50 DCSA 50 CCSA 50 DCSA 50 CCSA 50 DCSA 50 CCSA 50 DCSA 50 CCSA 50 DCSA 5	s true and correct	sulated. behind cs @ 3692' & ith 10 ppg st top cer 0'; pull c ut-off (es est top ce est top ce est top ce ending to 11 permane well loca	s and measured and true sg. @ 2740 2 shots @ 3715 s salt gel mud. hent plug at 35 sg. at at 2750') an ement plug at 2 ement plug at 2 ement plug at 2 ement plug at 2 ement plug at 3 surface.	vertical dep TD PBD (201) ad displa 6441) 0351) 7001) well ma	ace hole	rkers and zones p with
	Proposed work. If nent to this work.)* 8 5/8" OL 4 1/2" OL Casing F Proposed P & 1) Pull r 2) Spot 1 3) Cut 4 4) Run the 10 ppg 5) Spot 2 6) Spot 3 7) Spot 3 8) Spot 1 9) Salvag 10) Salvag satisf	well is direction CSA 754 CSA 3784 DCSA 50 CCSA 3784 DCSA 50 CCSA 50 DCSA 50 CCSA 50 DCSA 50 CCSA 50 DCSA 50 CCSA 50 DCSA 50 CCSA 50 DCSA 50 CCSA 50 DCSA 5	s true and correct	sulated. behind cs @ 3692' & ith 10 ppg st top cer 0'; pull c ut-off (es est top ce est top ce est top ce ending to 11 permane well loca	s and measured and true sg. @ 2740 2 shots @ 3715 s salt gel mud. hent plug at 35 sg. at at 2750') an ement plug at 2 ement plug at 2 ement plug at 2 ement plug at 2 ement plug at 3 surface.	vertical dep TD PBD (201) ad displa 6441) 0351) 7001) well ma	ace hole	rkers and zones p with