

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer 00, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. 30-015-22243
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name Rifleman AFQ "32" State Com
Well No. 1
Pool name or Wildcat Undesignated

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

Name of Operator  
Penwell Energy, Inc.

Address of Operator  
600 N. Marienfeld, Suite 1100, Midland, TX 79701

Well Location

Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line  
Section 32 Township 21S Range 26E NMPM Eddy County

Elevation (Show whether DF, RKB, RT, GR, etc.)  
3280' GR

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to P&A the Rifleman AFQ "32" State Com #1 as per the following:

1. MIRU plugging unit. ND tree, NU BOP, POOH with rods and tubing laying down.
2. RIH with workstring and tag cement on top of CIBP at 9650'.
3. Displace hole with gelled brine plugging mud.
4. Spot 2 sacks cement on top of cement above CIBP at 9650' bringing total cement to a minimum of 35' above CIBP.
5. Spot 25 sacks cement at 8400'.
6. Spot 25 sacks cement at 5857' to cover DV tool.
7. Spot 25 sacks cement at 4570'.
8. Set CIBP at 4300' and top with 35' cement.
9. Place 100' cement (shoe plug) across interval 2400'-2500'. Tag. 25 sx.
11. Cut and pull 5 1/2" casing at +/- 1700' (TOC @ 1750' by CBL).
12. Place 100' cement (stub plug) across casing cut 50' in and 50' out. Tag.
13. Place 100' cement (shoe plug) across interval 470'-570'. Tag.
14. Spot 10 sack cement plug at surface.
15. Cut off casing below ground level, weld on plate, and place P&A marker.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Charles W. Knight, Jr. TITLE Engineer DATE 11/24/98

TYPE OR PRINT NAME Charles W. Knight, Jr. TELEPHONE NO. 915-683-2534

(This space for State Use)

APPROVED BY M. S. Sheffield TITLE Field Rep. II DATE 5-13-99

CONDITIONS OF APPROVAL, IF ANY:

\* Notify NMCCO to witness plugging operations.