

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.  
30015-22243

Indicate Type of Lease

STATE ☒

FEE ☐

State Oil & Gas Lease No.

Lease Name or Unit Agreement Name  
Rifleman AFQ "32" State Com

Well No.  
1

Pool name or Wildcat  
Happy Valley Strawn

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:  
OIL  
WELL ☒

GAS  
WELL ☐

OTHER

Name of Operator  
Concho Resources Inc.

Address of Operator  
110 W. Louisiana, Ste 410; Midland Tx 79701

Well Location

Unit Letter K : 1980 Feet From The SOUTH Line and 1980 Feet From The WEST Line

Section 32 Township 21S Range 26E NMPM EDDY County

Elevation (Show whether DF, RKB, RT, GR, etc.)  
3280' GR

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ANBANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CONCHO RESOURCES INC. RESPECTFULLY REQUESTS APPROVAL TO PLUG & ABANDON THE RIFLEMAN AFQ '32' STATE COM #1 WELL ACCORDING TO THE FOLLOWING PROCEDURE:

1. MIRU plugging unit. ND tree, NU BOP, POOH w/ rods & tbg & LD.
2. RIH w/ WS and tag cmt on top of CIBP @ 9650'.
3. Displace hole w/ gelled brine plugging mud.
4. Spot 2 sxs cmt on top of cmt above CIBP @ 9650' bringing total cmt to min of 35' above CIBP.
5. Spot 25 sxs cmt @ 8400'.
6. Spot 25 sxs cmt @ 5857' to cover DV tool.
7. Spot 25 sxs cmt @ 4570'.
8. Set CIBP @ 4300' & top w/ 35' of cmt.
9. Place 100' cmt (shoe plug) (25 sxs) across interval 2400-2500'. TAG.
10. Cut & pull 5-1/2" csg at 1700' (TOC @ 1750' by CBL)
11. Place 100' cmt (stub plug) across csg, cut 50' in and 50' out. TAG.
12. Place 100' cmt (shoe plug) across interval 470'-570'. TAG.
13. Spot 10 sxs cmt plug @ surface.
14. Cut off csg below ground level. Weld on plate, and install P&A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terri Stathem TITLE Production Analyst DATE 07-21-99

TYPE OR PRINT NAME Terri Stathem

TELEPHONE NO. 915-683-7443

(This space for State Use)

APPROVED BY Terri Stathem TITLE Field Rep. II DATE 7/26/99

CONDITIONS OF APPROVAL, IF ANY:

\* Notific N.M.O.C.D. to witness Plugging Operations.