Form 3160-5 (August 1999)

## **JITED STATES** DEPARTMENT OF THE INTERIOR

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 200

	Expires: N
•	<ol><li>Leasé Serial No.</li></ol>

SUNDRY NOTICES AND REPORT
Do not use this form for proposals to de abandoned well. Use form 3160-3 (APD)

В	UREAU OF LAND MANA	GEMENT			5. Leasé Serial No.	5 Lears Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an  abandoned well. Use form 3160-3 (APD) for such proposals.					CONT 65			
					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRI	PLICATE - Other instruc	ctions on rev	erse side.		7. If Unit or CA/Agr	reement, Name and/or No.		
1. Type of Well	<del> </del>		<del>- 11 - 2-</del>		8. Well Name and No JICARILLA 22 8			
Oil Well Gas Well Oth		SEBABÁLLE	MDDEDDV		9. API Well No.	,		
Name of Operator     CONOCOPHILLIPS CO.					n 30-039-21280			
<sup>3a.</sup> Address P.O. BOX 2197 WL3 4061 HOUSTON, TX 77252	3b. Phone No. (include area code) Ph: 832.486.2326 Fx: 832.486.2688			10. Field and Pool, or Exploratory LINDRITH GALLUP-DAKOTA WEST				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish	n, and State		
Sec 16 T25N R4W NESE 179	95FSL 1080FEL			!	RIO ARRIBA (	COUNTY, NM		
12. CHECK APP	ROPRIATE BOX(ES) TO	O INDICATE	NATURE OF	NOTICE, RI	EPORT, OR OTHI	ER DATA		
TYPE OF SUBMISSION		TYPE OF ACTION						
Notice of Intent	Acidize		oen ture Treat	Product	ion (Start/Resume)	☐ Water Shut-Off ☐ Well Integrity		
☐ Subsequent Report	Subsequent Report Casing Repair		Construction	Recomp				
Final Abandonment Notice	Change Plans			_	arily Abandon	Other Workover Operations		
	Convert to Injection				Disposal			
following completion of the involved testing has been completed. Final Al determined that the site is ready for for the ConocoPhillips proposes to sproves unsuccessful we will p #22228).	pandonment Notices shall be fil inal inspection.) queeze this well as per th	led only after all se attached pr	requirements, include ocedure. If the	ding reclamatio	n, have been completed	AFMSS		
14. I hereby certify that the foregoing is	strue and correct. Electronic Submission # For CONOC Committed to AFMSS for p	#27497 verified OPHILLIPS Co	by the BLM Wel	I Information o Puerco	System			
	H MARBERRY			TTING CON				
Signature (Electronic S	Submission)		Date 02/03/2	2004				
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE SE			
Approved By Asana	- Se C	ueh	Title P.			Date 2 (17/6)		
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condi-	uitable title to those rights in the	s not warrant or e subject lease	Office					

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

# ConocoPhillips

### San Juan Workover Procedure

#### Jicarilla 22-#8

#### **PROCEDURE:**

Ensure that well is shut in, energy isolated, locked and tagged out; Cathodic protection disconnected.

- 1. Notify Operator, Travis Chavez 505 320-1537.
- 2. Prepare Location. Test anchors to 10,000 lbs.
- 3. Hold Safety Meeting.
- 4. MI & RU WO rig.
- 5. This well is a Category 1/Class 1 designation. Thus, one untested barrier will suffice. Kill the well with FSW or if possible sting in with a BPV.
- 6. ND wellhead and NU BOPE. (refer to COPC well control manual, Sec 6.13 for pressure testing procedure).
- 7. Pull tubing out of the hole.
- 8. RIH with plug, tubing, and packer. Test the casing every five hundred feet to determine locations of leaks.
- 9. Squeeze well per Service Company recommendation.
- 10. If squeeze is not successful or it is determined that a squeeze would not be adequate then plug the well, per Ron Bishop's procedure.
- 11. If well is successfully squeezed, drill-out cement and pressure test the casing to 500#.
- 12. Run tubing, seal nipple, and mule shoe, cleanout to PBTD, and land tubing at approximately 7713' KBM. While running tubing, run a drift after every connection as per Ron Bishop's attached recommended practice to insure no crimped joints.
- 13. ND BOPE and NU wellhead. If necessary, swab the well to kick-off prior to moving the WO rig. Call operator (Travis Chavez 505 320-1537) and arrange for a plunger to be dropped and insure that it make one cycle before rigging down.
- 14. RD MO rig. NOTIFY regulatory (Patsey or Yolanda or Deb) that work completed.
- 15. Turn well over to production.