

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other *WSW*

2. Name of Operator
% NMOCN

3a. Address *1000 Rio Brazos Rd.
Aztec, NM 87410* 3b. Phone No. (include area code)
334-6178

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
*Sec. 30, T. 31 N., R. 16 W.
369/S-64/E*

5. Lease Serial No.
14-20-603-734

6. If Indian, Allottee or Tribe Name
Navajo

7. If Unit or CA/Agreement, Name and/or No.
Horseshoe Gallup

8. Well Name and No.
2-W HGU

9. API Well No.
30045 10274

10. Field and Pool, or Exploratory Area
Morrison

11. County or Parish, State
San Juan NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

See Attached plugging procedure.



14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

NMOCN Contract Plugging

Title

Signature *NMOCN*

Date

4/14/03

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

[Signature] *M Ma*

Title

PE

Date

4/15/03

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FFU

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

OPERATOR

API WELL # Well Name Well # Operator Name Type Stat County Surf_Owner UL Sec Twp N/S Rng W/E Feet NS Ft EW

Order_No 30-045-10274 HORSESHOE GALLUP UNIT W 002 PLAYA MINERALS & ENERGY INC W San Juan P 30 31 N 16 W

369 S 64 E

13 3/8 @ 107' w/150s 8 5/8 @ 2736 w/640s No rpt tbg Perf @ 2224-2668

Procedure

MIRU, NUBOPE,

POOH Lay Down Rods & Tubing if present,

RIH with Gauge ring,

Pick up work string, Run Scraper if required,

RIH Set CIBP 2125', cap with 125' cement. (Morrison)

Test casing.

POOH lay down tubing.

RU wire line RIH, perforate @ 157' + - 50' under surface casing shoe or Mesa Verde

base whichever is lower.. Note: Perforating @ 157' may not be necessary due to cement being reported

Establish Circulation; circulate cement to surface inside and outside casing Circulated to surface.

Cut off well head and install P&A marker

Cut off anchors 2' below ground


Clean and level location

plug Dakota from 1832'-1732'

plug Gallup from 950'-850'

WELL NAME 2-W HGV
 SEC, TWN, RNG. 30-31N-16W

Mancos Surface



13 3/8" 48 #

107'

plug - 157 - surface

$$157 / 2.922(1.18) = 46 \text{ sks}$$

TOC - Surface (reported)

Gallup

900'

plug 950 - 850

$$150 / 2.922(1.18) = 44 \text{ sks}$$

Dakota

1782'

plug 1832 - 1732

$$(2125 - 2000) + 50 / 2.922(1.18) = 51 \text{ sks}$$

plug 2125 - 2000'

Morrison

2050'

BPE 2125'

2224' - 2234'

Perf @ 2658' - 2238'

8 5/8" 32 #

2736'

SURFACE CASING

SIZE HOLE _____"

SIZE CASING _____"

Annular Volume _____ ft³/ft.

Cement _____ sk

Volume _____ ft³

INTERMEDIATE CASING

SIZE HOLE _____"

SIZE CASING _____"

Annular Volume _____ f

Cement _____ s

Volume _____ f