# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



MAY 20 2011

REVISED

Sundry Notices and Reports on Wells	<del>Family l</del> on Fig Bureau of Land N	eld Office lanacemen
	5. Le	ase Number
1. Type of Well		'-079289 Indian, All. or
		ibe Name
2. Name of Operator  ConocoPhillips		nit Agreement Name n Juan 28-7 Unit
ConocoPhillips	\$	•
3. Address & Phone No. of Operator		ell Name & Number n Juan 28-7 Unit 61A
3. Address & Filone No. of Operator	Sa	n suan 20-7 Unit OfA
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9. <b>AI</b>	I Well No.
4. Location of Well, Footage, Sec., T, R, M	30	-039-22208
Unit P (SESE), 940' FSL & 790' FEL, Section 10, T28N, R7W, NMPM		eld and Pool Blanco PC / Blanco M
		ounty and State o Arriba, NM
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	, REPORT, OTHER DAT	A
Type of Submission Type of Action X Notice of Intent Abandonment Change		
Recompletion New Co.	enstruction	
Subsequent Report Plugging Non-Roi Casing Repair Water SI	utine Fracturing hut off	
	sion to Injection	
13. Describe Proposed or Completed Operations	<del></del>	
ConocoPhillips Company requests permission to remove the packer and comming Mesaverde well per the attached revised procedure and current wellbore schemati		
· · · · · · · · · · · · · · · · · · ·		
PLT failed 2008 No Relokis Wilmit	ted Attack thinke,	
14. I hereby certify that the foregoing is true and correct.		
Signed Taloya Crystal Tafoya Title	e Staff Regulatory Technic	ian Date 5 20 11
(This space for Federal or State Office use)		MAY 2 3 2011
APPROVED BY Original Signed: Stephen Mason Title CONDITION OF APPROVAL, if any:	Date	
Title 18 U.S.C. Section 1001, makes it a crume for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.		

## SAN JUAN 28-7 UNIT 61A Rig Uplift - Commingles

Lat 36° 40' 15,373" N

Long 107° 33' 14.238" W

#### **PROCEDURE**

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCl, if necessary.
- 4. ND wellhead and NU BOPE.
- 5. Release tubing hanger. TOOH with short tubing string (details below).

Number	Description
104	1.66" Tubing joint
1	1.66" S nipple
1	1.66" Perforated joints

- 6. Release tubing hanger and pull straight up on the 2-3/8" tubing to release the Model G Packer. If Model G Packer does not release contact Production Engineer and Rig Superintendent.
- 7. TOOH with long string tubing (details below).

Use Tuboscope Unit to inspect tubing and record findings in Wellview. Make note of corrosion, scale, or paraffin and save a sample to give to the engineer for further analysis. LD and replace any bad joints.

Number	Description
109	2-3/8" Tubing Joints
1	Model "G" Packer
74	2-3/8" Tubing joint
	2-3/8" S. Nipple
1	2-3/8" tubing joints ( 31' )

- 8. TIH with 2-3/8" tubing and 4- 1/2" RBP, set the RBP at 4918', 50' above the top MV perforation.
- 8. TOOH lay down 4-1/2" retrieving head.
- 10. Pick up 7" packer and TIH. Set 7" packer at 3435', 50' below the bottom of the PC perforations.
- 11. Pressure test 4-1/2" casing and liner top to 600 psi and chart for 30 minutes. If pressure test fails contact Engineer and Rig superintendent for additional remedial work.
- 12. Pull up hole 3269', 50' above top PC perforations. Set packer and pressure test 7" casing to 600 psi and chart for 30 minutes. If pressure test fails contact Engineer and Rig superintendent for additional remedial work.
- 13. TOOH and LD 7" packer.
- 14. TIH and retrieve 4-1/2" RBP.
- 15. TIH with tubing using Tubing Drift Procedure. (detail below). Tag for fill and clean out to PBTD 5927'.

Recommended	
Tubing Drift ID:	1 901
Land Tubing At:	5866'
Land F-Ningle At:	58851

16. Pick up and land 2-3/8" production string with F nipple at 5865'.

Number	Description
1	2-3/8" Exp. Check

1	2-3/8" F nipple (ID 1.78")
1	2-3/8" Tubing joint (31')
1	2-3/8" Marker Joint
183	2-3/8" tubing joints

17. ND BOPE, NU Wellhead. Pressure test tubing slowly with an air package as follows: pump 3 bbls pad, drop steel ball, pressure tubing up to 500 psi, and bypass air. Monitor pressure for 15 mins., then complete the operation by pumping off the expendable check. Note in Wellview the pressure in which the check pumped off. Notify the MSO that the well is ready to be turned over to Production Operations. Make swab run to kick-off the well, if necessary, then RDMO.

## **Tubing Drift Check**

### **Procedure**

- 1. Set flow control in tubing. With air, on location, use expendable check. With no air on location, use wire line plug.
- 2. RU drift tool to a minimum 70' line. Drift tool will have an OD of at least the API drift specification of 1.901" for the 2 3/8",4.7# tubing, and will be at least 15" long. The tool will not weigh more than 10# and will have an ID bore the length of the tool, so fluids may be pumped through the tool if it becomes stuck.
- 3. Drop the tool into the tubing string and retrieve it after every 2 joints of tubing ran in hole. If any resistance to the tool movement is noticed, going in or out, that joint will be replaced.
- 4. In order to stimulate the plunger lift operation, all equipment must be kept clean and free of debris.

The drift tool should be measured with calipers before each job, to ensure the OD is the correct size for the tubing being checked. The maximum allowable wear of the tool is .003".

