Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	Jun 19, 2008
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II	OIL CONSERVATION DIVISION	30-039-05988
1301 W Grand Ave , Artesia, NM 88210		5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St Francis Dr., Santa Fe, NM		E-291-36
87505	TOPE AND DEPONTE ON WELLS	7 I ama Nama an Huit A announcet Nama
	ICES AND REPORTS ON WELLS DISALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
	CATION FOR PERMIT" (FORM C-101) FOR SUCH	Harvey State
1. Type of Well: Oil Well	Gas Well 🛛 Other	8. Well Number 11
2. Name of Operator		9. OGRID Number
Burlington Resources Oil Gas C	Company LP	14538
3. Address of Operator		10. Pool name or Wildcat
P.O. Box 4289, Farmington, NM	87499-4289	South Blanco Pictured Cliffs
4. Well Location		
Unit Letter N : 990	feet from the South line and 1850	feet from the West line
-		NMPM Rio Arriba County
Section 16		
	11. Elevation (Show whether DR, RKB, RT, GR, etc. 6294' GR	
12 Charle		Panart or Other Data
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF I	NTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK □	l	i i
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DR	
PULL OR ALTER CASING		
DOWNHOLE COMMINGLE	MOETIFEE COMPE CASING/CEMEN	1 30B
A A A A A A A A A A A A A A A A A A A		
OTHER:	□ OTHER: □	
	pleted operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion.	,	, , , , , , , , , , , , , , , , , , , ,
1		
Burlington Resources requests perm	nission to P&A the subject well per the attached proced	ure, current and proposed wellbore
schematics.		102222
* Mare Machinistr	plug top to 706', inside and outside (706'-	903') RECEIVED
* HONG TOWN MILENTO	ping 10p 20 7 00, 11/3/02 and Bulsine (706 -	(No. 1)
		A TOUR DE
		& RECEIVED
		(E) 1 2019
		TIME 2013.
Spud Date:	Rig Released Date:	TE, DIL CONS. DIV. DIST. 3
I hereby certify that the information	above is true and complete to the best of my knowledge	903') RECEIVED RECEIVED OIL CONS. DIV. DIST. 3 Ge and belief.
-08/991		
SIGNATURE STALL	Takeya TITLE Staff Regulatory	Technician DATE 7/21/11
		1 '
Type or print name Crystal Tafo	ya E-mail address: crystal.tafoya@conoco	ophillips.com PHONE: 505-326-9837
For State Use Only Deputy Oil & Gas Inspector,		
APPROVED BY: Spanshon	Title District #3	DATE 7/27/11
Conditions of Approval (if any):		



ConocoPhillips HARVEY STATE 11 Expense - P&A

Lat 36° 23' 42.18" N

Long 107°28'29.1" W

PROCEDURE

Note: This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of a steel tank to handle waste fluids circulated from the well and cement wash up. All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Type II (Class B) mixed at 15.6 ppg with a 1.18 cf/sk yield.

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU P&A rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with water, if necessary.
- 4. ND wellhead and NU BOPE. Pressure test BOP. PU and remove tubing hanger and tag for fill, adding additional joints as needed. Record fill depth in Wellview.
- 5. TOOH with tubing (per pertinent data sheet).
- 6. PU casing scraper and run from top of perforations to surface. LD casing scraper.
- 7. Plug #1 (Pictured Cliffs perforations & Pictured Cliffs, Fruitland, Kirtland, & Ojo Alamo formation tops, 2,270' 1,604'): Wireline set CIBP for 5-1/2", 15.5#, J-55 casing at 2,270'. Pressure test casing to 800 psi. If casing does not test, then spot and tag subsequent plugs as necessary. TIH with tubing, load casing with water, and attempt to establish circulation. Mix 82 sx Class B cement and spot inside the casing above CIBP to isolate the Pictured Cliffs perforations and Pictured Cliffs, Fruitland, Kirtland, and Ojo Alamo formation tops. WOC. Circulate well clean with water. POOH.
- 8. Plug #2 (Nacimiento formation top, 903' 803'): Perforate 3 HSC holes at 903'. Set CR at 853'. Pressure test workstring to 1000 psi. Sting into CR and establish injection rate into squeeze holes. Mix 47 sx Class B cement. Sqz 30 sx Class B cement into HSC holes and leave 17 sx cement inside casing to isolate the Nacimiento formation top. POOH.
- 9. Plug #3 (Surface casing shoe and surface plug, 175' Surface): Perforate 3 HSC holes at 175'. Establish circulation out bradenhead with water and circulate BH annulus clean. Mix 53 sx Class B cement and pump down production casing to circulate good cement out bradenhead. Shut in well and WOC.
- 10. Nipple down BOP and cut off casing below the casing flange. Install P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location to its natural state:



