. . . . submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



AUG 15 2011

			HUO T	-	
	Sundry Notices and Reports on Wells		armington	Field Office	
1.	Type of Well GAS Name of Operator BURLINGTON Type of Well OLCONS DILL OLCONS D	5.un 6.	SF-0785	n, All. or	
2.	Name of Operator BURLINGTON PESCURCES OIL & GAS COMPANY LP	7.	Unit Ag	reement Name	
3.	Address & Phone No. of Operator	— 8.	Well Na Day B 4	me & Number	
	PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API We	ll No.	
4.	Location of Well, Footage, Sec., T, R, M		30-045-2		
	Unit K (NESW), 1700' FSL & 1616' FWL, Section 7, T27N, R8W, NMPM	10.	Field and Pool Basin Dakota		
		11.	County San Jua	and State n, NM	
12.	. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, or Type of Submission Type of Action X	OTHER	DATA Other -		
B	Casing Repair Water Shut off Altering Casing Conversion to Injection				
13.	Describe Proposed or Completed Operations				
	urlington Resources requests permission to $P&A$ the subject well per the attached procedure hematics.	, current	and propos	ed wellbore	
	ened Stal Taloya Crystal Tafoya Title: Staff Regu	llatory Te	echnician	Date 8 5	1
AF	his space for Federal ghat stephen Mason PPROVED BYTitle		Date	AUG 1 7 201	j
	ONDITION OF APPROVAL, if any:				

Title 18 U S C Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

ConocoPhillips DAY B 4

Expense - P&A

Lat 36° 35' 12.732" N

Long 107° 43' 29.316" W

PROCEDURE

This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. When an existing primary valve (i.e. casing valve) is to be used, the existing piping should be removed and replaced with the appropriate piping for the intended operation.
- 4. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with water, as necessary, and at least pump tubing capacity of water down tubing.
- 5. ND wellhead and NU BOPE. Function test BOP. PU and remove tubing hanger.
- 6. TOOH with tubing (per pertinent data sheet). LD tubing bailer (if applicable).

Rods:	No	Size:	N/A	Length:	N/A
Tubing:	Yes	Size:	2-3/8"	Length:	7370'
Packer:	No	Size:	N/A	Depth:	N/A

Round trip casing scraper through deepest perforation or as deep as possible.

All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Type II mixed at 15.6 ppg with a 1.18 cf/sk yield.

7. Plug 1 (Dakota, 7112-7212', 12 Sacks Class B Cement)

RIH and set 4-1/2" cement retainer at 7,212'. Pressure test tubing to 1000 psi. Pressure test casing to 800 psi. *If casing does not test, then spot and tag subsequent plugs as necessary.* Load casing with water and attempt to establish circulation. Mix 12 sx Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. TOH.

8. Plug 2 (Gallup, 6250-6350', 51 Sacks Class B Cement)

Perforate 3 holes at 6,350'. Set a 4-1/2" cement retainer at 6,300'. Establish injection rate into squeeze holes. Mix 51 sx Class B cement. Sqz 39 sx Class B cement into HSC holes and leave 12 sx cement inside casing to isolate the Gallup formation top. TOOH.

9. Plug 3 (Mancos, 5435-5535', 51 Sacks Class B Cement)

Perforate 3 holes at 5,535'. Set a 4-1/2" cement retainer at 5,485'. Establish injection rate into squeeze holes. Mix 51 sx Class B cement. Sqz 39 sx Class B cement into HSC holes and leave 12 sx cement inside casing to isolate the Mancos formation top. TOOH.

10. Plug 4 (Mesa Verde, 4450-4550', 51 Sacks Class B Cement)

Perforate 3 holes at 4,550'. Set a 4-1/2" cement retainer at 4500'. Establish injection rate into squeeze holes. Mix 51 sx Class B cement. Sqz 39 sx Class B cement into HSC holes and leave 12 sx cement inside casing to isolate the Mesa Verde formation top. TOOH.

11. Plug 5 (Chacra, 3704-3804', 51 Sacks Class B Cement)

Perforate 3 holes at 3,804'. Set a 4-1/2" cement retainer at 3754'. Establish injection rate into squeeze holes. Mix 51 sx Class B cement. Sqz 39 sx Class B cement into HSC holes and leave 12 sx cement inside casing to isolate the Chacra formation top. PUH.

12 Plug 6 (Fruitland Coal / Pictured Cliffs, 2507-2898', 34 Sacks Class B Cement)

Mix 34 sx Class B cement and spot a balanced cement plug inside casing to isolate the Fruitland Coal and Pictured Cliffs formation tops. TOOH.

13. Plug 7 (Ojo Alamo / Kirtland, 1850-2050', 97 Sacks Class B Cement)

Perforate 3 holes at 2,050'. Set a 4-1/2" cement retainer at 2,000'. Establish injection rate into squeeze holes. Mix 97 sx Class B cement. Sqz 78 sx Class B cement into HSC holes and leave 19 sx cement inside casing to isolate the Ojo Alamo and Kirtland formation tops. TOOH.

438 336


14. Plug 8 (Nacimiento, 346-416', 51 Sacks Class B Cement)


Perforate 3 holes at 4-1/2" cement retainer at 360. Establish injection rate into squeeze holes. ***Existing cement squeezed from 347-378.*** Mix 51 sx Class B cement. Sqz 39 sx Class B cement into HSC holes and leave 12 sx cement inside casing to isolate the Nacimiento formation top. TOOH.

15. Plug 9 (Surface Casing Shoe, Surface-271', 124 Sacks Class B Cement)

Perforate 3 holes at 271'. Establish circulation out bradenhead with water and circulate BH annulus clean. *If attempt to circulation is unsuccessful, then perforate at appropriate depth as required by NMOCD/BLM regulations*. Mix 124 sx Class B cement and pump down production casing to circulate good cement out bradenhead. Shut in well and WOC.

16. Nipple down BOP and cut off casing below the casing flange. Install P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location.





UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: 4 Day B

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made:
- a) Place the Nacimiento plug from 438' 338' inside and outside the 4 ½" casing.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.