submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

SEP 29 2011

				on Field Office
	Sundry Notices and Reports on Wells	Bui	eau of La	and Managemen.
_		5.		Number
1.	Type of Well GAS	6.	SF-079 If India Tribe N	an, All. or
2.	Name of Operator ConocoPhillips Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	7.	Unit A	greement Name
	ConocoPhillips	0	**/ 11 37	0 N 1
3.	Address & Phone No. of Operator	- 8.		ame & Number an 32 Fed 23 #1A
	PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API W	ell No.
_		_	30-045	-31997
4.	Location of Well, Footage, Sec., T, R, M Unit J (NWSE), 1775' FSL & 1535' FEL, Section 23, T32N, R9W, NMPM			nd Pool Fruitland Coal
		11.	-	y and State an, NM
12.	CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OT	THER	DATA	
	Type of Submission Type of Action X Notice of Intent Abandonment Change of Plans	X		Pull Liner & Cleanout
	Recompletion New Construction Subsequent Report Plugging Non-Routine Fracturing Casing Repair Water Shut off			,
B	Final Abandonment Altering Casing Conversion to Injection			
	Describe Proposed or Completed Operations			
	nocoPhillips Company requests permission to pull the production liner for the subject well an discurrent wellbore schematic.	d clean	out per th	e attached procedure
14.	I hereby certify that the foregoing is true and correct.			
Sig	ened Sal Tafaya Crystal Tafoya Title Staff Regulat	tory Te	<u>chnician</u>	Date <u>9/2</u> 8/11
	nis space for Federal or State Office use) PROVED BY Original Signed: Stephen Mason Title		Date	SEP 3 N 2011
Tıtle	NDITION OF APPROVAL, if any: 18 U S C Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of finited States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction			Ja. U V 2011





ConocoPhillips SAN JUAN 32 FEDERAL 23 1A

Lat 36° 58' 3.216" N

Long 107° 44' 40.848" W

PROCEDURE

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with produced Fruitland coal water, if necessary.
- 4. TOOH with pump and rods (See Pertinent Data Sheet)
- 5. ND wellhead and NU BOPE Rig up bloose line to flow back tank Pressure test BOP equipment.
- 6. Unseat tubing hanger, check and note weight. Attempt to free tubing from 5 ½" liner, make up power swivel and rotate down to break up coal, if successful trip out of the hole with tubing
- 7. If unable to dislodge 5 ½" casing, RU wireline specialties, RIH and chemical cut the 2 3/8" tubing above the F-nipple If tubing is free TOOH, if not make another cut 1 joint up. TOOH and stand back tubing.
- 8. Make up 4 ¾" spear, 12 4 ¾" drill collars with bumper sub, pick up and RIH with 2 3/8" AOH drill pipe. Engage spear in 5 ½" liner, trip out of the hole and stand back drill pipe and collars and lay down 5 ½" liner. (Note: use approved dispensation kill method for well control, see attached kill method.)
- 9. MU 6 1/4" bit, TIH and clean out fill to PBTD, circulate hole clean, trip to 7" casing.
- 10. RIH check fill, clean out as necessary. Trip out of the hole with bit.
- 11. Make up 6 ½" X 9 ½" undereamer. TIH to 10' below the 7" casing shoe. Inject air and walk pressure up to 300 psi, drill slowly 5' to open hydraulic arms. Increase air and mist to a range of 1200 to 2000 scf/min and 10 to 12 bbls/hr mist. Underream open hole section to PBTD. Trip out of the hole and lay down undereamer.
- 12. Make up Baker 5-1/2" bladed shoe with float, eight 5 ½" 15.5 #/ft J-55 blank liner joints and a Baker Hyfio III liner hanger with cone slip grips on 2 3/8" AOH workstring. Rotate to bottom if necessary, set hanger and release setting tool. TOOH and LD 2 3/8" AOH drill pipe and 4 ¾" drill collars. Immediately after recovering hanger setting tool, drop 2.25" ball in the well and close the blind rams. (Note: The ball will seat in the float allowing a column of fluid to be held in the liner.)
- 13. RU wireline Perforate using 3-1/8" HSC guns with 0.5" dia. holes @ 4 spf and 90 degree phasing Perforate the following intervals <u>from the top down</u>: 3350-53', 3358-64', 3370-79', 3388-99', 3492-98', 3526-32' & 3536-43'. This is based on original perf locations (mud logs not available).
- 14. TIH with 2 3/8" tubing.

Recommended

Tubing Drift ID:	1.901	
kB:	13'	
Land Tubing At ⁻	3604'	
Land F-Nipple At:	3573'	

Number	Description
1	2 3/8" Price Type cover joint (~30')
1	2 3/8" F nipple (1.78" ID)
112	2 3/8" tubing joints
As needed	2 3/8" pup joints
1	2 3/8" tubing joints

15. ND BOP, NU B-1 adapter, rod radigan, and flow tee (place rod radigan below flow tee).

16. RIH with rods (detail below). Place 5 guides per rod where rod wear was found. Rod subs to be rotated each time the well is pulled to spread coupling wear in the tubing.

Number	Description	Pump Component Description
1	1.25" Insert Pump	Run RHAC-Z 2" x 1-1/4" x 7' x 9' Insert pump. Pump should
1	1" x 1' Lift Sub	have double standing and traveling valves with California
1	3/4" Guided Rod Sub	pattern ball and seats to comply with new pump standards.
1	22K Norris Shear Tool	Plunger to barrel clearance to be .006 Do not set pump to
6	1 25" Sinker Bars	tag.
2	3/4" Guided Rod (8')	•
137	3/4" Sucker Rods	
As Needed	3/4" Pony Rods	
1	1 1/4" x 22' Polished Rod	

^{17.} Space out pump 0.5" for every 1000 ft of tubing depth and seat pump. Load tubing with water to pressure test tubing and pump to 1500 psi. Test for good pump action.

^{18.} Notify lease operator that well is ready to be returned to production. RD, MOL

