RECEIVED

UNITED STATES FORM APPROVED Form 3160-5 SFP 18 2012 DEPARTMENT OF THE INTERIOR (August 2007) OMB No 1004-0137 **BUREAU OF LAND MANAGEMENT** Expires: July 31, 2010 Farmington Field Officerial No. SUNDRY NOTICES AND REPORTS ON WELLS NMNM-0546 6 If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well Oil Well X Gas Well Other 8. Well Name and No. Maddox D Federal Com 100 2. Name of Operator 9. API Well No. **Burlington Resources Oil & Gas Company LP** 30-045-30600 3a Address 3b Phone No (include area code) 10 Field and Pool or Exploratory Area PO Box 4289, Farmington, NM 87499 (505) 326-9700 **Basin Fruitland Coal** 4 Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11 Country or Parish, State Unit B (NWNE), 1260' FNL & 1525' FEL, Sec. 23, T30N, R13W Surface San Juan **New Mexico** 12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report Casing Repair New Construction Recomplete Change Plans X Plug and Abandon Temporarily Abandon Plug Back Final Abandonment Notice Convert to Injection Water Disposal 13. Describe Proposed or Completed Operation Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection) Burlington Resources requests permission to P&A the subject well per the attached procedure, current and proposed wellbore schematics. RCVD SEP 21'12 OIL CONS. DIV. DIST. 3 # Set CR no shallower than 1464' for plug#1 or pump under it to lover the Fruitland formation top 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Title Staff Regulatory Technician Dollie L. Busse Signature Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE

that the applicant holds legal or equitable title to those rights in the subject lease which would
entitle the applicant to conduct operations thereon

Title 18 U S C Section 1001 and Title 43 U S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

Original Signed: Stephen Mason

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify

Approved by



Title

Date SEP 2 0 2012

ConocoPhillips MADDOX D FEDERAL COM 100 Expense - P&A

Lat 36° 48' 9.36" N

Long 108° 10' 14.124" W

PROCEDURE

This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. When an existing primary valve (i.e. casing valve) is to be used, the existing piping should be removed and replaced with the appropriate piping for the intended operation.
- 4. RU blow lines from casing valves and begin blowing down casing pressure. Unseat pump and kill well with water, as necessary, and at least pump tubing capacity of water down tubing.
- 5. TOOH w/rods and LD.
- 6. ND wellhead and NU BOPE. Pressure and function test BOP. PU and remove tubing hanger.
- 7. TOOH with tubing/rods (per pertinent data sheet).

 Rods:
 Yes
 Size:
 3/4"
 Set Depth:
 1785'

 Tubing:
 Yes
 Size:
 2-3/8"
 Set Depth:
 1794'

Round trip 4-1/2" casing scraper to top perforation @ 1487' or as deep as possible.

All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Type II mixed at 15.6 ppg with a 1.18 cf/sk yield.

8. Plug 1 (Fruitland Coal, 1337-1437', 12 Sacks Class B Cement)

PU 4-1/2" CR and set at 1437'. Load casing and circulate well clean. Pressure test tubing to 1000# and casing to 800#. If casing does not test, then spot or tag subsequent plugs as appropriate. Mix 12 sxs Class B cement and spot a plug inside casing above CR to isolate the Fruitland Coal formation top. PUH.

9. Plug 2 (Surface Plug/Kirtland/Ojo Alamo, 0-495', 42 Sacks Class B Cement)

Connect the pump line to the bradenhead valve and attempt to pressure test the BH annulus 300 PSI; note the volume to load. If the BH annulus holds pressure then establish circulation out casing valve with water. Mix 42 sxs Class B cement and spot a balanced cement plug inside casing from 495' to surface. Circulate good cement out casing valve. TOH and LD tubing.

10. Nipple down BOP and cut off casing below the casing flange. Install P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location.



