m 3160-5 cptember 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

April
FORM APPROVED OMB No. 1004-0135 Expires: January 31, 2004
AND No. 1004 (1116
OMB No. 1004-0133
Expires: January 31, 2004

Date MAY 0 2 2005

· •	Da 1.11111111111111111111111111111111111				1 /		·		
BUREAU OF LAND MANAGEMENT					5. Lease Scrial No.				
SUNDRY NOTICES AND REPORTS ON WELLS						Jicarilla Contract 452 6. If Indian, Allottee or Tribe Name			
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.									
					Jicarilla A				
SUBMIT IN TR	IPLICATE Other instru	ctionsion	everse siq	e i i i i i	7. If Unit or	r CA//	Agreement, Name and/or No.		
Type of Well						20463			
Oil Well Gas Well Other						8. Well Name and No.			
Name of Operator						Jicarilla 452 No. 1Y 9. API Well No.			
lack Hills Gas Resources, Inc. 3b, Phone No. (include area code)						30-039-24046			
i. Address			•	10. Field and Pool, or Exploratory Area					
50 Indiana Street, Suite 400 Golden, CO 80401 720-210-130 Location of Well (Footage, Sec., T. R., M., or Survey Description)				I.			East Blanco, Pictured Cliffs		
030' FSL & 935' FEL, Unit P						11. County or Parish, State			
ec. 6, T29N-R03W					71. 1-11	- 3/3			
					Rio Anib				
12. CHECK AP	PROPRIATE BOX(ES) TO	INDICATE	NATURE (OF NOTICE, R	EPORT, OI	KUI	HER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION								
	Acidize	Deepen		Production (Star	t/Resume)		Water Shut-Off		
Notice of Intent	Alter Casing	Fracture T	reat	Reclamation			Well Integrity		
Subsequent Report	Casing Repair	New Cons	truction [Recomplete			Other		
Subsequent Report	Change Plans	Plug and A	Abandon	Temporarily Ab	andon				
Final Abandonment Notice	Convert to Injection	Plug Back		Water Disposal					
		results in a multi- filed only after	r all requiremen	n or recompletion ints, including recla	macion, have l	умі. Ді	rumi 3100-4 anan de mee viiet		
4. I hereby certify that the foregoing	ng is true and correct					,,,,			
Name (PrintedITyped)			Title Engineering Technician						
				Date 4/29/2005					
	THIS SPACE F	OR FEDERA	NE OR STAT	E OFFICE USE		125			
approved by (Signature) Original Signed: Stephen Mason			Name (Printed)	Typed)		Titl	c		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

BHEP/Mallon Oil Company

JICARILLA 452 #1Y

SE/4 SE/4 Sec 6, T29N - R3W Rio Arriba County, New Mexico

KB: 6,997', GL: 6,990', PBTD: 3,910'

Surface casing: Production casing: 5-1/2", 15.5 lb/ft, Casing @ 133' 3-1/2", 9.3 lb/ft, Casing @ 3,935'

3 1/2" esg vol factor:

0.04882 cu ft/ lin ft.

Current Perforations:

Fruitland Coal:

3,644'-3,743' (Open)

Completion Procedure

P&A well

- 1. MIRU completion rig, install flanged tubing head, NU BOP.
- 2. Rig up with 2 1/16" the to drill out composite BP set @ 3575'.
- 3. Drill out composite BP, push remains to bottom. TOOH with tubing.
- 4. TIH with tubing to 3800' to set the PC/FC/OA plug.
- 5. Pump balanced cement plug of 22 sx Type III cement÷ 2% CaCl2 (14.6 ppg, 1.34 cu ft / sx). Anticipated TOC plug will be @ 3198'.
- 6. Pull up to 3198' and reverse circulate hole to clear tubing.
- 7. Pull up to +/- 3000' SD and WOC for 3 hrs.
- 8. Trip down and tag TOC to confirm depth of cement plug.
- 9. Pull up to 1995' to set the NAC plug.
- 10. Pump balanced cement plug of 4 sx Type III cement + 2% CaCi2 (14.6 ppg, 1.34 cu ft / sx). Anticipated TOC plug will be @ 1895'.
- 11. Pull up to +/- 1600' SD and WOC for 3 hrs.
- 12. Trip down and tag TOC to confirm depth of cement plug.
- 13. Pull up to 500'.
- 14. Pump 20 sx Type III cement+ 2% CaCl2 (14.6 ppg, 1.34 cu ft / sx).to surface.
- SI and WOC.
- 16. Check cement for fall-back, top out if needed.

PAGE 44/45

- 17. Prepare to set a subsurface P&A marker. Notify state and tribal agencies to witness the marker placement. Prior to commencing with the marker review the requirements for the sub surface marker.
- 18. RDMU rig.
- 19. Prepare to reclaim location; remove all surface equipment, anchors, piping and trash.
- 20. Have surface prepared and seeded as per tribal/BLM requirements.

Initiated by:

Loren Diede 4-04-05 Rev 5-03-05

First-call for services:

Cement:

 \mathbf{BJ}

327-6222

Trucking:

open

Jicarilla 452 #1Y Approved WB Diagram

SE/SE, Sec 6, T29, R3W Rio Arriba, NM

