

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

Sundry Notices and Reports on Wells

1. **Type of Well**
GAS

2. **Name of Operator**
BURLINGTON
RESOURCES OIL & GAS COMPANY LP

3. **Address & Phone No. of Operator**


PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. **Location of Well, Footage, Sec., T, R, M**
Sec., T—N, R—W, NMPM

Unit L (NWSW), 1850' FSL & 1190' FWL, Sec. 17, T30N, R6W NMPM

2005 JUN 28 PM 12 50

RECEIVED
070 FARMINGTON NM



5. **Lease Number**
NM-03385
6. **If Indian, All. or Tribe Name**
7. **Unit Agreement Name**
San Juan 30-6 Unit
8. **Well Name & Number**
San Juan 30-6 Unit #80
9. **API Well No.**
30-039-07843
10. **Field and Pool**
11. **Blanco Mesaverde County and State**
Rio Arriba, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission:

- ☒ Notice of Intent
- ☐ Subsequent Report
- ☐ Final Abandonment

Type of Action:

- ☒ Abandonment
- ☐ Recompletion
- ☐ Plugging
- ☐ Casing Repair
- ☐ Altering Casing

- ☐ Change of Plans
- ☐ New Construction
- ☐ Non-Routine Fracturing
- ☐ Water Shut-off
- ☐ Conversion to Injection

☐ Other :

13. Describe Proposed or Completed Operations

It is intended to Plug & Abandon the subject well according to the attached procedure and well bore diagrams.

14. I hereby certify that the foregoing is true and correct.

Signed Philana Thompson Philana Thompson Title Regulatory Associate II Date 6/28/05

(This space for Federal or State Office use)
Original Signed: Stephen Mason

APPROVED BY _____ Title _____ Date JUL 05 2005

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOC

PLUG AND ABANDONMENT PROCEDURE

June 21, 2005

San Juan 30-6 Unit #80

AIN #6980901

Blanco Mesaverde

1850' FSL and 1190' FWL, Section 17, T30N, R6W

Rio Arriba County, NM API 30-039-07843

Lat: N 36.81306 / Long: W 1007.49062

1. Install and test rig anchors. Prepare blow pit. Comply with all NMOCD, BLM and BR safety rules and regulations. Conduct safety meeting for all personnel on location. MOL and RU daylight pulling unit. NU relief line and blow well down; kill with water as necessary. ND wellhead and NU BOP and stripping head; test BOP.
2. TOH tallying and visually inspect 2.375" tubing, total 6000'. If necessary LD tubing and PU workstring. Round-trip 5.5" casing scraper or wireline gauge ring to 5423'.
3. **Plug #1 (Mesaverde open hole interval and top, 5423' – 5323')**: TIH and set a 5.5" CR at 5423'. Pressure test tubing to 1000#. Load casing above the CR with water and circulate well clean. Pressure test casing to 800#. *If casing does not test, spot or tag subsequent plugs as appropriate.* Mix 16 sxs Type III cement and spot a balanced plug above CR to isolate the Mesaverde open hole interval and top. TOH with tubing.
4. **Plug #2 (Chacra top, ⁴³²³4730' – ⁴²²³4630')**: Perforate 3 squeeze holes at ⁴³²³4730'. Attempt to establish rate into squeeze holes if casing pressure tested. TIH and set 5.5" cement retainer at ⁴³²³4680'. Mix 43 sxs Type III cement, squeeze 27 sxs outside and leave 16 sxs inside to cover the Chacra top. PUH to 3630'.
5. **Plug #3 (Pictured Cliff top, 3630' – 3530')**: Mix 16 sxs Type III cement and spot a balanced plug inside the casing to cover the Pictured Cliffs top. PUH to 3240'.
6. **Plug #4 (Fruitland top, 3240' – 3140')**: Mix 16 sxs Type III cement and spot a balanced plug inside the casing to cover the Fruitland top. TOH with tubing.
7. **Plug #5 (Kirtland and Ojo Alamo tops, 2830' – 2520')**: Perforate 3 squeeze holes at 2830'. Attempt to establish rate into squeeze holes if casing pressure tested. TIH and set 5.5" cement retainer at 2780'. Mix and pump 119 sxs Type III cement, squeeze 82 sxs outside and leave 37 sxs inside to cover through the Ojo Alamo top. TOH with tubing.
8. **Plug #6 (Nacimiento top, 1400' – 1300')**: Perforate 3 squeeze holes at 1400'. Attempt to establish rate into squeeze holes if casing pressure tested. TIH and set 5.5" ^{Cement} casing at 1350'. Mix and pump 43 sxs Type III cement, squeeze 27 sxs outside the casing and leave 16 sxs inside casing. TOH and LD tubing.
9. **Plug #7 (10.75" casing shoe and surface, 188' - Surface)**: Perforate squeeze holes at 188'. Establish circulation out the bradenhead valve with water. Mix and pump approximately 90 sxs cement down the 5.5" casing to circulate good cement out bradenhead. Shut well in and WOC.
10. ND BOP and cut off casing below surface casing flange. Install P&A marker with cement to comply with regulations. RD, move off location, cut off anchors and restore location.

Recommended:


Operations Engineer

Engineer

Office - (599-4043)
Cell - (320-0321)

Approved:


Drilling Superintendent

San Juan 30-6 Unit #80

Current

AIN # 6980901, Blanco Mesaverde

Today's Date: 6/21/05

Spud: 12/10/52


Completion: 2/2/53

Elevation: 6647' GL

1850' FSL, 1190' FWL, Section 17, T-30-N, R-6-W

Rio Arriba County, NM, API #30-039-07843

Lat: N 36.81036 / Long: W 107.49062



San Juan 30-6 Unit #80

Proposed P&A

AIN # 6980901, Blanco Mesaverde

Today's Date: 6/21/05

Spud: 12/10/52

Completion: 2/2/53

Elevation: 6647' GL

1850' FSL, 1190' FWL, Section 17, T-30-N, R-6-W

Rio Arriba County, NM, API #30-039-07843

Lat: N 36.81036 / Long: W 107.49062

