<b>→</b> .	ENT OF THE INTERIOR OF LAND MANAGEMENT	
Sundry Not	ices and Reports on Wells	
	2005 SEP 7 PM	
1. Type of Well GAS	RECEIVED 070 FARMINGT(	· · · · · · · · · · · · · · · · · · ·
2. Name of Operator BURLINGTON		7. <b>Unit Agreement Name</b> San Juan 28-4 Unit
RESOURCES OIL & GA	S COMPANY	8. Well Name & Number
3. Address & Phone No. of Opera PO Box 4289, Farmington, NM		San Juan 28-4 Unit 33 9. <b>API Well No</b> . 30-039-20175
4. Location of Well, Footage, 8 890'FSL, 990'FWL, Sec. 33, 7	· · · ·	10. Field and Pool Blanco Mesaverde/Basin Dakot; 11. County and State Rio Arriba Co, NM
Type of Submission _X_ Notice of Intent Subsequent Report Final Abandonment	Recompletion New Plugging Back Non- Casing Repair Wate Altering Casing Conv X Recompletion	ge of Plans Construction Routine Fracturing Ex Shut off Version to Injection  SEE ATTACHED FOR
Adhpento previously issued stipulation	ete and commingle the Dakota we of intent is approved, a Down	Mnole Commingle Will be
14. I hereby certify that the Signed Could	Title PE  any person knowingly and willfully to make to any	Date 9/19/05  Date of the
	d HC	1996AZ

UNITED STATES

submitted in lieu of Form 3160-5

MMOCD

## San Juan 28-4 Unit #33 Sundry Procedure

Unit M, Section 33, T28N, R04W

- 1. MIRU completion rig. TOOH with tubing.
- 2. Set cast iron bridge plug at 8434'.
- 3. Pressure test casing to  $\pm /-3000$  psi for 15 minutes.
- 4. Perforate and fracture stimulate the Point Lookout, Menefee and Cliff House formations.
- 5. Flow back well. Mill out frac plug and cast iron bridge plug over Dakota.
- 6. Clean out as required.
- 7. Land tubing. RDMO rig.
- 8. Return well to production as a commingled DK/MV producer.

## San Juan 28-4 Unit #33

890' FSL , 990' FWL Unit M, Section 33, T28N, R04W Rio Arriba County, NM

LAT: 107 deg 15.64 min GL = 7.305'

LONG: 36 deg 36.69 min



