Form 3160-5 (August 2007)

#### **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

Lease Serial No.

SF-078049-A

SUNDRY NOTICES AND REPORTS ON WELLS	
ot use this form for proposals to drill or to re-enter	an

6. If Indian, Allottee or Tribe Name

Do not use abandoned	e this form for proposals t well. Use Form 3160-3 (A	717-17-17-1	RCVD DEC 2'13 OIL CONS. DIV.			
	BMIT IN TRIPLICATE - Other ins			7-If-Unit of CA/Agreement		
1. Type of Well		NOV	22 <b>2</b> 0	8 Well Name and No.	DIST. 3	
Oil Well	X Gas Well Other	( <del>-</del>			Hardie 2	
2. Name of Operator	ConocoPhillips Compa		i Field ( id iVlana	9 APL Well No.	0-045-20112	
3a. Address PO Box 4289, Farmington	3b. Phone No. (include area (505)-326-97	code)	10. Field and Pool or Exploratory Area  Basin-DK			
4. Location of Well (Footage, Sec., T., Surface UL: D (N	R.,M., or Survey Description) WNW), 970' FNL & 850' F\	WL, Sec. 28, T29N, R	8W	11. Country or Parish, State San Juan	, New Mexico	
12. CHECK	THE APPROPRIATE BOX(ES)	TO INDICATE NATUR	E OF NOT	TICE, REPORT OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	=	roduction (Start/Resume)	Water Shut-Off Well Integrity	
X Subsequent Report	Casing Repair Change Plans	New Construction  X Plug and Abandon		ecomplete emporarily Abandon	Other	
Final Abandonment Notice	Convert to Injection	Plug Back		Vater Disposal		
13. Describe Proposed or Completed O	peration. Clearly state an pertinent di	rians, mending estimated sta	rung date of	i any proposed work and app	noximate duration thereof.	

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

10/15/13 - Procedure was to cut casing @ 2800' & run CBL. Looks like mud behind casing, asked to perf to see if can circ. If can circ, will use mud, cut it, pull casing & log, if cannot circ, will try to pump cement behind 7" casing. CBL shows TOC @ 2405'. Called Brandon Powell w/ OCD & got approval. Walter Gage is on site for BLM. Crew called back & said after perf, there is cement behind & inside 7" Called Brandon back @ OCD to make sure he is still ok to cut offf @ 2400'. Got approval. 10/16/13 - asked to combine plugs 6&7 due to only having 3' to perf between them, Brando Powell w/ Ocd was called and gave verbal approval after review of 2/2013 CBL but did ask to be called back after circ was achieved. This call was made to notify OCD. 10/21/13 - Ran CBL on 7" & found no cement behind plug 9 area, asked to change from balance plug to inside/outside, perf @ 2138' & set retainer. Called Brandon w/ OCD and he gave verbal approval.

The subject well was P&A'd on 10/25/13 per the above notifications & attached report.

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Title Staff Regulatory Technician **Kenny Davis** 11/22/2013 Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by

Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify Office that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department. false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

# A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 \*fax: 505-325-1211

Conoco Phillips Hardie 2

October 25, 2013 Page 1 of 3

970' FNL and 850' FWL, Section 28, T-29-N, R-8-W San Juan County, NM Lease Number: SF-078049 API #30-045-20112

Plug and Abandonment Report
-Notified NMOCD and BLM on 10/4/13

### Plug and Abandonment Summary:

- Plug #1 with 24 sxs (28.32 cf) Class B cement inside casing from 7244' to 6928' to cover the Dakota and Graneros tops. Tag TOC at 7117'.
- Plug #2 with 32 sxs (37.76 cf) Class B cement inside casing from 6212' to 5791' to cover the Gallup top. Tag TOC at 5077'.
- Plug #3 with 32 sxs (37.76 cf) Class B cement inside casing from 5712' to 5291' to cover the Mancos top. Tag TOC at 5541'.
- Plug #4 with 32 sxs (37.76 cf) Class B cement with 2% CaCl inside casing from 4653' to 4232' to cover the Mesaverde top. Tag TOC at 4311'.
- Plug #5 with 32 sxs (37.76 cf) Class B cement inside casing from 4005' to 3584' to cover the Chacra top. Tag TOC at 3667'.
- Plug #6 (combined #7) with CR at 3145' spot 67 sxs (79.06 cf) Class B cement 36 sxs in annulus, 4 sxs below CR and 27 sxs above CR from 3193' to 2790' to cover the Intermediate shoe and Pictured Cliffs tops. Tag TOC at 2787'.
- Plug #8 with 50 sxs (59.00 cf) Class B cement inside casing from 2787' to 2299' with 30 sxs in 4.5" casing, 20 sxs in 7" casing to cover the Liner top and Fruitland top. Tag TOC at 2339'.
- Plug #9 with CR at 2097' spot 142 sxs (167.56 cf) Class B cement inside casing from 2138' to 1743' with 64 sxs in annulus, 8 sxs below CR, 70 sxs above CR to cover the Ojo Alamo and Kirtland tops. Tag TOC at 1818'.
- Plug #10 with CR at 595' spot 76 sxs (89.68 cf) Class B cement inside casing from 645' to 393' with 26 sxs in annulus, 10 sxs below CR, 40 sxs above CR to cover the Nacimiento top. Tag TOC at 386'.
- **Plug #11** with CR at 197' spot 139 sxs (164.02 cf) Class B cement in annulus from 265' to surface. Continue to mix and pump 55 sxs from 197' to surface to cover the surface casing shoe.
- Plug #12 with 26 sxs Class B cement top of casing and install P&A marker.

#### **Plugging Work Details:**

- 10/7/13 Rode rig equipment to location. Spot in and RU. Check well pressures: tubing 300 PSI, casing 550 PSI and bradenhead 0 PSI. RU A-Plus relief lines and blow well down. ND wellhead and NU kill spool. Pressure test pipe rams to 300# and 1500#, OK. Pull tubing hanger install stripping rubber. Attempt to pump 76 bbls with 4 bpm at 1200#. Establish rate of 3.5 bpm at 800 PSI lost circulation. SI well. SDFD.
- 10/8/13 Bump test H2S equipment. Open up well; no pressures. Perform function test on BOP. TOH and tally 170 jnts, 2-3/8" tubing, 4.7# EUE total 5376'. RU Air package. TIH and tally PU 174 jnts, A-Plus tubing, EUE 4.7#, 2-3/8" tubing tag CIBP at 5420'. LD 1 jnt with 3-7/8" cone bit and bit sub on bottom. PU power swivel and install 2-3/8" stripping rubber. Drill 6" on CIBP. PUH and rolled well clean. SI well. SDFD.

## A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 \*fax: 505-325-1211

Conoco Phillips Hardie 2

October 25, 2013 Page 2 of 3

### Plugging Work Details (continued):

- Bump test H2S equipment. Check well pressures: tubing and bradenhead 0 PSI and casing 100 PSI. RU air package. Wait on circulation. Drill out CIBP at 5420'. PU 2 jnts with PS, no tag. RD power swivel. Continue to TIH and tally 56 jnts (A-Plus) tubing 2-3/8" (232 jnts total). Tag CIBP at 7244'. LD 1 jnt, PU 2-10' subs. Pump 120 bbls, no circulation. LD 2-10' and1 jnt. TOH with 115 stands, LD bit sub and bit. PU 4' plugging sub, TIH with 115 stands. RU sandline and RIH establish fluid level at 1500'. Spot plug #1 with estimated TOC at 6928'. SI well. SDFD.
- 10/10/13 Bump test H2S equipment. Open up well; no pressures. TIH and tag TOC at 7117'. RU sandline, RIH find fluid level at 1500 PSI. Spot plug #2 with estimated TOC at 5791'. WOC. TIH and tag cement stringer at 5077'. SI well. SDFD due to weather.
- 10/11/13 Bump test H2S equipment. Open up well; no pressures. RU power swivel. Tag TOC at 5077'. Attempt to circulate with 60 bbls, no circulation. Reverse circulate. Drilled out stinger from 5077' to 5079'. TIH and tag TOC at 6011'. RU sandline and establish fluid level at 1500'. Spot plug #3 with estimated TOC at 5291'. SI well. SDFD.
- 10/14/13 Bump test H2S equipment. Open up well; no pressures. Function test BOP. TIH and tag TOC at 5541'. Establish circulation. Spot plug #4 with estimated TOC at 4232'. TIH and tag TOC at 4311'. Establish circulation. Spot plug #5 with estimated TOC at 3584'. SI well. SDFD.
- 10/15/13 Bump test H2S equipment. Open up well; no pressures. TIH with 4.5" string mill to 3667'. Pressure test casing to 800 PSI, bled down to 0 in 5 minutes. Perforate 3 HSC holes at 3193'. Establish rate of 1.5 bpm at 1000#. TIH with 4.5" DHS CR and set at 3145'. Pressure test tubing to 1000#, OK. Establish circulation. Pressure test casing to 800 PSI, bled down to 0 in 5 minutes. Establish rate of 1-1/4 bpm at 800 PSI. Note: BLM and NMOCD approved to combine plugs. Spot plug #6 combined with #7 estimated TOC at 2790'. SI well. SDFD.
- 10/16/13 Bump test H2S equipment. Open up well; no pressures. TIH and tag TOC at 2787'. Ran CBL from 2787' to 1000', estimated TOC at 2420'. Wait on orders. Note: J. Morris, COPC received approval for procedure change. Perforate 3 HSC holes at 2718'. Attempt to establish rate, pressure test to 800 PSI no rate. Perforate 3 HSC holes at 2718'. Attempt to establish rate, no rate. Pressure test to 800 PSI. Note: J. Morris, COPC received approval for procedure change. ND BOP and wellhead. Weld on slip collar on 4.5" casing. NU x-over spool and kill spool, BOP. SI well. SDFD.
- 10/17/13 Bump test H2S equipment. Open up well; no pressures. ND BOP. RU 6' 4.5" sub, and attempt to pull slips, unable to pull. RU High Desert. Welder cut plate top of slips, work plate off. Attempt to pull slips, still unable. RIH with Jet Cutter and cut casing at 2400'. Strip on x-over spool. RU San Juan Casing. SI well. SDFD.

## A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 \*fax: 505-325-1211

Conoco Phillips Hardie 2 October 25, 2013 Page 3 of 3

#### Plugging Work Details (continued):

- 40/21/43 Bump test H2S equipment. Open up well; no pressures. TIH with 7" string mill. Establish circulation. Ran CBL from 2400' to surface. Establish circulation. Spot plug #8 with estimated TOC at 2299'. WOC. SI well. SDFD.
- 10/22/13 Bump test H2S equipment. Open up well; no pressures. TIH and tag TOC at 2339'. Note: BLM and NMOCD approved procedure change. Attempt pressure test got circulation out bradenhead, no test. Perforate 3 HSC holes at 2138'. TIH with 7" DHS CR and set at 2097'. Establish circulation. Attempt to pressure test casing, establish circulation out bradenhead, no test. Sting into CR and establish rate of 3 bpm at 800 PSI. Spot plug #9 with estimated TOC at 1743'. WOC. TIH and tag TOC at 1818'. Attempt to pressure test casing establish circulation out bradenhead, no test. Perforate 3 HSC holes at 645'. TIH with 7" DHS CR and set at 595'. Attempt to pressure test casing establish circulation out bradenhead 2 bpm at 500 PSI. Spot plug #10 with estimated TOC at 393'. Reverse circulate at 311' with 4 bbls no cement. SI well. SDFD.
- 10/24/13 Bump test H2S equipment. Open up well; no pressures. TIH and tag TOC at 386'. Establish circulation. Perforate 4 holes at 265'. TIH with DHS CR and set at 197'. Establish circulation. Pressure test casing to 800 PSI for 30 minutes. Establish circulation. Spot plug #11 with estimated TOC at surface. Reverse circulate. Dig out wellhead. WOC. SI well. SDFD.
- 10/25/13 Bump test H2S equipment. Open up well; no pressures. TIH tag TOC in 7" casing with tally tape at 6'. ND BOP and kill spool. RU High Desert. Cut off wellhead. Top off casing. Spot plug #12 and install P&A marker. RD and MOL.

Walter Gage, BLM representative, was on location. Jim Morris, MVCI representative, was on location.