Form 3160-5 (August 2007)		ED STATES	DR DEC		CMB 1	1 APPROVED NO. 1004-0137	
- '		AND MANAGEME	ENT Li Valizza La		5. Lease Serial N	s July 31, 2010	
	SUNDRY NOTICES A	AND REPORTS	ON WELLS	21 2014	SF-077972		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals ington Field Offic					6. If Indian, Allottee or Tribe Name		
abanc	loned well. Use Form	3160-3 (APD) foi					
	IBMIT IN TRIPLICATI	E - Other instructio	ns on page 2	မ်းကို ကြင်းကြည့်များ	7. If Unit or CA/A	Agreement, Name and/or	
1. Type of Well Oil Well X Gas Well Other						8. Well Name and No. Richardson #7	
2. Name of Operator Energen Resources	Corporation						
3a. Address	3b. Phone No. (include a	Phone No. (include area code)		9. API Well No. 30–045–26082			
2010 Afton Place, Farmington, NM 87401			(505) 325-68	(505) 325-6800		10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage,	Sec., T., R., M., or Survey De	escription)				/Fruitland Coal	
833' FNL, 2142' FE	L Sec. 03, T27N,	R13W (B) NW/N	2			· h. State	
					11. County or Pa San Juan	Irish, State	
12. 0	CHECK APPROPRIATE	BOX(ES) TO INI	DICATE NATURE OF	NOTICE REPO			
TYPE OF SUB	r			YPE OF ACTION			
X Notice of Inte	ent	Acidize	Deepen	Production	(Start/Resume)	Water Shut-Off	
Subsequent F	Renort	Alter Casing	Fracture Treat	Reclamatic	on L	Well Integrity	
		Casing Repair	New Construction	Recomplet	te L	Other	
Final Abando	onment Notice	Change Plans	X Plug and Abandon	Temporaril	ly Abandon		
	Br	Convert to Injecti	on Plug Back	Water Disp	posal		
Attach the Bond under following completion or testing has been comple determined that the fina	pen directionally or recomple which the work will be perfect f the involved operations. If eted. Final Abandonment No l site is ready for final inspec	ormed or provide the l the operation results i otices shall be filed or ction.)	Bond No. on file with BLN a a multiple completion or ly after all requirements, i	M/BIA. Required su recompletion in a n including reclamation	ubsequent reports s new interval, a Forn on, have been com	hall be filed within 30 da n 3160-4 shall be filed or pleted, and the operator l	
Energen Resource	es plans to plug an	id abandon the	Kichardson #/ aco	ording to the	e attached pr	oceaure.	
This will be a closed loop operation.				RCVD JAN 24'14 OIL CONS. DIV.			
		nrio	NMOCD 24 hrs r to beginning			ST. 3	
			operations				
14. I hereby certify that the fo Name (Printed/Typed) Collin Placke			Title Distr	ict Engineer			
Signature	h Plarke		Date 01/20/2	14			
	THIS	SPACE FOR FEE	ERAL OR STATE O	FFICE USE			
Approved by O	Title	Title		Date JAN 2 3 2014			
Conditions of approval, if any, are the applicant holds legal or equitat entitle the applicant to conduct ope	ole title to those rights in the subj	e does not warrant or cer	ify that Office		I	~~~	
Title 18 U.S.C. Section 1001, and	Title 43 U.S.C. Section 1212, m		rson knowingly and willfully to	o make to any departm	nent or agency of the	Jnited States any false,	
fictitious or fraudulent statements	or representations as to any matt	er within its jurisdiction.			<u> </u>		
			ուտ թունին նանդանին հետում				

.



PLUG AND ABANDONMENT PROCEDURE

December 18, 2013

Richardson #7

Basin Dakota / Fruitland Coal 833' FNL, 2142' FEL, Section 03, T27N, R13W, San Juan County, New Mexico API 30-045-26082 / Long _____/ Lat: _____

- Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.
 - Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
 - Rods: Yes___, No_X_, Unknown____. Tubing: Yes___, No_X_, Unknown____, Size _____, Length _____. Packer: Yes___, No_X_, Unknown___, Type _____.
 - Plug #1 (Pictured Cliffs and Fruitland Intervals, 1404' 1105'): PUH tubing workstring and trip in hole. Tag existing CIBP at 1404'. Pressure test tubing to 1000#. Pressure test casing to 800#. <u>If</u> <u>casing does not test, then spot or tag subsequent plug as appropriate</u>. Spot 27 sxs Class B cement inside casing from 1404' to isolate the Pictured Cliffs and Fruitland intervals. PUH.
 - 4. Plug #2 (Kirtland and Ojo Alamo tops, 8-5/8" Surface casing shoe, 695' Surface): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 55 sxs cement and spot a balanced plug from 695' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth (s) and attempt to circulate cement to surface filling the casing to surface (as approved). Shut in well and WOC.
 - 5. ND BOP and cut off wellhead below surface casing flange. Install P&A marker with cement to comply with regulations. RD, MOL and cut off anchors. Restore location per BLM stipulations.

Richardson #7

Current

Basin Dakota / Fruitland Coal

833' FNL & 2142' FEL, Section 03, T-27-N, R-13-W, San Juan County, NM

___/ Long: W ___ _____/ API #30-045-26082 Lat: N __ Today's Date: 12/18/13 Spud: 9/23/84 TOC at surface, circulated to surface DK Completed: 1/17/85 according to sundry report. FtC Completed: 9/2/08 8-5/8" 24#, K-55 Casing set @ 334' 12-1/4" hole Elevation: 5999' Gl Cmt with 100 sxs (Circulated to Surface) 6383' KB Ojo Alamo @ 490' Kirtland @ 645' Fruitland @ 1155' Set CIBP @ 1404' (2010) Fruitland Coal Perforations: 1446' - 1472' Pictured Cliffs @ 1480' Set CIBP @ 1650' (2008) Existing Plug #3a: 2449' - 2349' 12 sxs Class G Cement Existing Plug #3: 2449' - 2435' Mesaverde @ 2399' 12 sxs Class G Cement TOC at DV tool, (calc 75%) DV Tool @ 2880' Stage 2: Cement with 1300 sxs Circulate cement to surface Existing Plug #2: 5205' - 5105' 12 sxs Class G Cement Gallup @ 5155' Existing Plug #1: 6050' - 5912' 12 sxs Class G Cement Set CIBP @ 6070' (7/08) Dakota @ 6100' Dakota Perforations: 6120' - 6211' 7-7/8" hole 4-1/2" 1j0.5#, K-55 Casing set @ 6377' Stage 1: Cement with 840 sxs (1242 cf)

> TD 6383' PBTD 1650'

Richardson #7 Proposed P&A

Ŷ

Basin Dakota / Fruitland Coal



TD 6383' PBTD 1650'