	State	of New M	1exico	
Energy,	Minerals and N	latural I	Resources	Department

Susana Martinez Governor David Martin Cabinet Secretary-Designate	Jami Bailey, Division Director Oil Conservation Division	SHE OF NEW MEXCO					
Brett F. Woods, Ph.D. Deputy Cabinet Secretary		OR CONSERVATION DUNS					
New Mexico Oil Conservation Divis listed below are made in accordance and are in addition to the actions a following <u>3160-4 or 3</u>	with OCD Rule 19 approved by BLM of	.15.7.11					
Operator Signature Date:							
Application Type: P&A Drilling/Casing	•	omplete/DHC					
Location Change Other:							
Well information: XPIWELL # Vell Name Well # Operator Name Type 30-045-31055-00-00 NV NAVAJO 21 003 XTO ENERGY, INC G	Stat County Surf Owner UL Sec A San Juan N L 21	Twp N/S Rng W/E 29 N 14 W					

Conditions of Approval:

Notify NMOCD 24hrs prior to beginning operations

Add a plug from 978'-1078'. This plug is not required to be tagged

NMOCD Approved by Signature

FEB 1 9 2014

Date

.

Form 3160-5 (August 2007)	DEPARTM	IITED STATES ENT OF THE INTERI 7 LAND MANAGEME			CEIV	E E	ORM APPROVED MB NO. 1004-0137 xpires July 31, 2010		
- Di aba	SUNDRY NOTICES o not use this form for andoned well. Use Fo	AND REPORTS (ON WE	enter an roposalsଆଣ୍ଡ		6. If Indian, J	rial No. L 99 Allottee or Tribe Name		
<u> </u>	SUBMIT IN TRIPLICA	TE - Other instructio	ns on pa		fland have	1	CA/Agreement, Name and/or No		
Type of Well Oil Well Oil Well X Gas Anne of Operator	Well Other	· · · · · · · · · · · · · · · · · · ·				8. Well Nam NV NAVAJO			
XTO ENERGY INC.	· · · ·		21 01			9. API Well	No.		
3a. Address 382 CR 3100, AZ	TEC. NM 87410			ne No. (<i>include arc</i> 505) 333-363	-	30-045-31055 10. Field and Pool, or Exploratory Area			
	ge, Sec., T., R., M., or Survey	Description)		<u></u>	<u> </u>	1	JITLAND COAL		
1660' FSL & 710	'FWL NWSW SEC.	21 (L) -T29N-R14W	NME	M		11. County of SAN JUAN	or Parish, State		
12.	CHECK APPROPRIAT	E BOX(ES) TO INE	DICATE	NATURE OF N	IOTICE, REPO	RT, OR OTH	IER DATA		
TYPE OF S	UBMISSION			TYI	PE OF ACTION				
X Notice of		Acidize		Deepen Fracture Treat	Production Reclamatio	(Start/Resume) n	Water Shut-Off		
	nt Report Indonment Notice	Casing Repair Change Plans Convert to Injectic	X	Vew Construction Plug and Abandon Plug Back	Recomplete Temporaril Water Disp	y Abandon	Other		
If the proposal is to Attach the Bond und following completion testing has been con determined that the f XTO Energy In d	deepen directionally or recon der which the work will be pen of the involved operations.	plete horizontally, give su erformed or provide the H If the operation results in Notices shall be filed on ection.) and abandon this	ibsurface Bond No. 1 a multipl ly after al well g	locations and meas on file with BLM/ e completion or re l requirements, inc	ured and true ver BIA. Required s completion in a n luding reclamatio	tical depths of ubsequent repo lew interval, a n, have been c ure and wi	-		
Closed hoop s	ystem. Flease see a	iso the attached	currer		sed wermore	-	:VD JAN 23'14		
							IL CONS. DIV.		
						<u>ار</u> ا			
							DIST. 3		
Name (Printed/Typed)	e foregoing is true and correct		Titl			-			
Signature Signature			Dat		TORY ANALYS	<u>r</u>			
<u></u>		S SPACE FOR FED							
Approved by		·····		Title		I	Date 0014		
Conditions of approval, if any,	Original Signed: Step are attached. Approval of this no	tice does not warrant or certi	fy that	Office			JAN 2 1 2014		
	itable title to those rights in the su		-						

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



NV Navajo 21 #3 Sec 21, T 29 N, R 14 W San Juan County, New Mexico

Plug and Abandon Procedure

Spud Date:	6/4/2005					
Surface Casing:	8-5/8", 24#, J-55 csg @ 235'. Cmt'd w/112 sx. Circ 12 bbls cmt to surf.					
Production Casing:	5-1/2", 15.5#, J-55 csg @ 1,159'. Cmt'd w/100 sx (lead) & 65 sx (tail). Circ 15 bbls cmt to surf. Ran CBL on 7/14/2005. Good cmt to surf. Capacity: .023802 bbls/ft or .9997 gal/ft					
Production Tubing:	l jt 2-3/8", 4.7#, J-55, 8rd EUE tbg, 2-3/8" x 6' tbg sub, 29 jts 2-3/8", 4.7#, J-55, 8rd EUE tbg & 2-3/8" x 2" x 16' TWE (DV) pmp w//1-1/4" strnr nip. EOT @ 1,006'.					
Rod String:	1-1/4" x 22' PR w/10' Inr, 36 - 3/4" rods, 2 - 1-1/2" sbs, 21K shear tl, 1-1/2" sb, spiral rod guide & on-off tl.					
Perforations:	Fruitland Coal: 958' - 978'					
PBTD:	1,124'					
Recent Production:	INA since 8/27/2009. 2 mcfpd, 100 bwpd					
Notify NMOCD & BLM 24 hours prior to beginning plugging operations						

- 1. Check for COA's and approved NOI before beginning operations.
- 2. Test rig anchors.

٠

- 3. Set flowback tank.
- 4. MIRU completion rig. Review JSA.
- 5. TOH rods & on-off tool. ND WH. NU & FT BOP. TOH & LD tubing and pump.
- 6. TIH with 4-3/4" bit & 4-3/4" string mill on 2-3/8" workstring to 958'. TOH.
- 7. TIH 5-1/2" CIBP and set @ \pm 908'. Circulate hole clean.
- 8. PT casing and CIBP to 550 psig for 10 minutes. Record test on chart. If casing does not test, contact engineer.
- 9. MIRU cement truck. Review JSA.

- 10. Perforation Isolation Plug (908' 858'): Pump 15 sx Class "B" cement (15.6 ppg, 1.18 cuft/sx yield) down tubing and spot balanced plug from 908' - 858' (volume calculated with 50' excess). $\xrightarrow{}$ f'_{a} f'_{a}
- 11. Fruitland-Coal Fop-& Casing Shoe Plug (292' Surface): Pump 40 sx Class "B" cement (15.6 ppg, 1.18 cuft/sx yield) down tubing and spot a balanced plug from 292' Surface (volume calculated with 50' excess).
- 12. TOH & LD tubing.
- 13. RDMO cement truck.
- 14. WOC 4 hours.
- 15. Cut off WH. Fill in casing as needed with cement. Install above ground P&A marker.
- 16. Cut off anchors and reclain location.

Checklist

REGULATORY:

- 1. NOI to P&A on form C-103
- 2. Submit a post-work sundry on form C-103 which details the P&A work and location work within 30 days of completing all required restoration work.

Equipment:

- 1. 1 flowback tank
- 2. 1,000' 2-3/8" workstring
- 3. 1 4 3/4" bit
- 4. 1 4 3/4" string mill
- 5. 1 5-1/2" CIBP
- 6. 55 sx Class "B" cement
- 7. 1 above ground marker

Services:


- 1. Completion rig
- 2. Cement truck



Current XTO - Wellbore Diagram

Well Name: NV Navajo 21-03

3004531055000) FWL	N/S Dist (ft) 1,660.0	N/S F	FSL T2	Location T29N-R14W-S21		1 Bas	Field Name Basin Fruitland Coal			Sa	^{nty} n Juan	State/Province New Mexico	
ell Configuration Ty ertical	ype XTO ID B Orig KB Elev (ft) 77474 5,600.00		Gr Elev (ft) 5,590.00	KB-G	rd (ft) Spu 10.00	ud Date 6/4/20	05		o (All) (fth riginal H		1124		I Depth (ftKB 1,170.0		Production
		Original Hole, 1/13/2014		 	Zones	0/4/20	00		iginai r		1124.		1,170.0	Beam	
		<u></u>	ftKB	ftKB		Zone					KB)			Btm (ftKB)	
Schematic - Actual.		Incl (TVD)	- (MD) [*]	Fruitland Coa					```		958.	0		97	
					Casing Strin	ngs		, ,	a Nara (M Narat (Mari						
			0			D(in)			tring Gra	de Top C	onnection Se	et Depth (f 235.0			
							0 5/0 DD (in)			4.00 J-5 s/ft) String Gra			onnection Se	z 35.0 et Depth (f	
			5	Production			5 1/2		15.5		J-5{			1,159.0	
					Cement		1		દ્રો છે.						
				9	Description			Туре					String	005 0000	
					Surface Casi	ing Ceme	ent	cas	ing				Surface	, 235.0ftKB	
		uran na kanana kanan karanan karanan kanan ka		10	Contantent										
					Description			Туре					String		
				22	Production C	casing Ce	emen	t cas	ing				Product	tion, 1,159.0	OftKB
					Comment										
				43	Perforations			1. 1. 1. 1. L.	· 	•		· · "		4	
				49	Perforations	3	·		<u> </u>	<u>.</u>	Hole	rret.			
				49					Shot	Dens	Diamet	er Phás	ing Curr		
				235	Date 7/14/2005	Top (fth	(B) <u>)</u> 58.0	Btm (ftK	B)., (shi 8.0	ots/ft) 3.0	(in)	(")		Zor	
				200	7/14/2005		53.0		8.0	3.0				Fruitland Co Fruitland Co	
	1 11 12			236			/0.0	57	<u></u>	0.0		1			
				200	Tubing Strin			Run	Date		<u>.</u>		Set Depth	(ffK8)	
				922	Tubing - Proc			, call		2/12/2	009		our bopai	1,006.2	
					Tubing Com	ponents	;			· .	·	•	7		
E				924	Item Descrip	1 - F 2		Model		Wt (lbs/	6	Top ' Thread	. han (fi)	Tap (BI(D)	Dim (Å)
					Tubing	puon,		T&C			J-55		Len (ft) 32.55	5 Top (ftKB)	4 Bun (nk
n-E				958				Upset				EUE			
					Tubing Sub		1	T&C	2 3/8	4.70	J-55	8RD	6.10	42.5	4
				963	-			Upset				EUE			
		Top (MD):958, Des:Fruitland Coal			Tubing			T&C	2 3/8	4.70	J-55		875.58	3 48.6	924
				972				Upset				EUE			
					Tubing			T&C Upset	2 3/8	4.70	J-55	8RD EUE	65.95	924.2	990
				972	Tubing Barre	Dump			2 3/8			8RD	16.00	990.2	1,006
le l					Tubing barre	arump	'		2 3/0			EUE	10.00	990.2	1,000
°Ľ				978	Rods							1		a f a sa	· • • •
				983	Rod Description		Run	Date 🥂	<u> </u>	<u>() (</u>	itrina Le	ngth (ft)	<u> </u>	Set Depth (ftKB	() ()
				903	Rod String			2/12/			-	998.4	0	998	
E				990	Rod Compo	nents									
					Item Dese Polished Roc		<u>. 15</u>	Jts 1	Model		D (in) (G 1/4	rade	tien (ft) 22.00	Top (ftKB) 1	Btm (ftK 2
E		/		997	Sucker Rod			1	CN-78		3/4 D		900.00	22.0	922
					Sinker Bar			2	55	1	1/2 K		50.00	922.0	972
Ē				997	Shear Tool - 2	21K		1			3/4		0.50	972.0	972
					Sinker Bar			1		1	1/2 K		25.00	972.5	99
				998	Spiral Rod G	Guide		1 :			3/4		0.40	997.5	997
PBTD, 1,124	1 M B				On-Off Tool			1	7 7.19		3/4		0.50	997.9	99
				998	Stimulations					(ITet	al Pron) MTP (psi)	
	1 1 8				7/18/2005	iop i en (it,		G.,.	• (arouny)		ωι τυμ.	- Air (1 40			ion (psi)
				999	Comment			l_						l	I
E															
	1 1			1,006											
PBTD,	1 12			4 4 4 4 4											
1,124				1,124											
n /	1 12			4 455											
	- •~			1,159											
D, 1,170				1,170											



UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: 3 NV Navajo 21

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

3. The following modifications to your plugging program are to be made:

a) Place the Fruitland plug from 676'- 576'.

b) Place the Surface plug from 285' to suface.

c) High H2S has been encountered in the area, therefore you are required to have H2S personal and equipment on location during plugging operations.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.