Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

5. Lease Serial No. NMSF079341-A

| 5. | If Indian, | Allottee | or Tribe | Name |
|----|------------|----------|----------|---------|
| ٠. | n muan, | MILOUECE | OI TITUE | Ivaille |

| | apandoned w | ell. Use Form 3160-3 (APD) |) tor such prope | osais. | | | | |
|--|--|--|--|--------------|---|--|--|--|
| 1. | Type of Well | PLICATE - Other instruc | tions on reve | rse side | | | CA/Agreement, Name and/or No. | |
| Oil Well Gas Well Other 2. Name of Operator | | | | | | | 8. Well Name and No. San Juan 32-8 Unit #239A | |
| Col | nocoPhillips Co. | | T | | | 9. API Well 1 | | |
| | Address D. Box 2197, WL3-6085 | Houston Tx 77252 | 3b. Phone No. (ii (832)486-246 | | code) | 10. Field and Pool, or Exploratory Area | | |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 30 T32N R8W SENW 2035FNL 705FWL | | | | | | Basin Fruitland Coal 11. County or Parish, State San Juan NM | | |
| | 12. CHECK AP | PROPRIATE BOX(ES) TO | INDICATE NA | TURE O | F NOTICE, RI | EPORT, OR | OTHER DATA | |
| TYPE OF SUBMISSION TYPE OF ACTION | | | | | | | | |
| | Notice of Intent Subsequent Report | ☐ Acidize [☐ Alter Casing [☐ Casing Repair [| Deepen Fracture Treat New Construction | on \square | Production (Start/ Reclamation Recomplete | | Water Shut-Off Well Integrity Other Tubing Chg & | |
| | Final Abandonment Notice | ☐ Change Plans [☐ Convert to Injection [☐ | ☐ Plug and Aband ☐ Plug Back | | Temporarily Abar Water Disposal | ndon | Pump Repair | |
| | testing has been completed. Fin determined that the site is ready | d. Tubing now lands @ 36 | iled only after all req | ily summ | ncluding reclamat | ion, have been o | 2005 OCT 5 PM 12 3 | |
| | I hereby certify that the foregoir Name (Printed/Typed) | ng is true and correct | Title | | | | ۵ | |
| Chi | ristina Gustartis | | Re | gulatory | Specialist | | | |
| | Signature | 2 minto | Date 10/ | 03/2005 | | AĈ(. | <i>678</i> 57 | |
| | Puggi Balling Sta | THIS SPACE FO | R FEDERAL O | RSTATE | OFFICE USE | Ps. AAA | karina mana Mana - Kal | |
| Appr | oved by | | | Title | | Dat | DCT 0 5 2005 | |
| certif which | y that the applicant holds legal h would entitle the applicant to | | n the subject lease | | | BY_ | | |
| Title fraud | 18 U.S.C. Section 1001, make fulent statements or representate | s it a crime for any person knowir ions as to any matter within its ju | igly and willfully to | make to an | y department or a | gency of the U | nited States any false fictitious or | |

Regulatory Summary

ConocoPhillips

SAN JUAN 32 8 UNIT #239A

Repair Downhole Failure, 08/29/2005 07:00 API/Bottom UWI County State/Province Surface Legal Location N/S Dist (ft) N/S Ref E/W Dist (ft) E/W Ref 300453239600 SAN JUAN **NEW MEXICO** NMPM-32N-08W-30-E 2.035.00 705.00 N W **Ground Elevation (ft)** Latitude (DMS) Spud Date Longitude (DMS) Rig Release Date 107° 43' 9.3" W 36° 57' 25.164" N 6,679.00 08/18/2004 08/22/2004

08/29/2005 07:00 - 08/29/2005 19:00

Last 24hr Summary

Hold safety meeting and review JSA for moving rig. Move rig and equipment to San Juan 32-8 #239A. Hold safety meeting and review JSA for rigging up. Check LOTO, pressure and LEL. SICP - 356 psi; SITP - 0 psi. Move onto location and rig up rig and equipment. Blow well down to flow back tank and remove horse head. Try to pull pump. Lay down polish rod. Unable to pull pump. Rig up tongs and back off tool and back rods off. Recovered 75 rods. Remove tree and nipple up BOP. Rig up floor. Pressure test BOP; 250 psi for 3 min and 2000 psi for 10 min.. Secure well and location and SDFN.

08/30/2005 07:00 - 08/30/2005 17:30

Last 24hr Summary

Hold safety meeting and review JSA. Check LOTO and pressure. SICP - 375 psi; SITP - 0 psi. Unseat tbg hanger and lay down. Tag for fill @ 3599'. Rig up barrel and lines to catch fluid from tbg in pit and strap tbg out of well. Strip out of well and strap tbg. Strapped out . Pump stuck in bottom jt of 2-3/8" tbg. Lay down mud jt. Pick up bailer and TIH to 3628' and clean out to 3640'. TOH with bailer. Lay down and load out bailer, secure well and location and SDFN.

08/31/2005 10:30 - 08/31/2005 17:30

Last 24hr Summary

Monthly safety meeting for operators and supervisors. Drive to location. Hold safety meeting and review JSA. Check LOTO and pressure. SICP - . Clean coal out of mud anchor (approx. 16' of coal in mud anchor). Try to remove pump that is stuck in jt of tbg. Unable to remove pump. Pick up BHA and TIH with tbg as follows: 2-1/16" saw tooth collar (0.35'), 2-1/16" X 1.50 ID seating nipple (0.75'), 2-1/16" X 2-3/8" crossover (0.83'), 2-3/8" mud anchor with 1/2" hole just below upset (30.78'), 2-3/8" X 1.78" ID profile nipple (0.82'), 113 jts, 2-3/8", 4.7#, J-55, EUE 8rd tbg (3565.92'). EOT @ 3611.46' KB. Top of profile nipple @ 3577.92' KB. Rig down floor and nipple down and set out BOP. Install pumping tree and rig up to run pump and rods. Pick up and prime 2" X 1-1/4" X 12' X 12' 3" X 12' 6" RHAC-ZDV pump with 1" X 8' 12 slot sand screen. Pump # CP111. RIH with pump, 4 1-1/4" X 25' sinker bars, 138 3/4" "D" rods and space out with 2, 8' X 3/4" and 1, 6' X 3/4" pony rods. Space pump for light tag. Load tbg with 2% KCL water and pressure test tbg to 500 psi. Long stroke pump and function test. Re-check tag, attach horse head and hang rods on carrier bar and load cell. Rig down and prepare to move to Southern Ute 33-9; 20-4. Rig released @ 18:30. Job complete.