Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

F	٠.		\sim		- ()	7	<u>ئ</u> ت ب
- S. Francis	ſ,	·	1	بر الاستان	11	\$	
15	10	H	. ,		14 1	1	Same 1
I	17	<i>1</i> 222 /		-	123	_	-

FORM APPROVED OMB NO. 1004-0137 Expires July 31, 2010

Lease Serial No.

Date

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an IUN 16 2014

NMNM-024158

Do not use this form for p abandoned well. Use Forn	6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICAT	7. If Unit or CA/Agreement, Name and/or No.				
	Description) 20 (M) -T30N-12W	3b. Phone No. (include area code) 505-333-3630 N.M.P.M.		8. Well Name and No. FOOTHTILS A #1 9. API Well No. 30-045-25725 10. Field and Pool, or Exploratory Area WC FOOTHTILS FRUTTLAND SAND 11. County or Parish, State SAN JUAN NM	
12. CHECK APPROPRIATE TYPE OF SUBMISSION	BOX(ES) TO INDI		OTICE, REPO	RT, OR OTHER DATA	
Notice of Intent X Subsequent Report Final Abandonment Notice Final Abandonment Notice 13. Describe Proposed or Completed Operation (clearly If the proposal is to deepen directionally or recompled Attach the Bond under which the work will be perfollowing completion of the involved operations. If testing has been completed. Final Abandonment N determined that the final site is ready for final inspect XTO Energy Inc. has plugged and alwas used - Basin Disposal NM01-005	lete horizontally, give sub- formed or provide the Bo the operation results in a octices shall be filed only tion.) candoned this wel	surface locations and measind No. on file with BLM/lamultiple completion or reafter all requirements, incl	Reclamatio Recomplete Temporaril Water Disp g date of any pro ured and true ver BIA. Required so completion in a n luding reclamation	posed work and approximate duration thereof. tical depths of all pertinent markers and zones. ubsequent reports shall be filed within 30 days ew interval, a Form 3160-4 shall be filed once n, have been completed, and the operator has	
	OIL CONS. DI	V DIST. 3			
	ACCEPTED FOR RECORD				
				JUN 17 2014	
				FARMINGTON FIELD OFFICE BY: The Salvers	
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) SHERRY J. MORROW	·	Title REGULAT	TORY ANALYST		
	now	Date 6/13/14			

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

J

entitle the applicant to conduct operations thereon.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would

Approved by

Title

Office

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

XTO Energy Inc. Foothills A #1

June 3, 2014 Page 1 of 1

1185' FSL and 690' FWL, Section 20(M), T-30-N, R-12-W San Juan County, NM Lease Number: NMNM-024158 API #30-045-25725

Plug and Abandonment Report Notified NMOCD and BLM on 5/30/14

Plug and Abandonment Summary:

- Plug #1 with 10 sxs (11.8 cf) Class B cement inside casing from 1828' to 1465' to cover the Pictured Cliffs top. ✓
- Plug #2 with 16 sxs (18.88 cf) Class B cement inside casing from 1391' to 811' to cover the Fruitland top.✓
- Plug #3 with 17 sxs (20.06 cf) Class B cement inside casing from 440' to surface to cover the Kirtland. Ojo Alamo, 7" shoe and surface, 1) pump 13 sxs to circulate good cement out casing valve, 2) TOH LD all tubing and plugging sub and RU pump to casing, 3) pump 4 sxs to re-fill 2-7/8" casing.✓
- Plug #4 with 22 sxs Class B cement thru poly pipe to top off 7" casing and install P&A marker. ✓

Plugging Work Details:

- 5/30/14 Rode rig and equipment to location. SDFD.
- Spot in equipment and RU. X-over for 1-1/2" tubing. Check well pressures: SITP 260 PSI, SICP 250 PSI and SIBHP 0 PSI. Pump 10 bbls of water down tubing to kill well. ND wellhead. PU on tubing string and remove slips. Strip on companion flange. NU BOP and function test. TOH and tally 50 jnts 1-1/2" IJ tubing total 1594.22', SN and slotted MA 2 jnts with bad boxes. X-over for 1-1/4" tubing. Well unloading. Pump 10 bbls of water down casing to kill well. Spot plug #1 with calculated TOC at 1465'. SI well. SDFD.
- 6/3/14 Check well pressures: SICP on vacuum and SIBHP 0 PSI. TIH with 2-7/8" GR to 1400' and set PW CIBP at 1391'. PU plugging sub and tag CIBP at 1391'. Pressure up to 300 PSI, OK. Circulate well clean. Pressure test casing to 550 PSI, OK. ✓ Spot plugs #2 and #3. ND BOP. Dig out wellhead. RU High Desert. Write Hot Work Permit. Cut off wellhead. Spot plug #4 top off with poly pipe and install P&A marker. RD and MOL.

Mark Decker, BLM representative, was on location.