Form 3160-5 (August 2007)

Type of Well

Oil Well

UNITED STATES DEPARTMENT OF THE INTERIOR

Marie July 1

BUREAU OF LAND MANAGEMENT JUL 24 2014

FORM APPROVED

OMB No. 1004-0137 Expires: July 31,2010

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. Lease Serial No. MDA 701-98-0013, Tract 4

If Indian, Allottee, or Tribe Name

Jicarilla Apache Tribe If Unit or CA. Agreement Name and/or No. SUBMIT IN TRIPLICATE - Other Instructions on page 2. OIL CONS. DIV DIST. 3 Well Name and No. √ Gas Well

Name of Operator JUL **29** 2014 Black Hills Gas Resources, Inc.

Jicarilla 29-02-05 #44 API Well No.

3a. Address 3200 N 1st St, Bloomfield, NM 87413 3b. Phone No. (include area code) (505) 634-5104

30-039-29315

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

10. Field and Pool, or Exploratory Area

425' FSL & 425' FEL SE/SE Section 5 T29N R2W (UL: P)

Burro Canvon Tertiary/E.Blanco PC 11. County or Parish, State

Rio Arriba County, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent	Acidize	Deepen	Production (Start/ Resume)	Water Shut-off
·	Altering Casing	Fracture Treat	Reclamation	Well Integrity
X Subsequent Report	Casing Repair	New Construction	Recomplete	Other
_ BP	Change Plans	✓ Plug and abandon	Temporarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug back	Water Disposal	
112 Describe Proposed - Completed Co				

13. Describe Proposed or Completed Operation Clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

Black Hills Gas Resources has plugged & abandoned this well as follows:

See attachment.

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER **AUTHORIZATION REQUIRED FOR OPERATIONS** ON FEDERAL AND INDIAN LANDS

Approved as to plugging of the well bore. Liability under bond is retained until surface restoration is completed.

ACCEPTED FOR RECORD

JUL 24 2014

14. I hereby certify that the foregoing is true and correct. Name (Printed Typed)

Daniel Manus

Regulatory Techician

Signature

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify

that the applicant holds legal or equitable title to those rights in the subject lease which would

Title Office

entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false,

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

Approved by



Jicarilla 29-02-05 #44 Plug and Abandoned Subsequent Report

- 7/10/14: 11:00 AM, Notified Bryce Hammond, JAT-BLM, BLM Cement Hotline & B. Powell, NMOCD of upcoming operations.
- 7/14/14: MIRU A-Plus Well Service Rig #14. SITP 0 PSI. SICP 15 psi. SIBHP 0 psi. Blow down well. Load tubing with 4 bbls. Pressure test to 600 psi, held ok. TOH, lay down rods and pump. ND WH. NU & function test BOP. SDFN.
- 7/15/14: SITP 0 PSI. SICP 15 psi. SIBHP 0 psi. TOH with 2 3/8", 4.7#, J-55 prod tbg. TIH with 2 3/8" tubing. Tag PBTD at 3836'. Receive OK from Reuben Perea, JAT-BLM & B. Powell, NMOCD to spot Plug #1 from 3836'. Pump 25 bbls, establish circ. Pump 100 bbls total. Mix & pump Cmt Plug #1 (133 sx, 156.94 cu ft, 15.6 ppg, 1.18 yield, class 'B' cmt) from 3836' to 2662' to isolate PC, Fruitland, Kirtland & Ojo Alamo. TOH to 1330'. SDFN. Reuben Perea & Rod Velarde, JAT-BLM on location.
- 7/16/14: SITP 0 psi. SICP 0 psi. SIBHP 0 psi. Function test BOP. TIH, tag plug #1 at 2769'. TOH to 2257'. Pump 22 bbl, establish circ. Pump 25 bbl total. Mix & pump Cmt Plug #2 (28 sx, 33.04 cu ft, 15.6 ppg, 1.18 yield, class 'B' cmt, 2% CaCl2) from 2257' to 2010' to isolate Nacimiento. TOH. WOC. While WOC, load BH with less than 1/8 bbl. Pressure test BH to 300 psi, held ok. TIH with 5 ½" string mill. Tag plug #2 at 2001'. TOH. TIH with cement retainer to 1397'. Attempt but unable to set CR. TOH. SDFN. Rod Velarde, JAT-BLM on location.
- 7/17/14: SICP 0 psi. SIBHP 0 psi. Function test BOP. TIH with 5 ½" csg scraper to 1397'. TOH. A-Plus wireline set CIBP at 1372'. TIH, tag CIBP. Load hole with 23 bbl & circ clean with 34 bbl total. Pressure test csg with 800 psi, held ok 10 min. Mix & pump Cmt Plug #3 (20 sx, 23.60 cu ft, 15.6 ppg, 1.18 yield, class 'B' cmt) from 1372' to 1196' to isolate San Jose perfs. TOH to 323'. Mix & pump Cmt Plug #4 (47 sx, 55.46 cu ft, 15.6 ppg, 1.18 yield, class 'B' cmt) from 323' to surface to cover 8 5/8" shoe & surface. Circ good cmt out csg valve. ND BOP. Dig out & cut off wellhead. Cmt at cutoff point' in 5 1/2" csg & 10' in 8 5/8" csg. RD rig. SDFN. Reuben Perea, JAT-BLM on location. ✓
- 7/18/14: Mix & pump 20 sx 15.6# class 'B' cmt to top off & set DHM. RD equipt. Release rig. MOL. ✓