
UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS SEP 10 2014



FORM APPROVED OMB No. 1004-0135 Expires Inovember 30, 2000

Lease Serial No.

SF 047017B

abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name RCUD SEP 29 '14	
SUBMIT IN TRIPLICATE – Other instructions on reverse side 1. Type of Well				77: If Unit or CA/Agreement, Name and/or No. OIL CONS. DIV. DIST. 3		
Oil Well X Gas Well Other				8. Well Name and No.		
 Name of Operator Cnaparral Oil and Gas Comp 	o any c/o Walsh Engin	eering .		Sally #1 9. API Well N	· · · · · · · · · · · · · · · · · · ·	
3a. Address		3b. Phone No. (include area code) 505-327-4892		30-045-20611 10. Field and Pool, or Exploratory Area Fulcher Kutz PC		
7415 E. Main, Farmington, NM, 87402 4. Location of Well (Footage, Sec., T., R., M., or Survey Description,						
790' FSL and 1850' FEL, Sec. 24, T28N, R11W				11. County or Parish, State San Juan County, NM		
12. CHECK AP	PROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, REP	ORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
■ Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Reclamation Recomplet	mplete Other Other		
13. Describe Proposed or Completed Oper If the proposal is to deepen direction: Attach the Bond under which the wo Following completion of the involved Testing has been completed. Final A	ations (clearly state all pertinent ally or recomplete horizontally, g rk will be performed or provide operations. If the operation resident abandonment Notices shall be fi	details, including estimated give subsurface locations and the Bond No. on file with I ults in a multiple completion led only after all requirement	starting date of an measured and tru BLM/BIA. Requir or recompletion in its, including recla	ny proposed work a e vertical depths o red subsequent rep n a new interval, a mation, have been	and approximate duration thereof. f all pertinent markers and zones. orts shall be filed within 30 days Form 3160-4 shall be filed once completed, and the operator has	

Chaparral Oil and Gas proposes to plug and abandon this well according to the attached procedure.

SEE ATTACHED FOR **CONDITIONS OF APPROVAL**

Notify NMOCD 24 hFs prior to beginning operations 3.5 **3.4**5 Å

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER **AUTHORIZATION REQUIRED FOR OPERATIONS** ON FEDERAL AND INDIAN LANDS

14. I hereby certify that the foregoing is true and correct	
Name (Printed/Typed)	Title
Paul C. Thompson, P.E.	Agent
Signature Paul C. Thoys-	Date September 8, 2014
THIS SPAC	CE FOR FEDERAL OR STATE USE
Approved by Salvers	Petroleum Eng. Pate 9/25/2014
Conditions of approval, if any, are attached. Approval of this notice does not certify that the applicant holds legal or equitable title to those rights in the swhich would entitle the applicant to conduct operations thereon.	not warrant or Office

Title 18 U.S.C. Section 1001, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Walsh Engineering and Production

P & A Procedure for Chaparral Oil and Gas Co. Sally #1

Location: SE/4 Sec 24 T28N R11W

San Juan County, NM API: 30-045-20611

Date: September 8, 2014

Field: Fulcher Kutz Pictured Cliffs

Surface: BLM

Minerals: BLM SF - 047017-B

Elev: GL 5853' 4-1/2" @ 1922'

PBTD: 1922' KB

PC Perfs: 1863' - 1887'

Procedure:

1. Move on location and rig up a well service unit. Hold a safety meeting and explain the procedure to the crew.

- 2. Nipple down the well head and nipple up the BOP. Lay down 1865' of $1-1/2^{\prime\prime}$ tubing.
- 3. Pick up a 4-1/2" casing scrapper on a 2-3/8" work string and TIH to at least 1863' or PBTD if fill is encountered. TOH and lay down the scrapper.
- 4. Pick up a 4-1/2" CICR on 2-3/8" tubing and set it at approximately 1800'. Pressure test the tubing to 1000 psi. Sting out of the retainer and load the casing with water. Pressure test the casing to 500 psi. Sting back into the retainer and pump 10 sx (11.8 cu.ft.) of neat cement below the CICR. Sting out and leave another 20 sx (23.6 cu.ft) above the CICR to 1600' to cover the Fruitland top plus 50'. POH above the cement (approx. 1400') and reverse circulate the tubing clean. TOH and lay down the stinger.
- 5. TIH open ended to 920'. Spot a balanced plug with 12 sx (14.2 cu.ft.) of neat cement to cover the Ojo Alamo at 870' +/- 50'. TOH and lay down all but 6 joints of tubing.

Û

- TIH with tubing to at least 163' and spot a surface plug with $15~\rm sx~(17.7~\rm cu.ft.)$ of neat cement or until the hole is standing full of good cement. TOH and top off as necessary. 6.
- Cut the wellhead off 4' below the ground level. Install a dryhole marker 7. with a weep hole. Reclaim location as per surface owner specifications.

Paul C. Thompson, P.E.

CHAPARRAL DIL & GAS CO. SALLY #1 30-045. ZOGII SEC Z4, TZ9N, RUW

GL - 5853"

CURTENT STATUS PAA STATUS HOLE SIZE: 12 1/2" PHU #3 D'-163 156x (17.7 cm.ft.) 7 % c 113 CMT W/805K CMT CIRC 820 PLUG #2 125x (14,2 cu.ft) 010 ALAMO - 870' 920 HOLE SIZE: 6 3/4" TOC @ 1600 FRUITLAND SAND 1657 20 sx (23.4 cu. ft.) FRUITZAND GAL 1695 CICR @ 1800 10 sx (11.8 cuft) PICTURED CLIFFS 1863-69 PC TERFS 1877-87 RCWD SEP 29'1/1 OIL CONS. DIV. DIST. 3 4/2 9.5 0 19ZZ CAT W/ 2755X CMT CIRC.

Pt 9/2/11

7777 SON SHETTS, FILTHER SCOLARF 781 105 SHETTS, FFLEAGE SCOLARF 782 200 SHETTS, FFLEAGE SOUARF 782 200 SHETTS, FFLEAGE SOUARF 783 200 SHETTS, FFLEAGE SOUARF 784 200 SHETTS, FFLEAGE SOUARF 785 200 SHETTS, FFLEAGE SOU

42-382 atlonal ®Brand 42-382 42-389 42-392

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: Sally #1

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Bring the top of plug #1 to 1525 ft. to cover the Fruitland top. Adjust cement volume accordingly.
 - b) Bring the top of plug #2 to 640 ft. to cover the entire Ojo Alamo fresh water aquifer. Adjust cement volume accordingly

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.