UNITEDSTATES DEPARTMENT OF THE INTERIOR

Form 3160-5 (April2004)	UNITEDSTATES DEPARTMENT OF THE INTER	RIOR			FORMAPPRO OM B No. 100	4-0137	
	BUREAU OF LAND MANAGEME			5. Lease Sei	Expires: Marc	31,2007	
SUNDRY	NOTICES AND REPORTS	ON W	ELLS	NMSF07	/		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well				8. Well Nam	8. Well Name and No.		
2. NameofOperator				San Juan 32 FED 22 #2A			
ConocoPhillips Co. 3a. Address 3b. PhoneNo. (include area code)				9. API Well No. 30-045-31613			
P.O. Box 2197, WL3-6085 Houston Tx 77252 (832)486-2463				10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				Basin Fruitland Coal			
Sec 22 T32N R9W SENW 1600FNL 1725FWL				11. County or Parish, State San Juan NM			
12. CHECK AI	PPROPRIATE BOX(ES)TO INDICA	ATE NATU	JRE OF NOTICE, R	 	OTHER DA	TA	
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent Subsequent Report Final Abandonment Notice	Casing Repair New (ureTreat Construction and Abandon		[[] pandon	Water Shu Well Integr X OtherWO	rity	
If the proposal is to deepen dire Attach the Bond under which t following completion of the inv	ted Operation (clearly state all pertinent detail ectionally or recomplete horizontally, give sub- the work will be performed or provide the Bou volved operations. If the operation results in a hal Abandonment Notices shall be filed only a by for final inspection.)	bsurface loca nd No. on fil multiple cor	tions and measured and t le with BLM/BIA. Requ npletion or recompletion	rue vertical depti ired subsequent i in a new interval	hs of all pertinen reports shall be i l, a Form 3160-4	nt markers and zones. filed within 30 days 4 shall be filed once	
Replaced BHA and tubin attached.	ng. Tubing now lands @ 3 <u>692'</u>	KB. Daily	summary report	is	_1		
			1500		0	MA3	
		450	79311 237		RE(
		TO C		57 /2	REC (ು	
		19	18 2006	Marca.	MINGTON	当	
		52	MAR LIED DIN.	1016.8	35		
		33	W CO. 70 8	7		10	
			W COMPT 8		46		
		E.	MAR 2008 MAR	ř			
14. I hereby certify that the foreg	joing is true and correct		There is a second of the secon				
Name (Printed/Typed) Christina Gustartis		Title	Regulatory Spec	cialist			
Signature Chris E	Pustanta	Date	03/02/2006				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.

Office

Title

ACCEPTED FOR RECORD

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department of the states any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

FARMINGTON FIGUR OFFICE

ConocoPhillips

Regulatory Summary

SAN JUAN 32 FED 22 #002A

Repair Downhole Failure, 2/20/2006 00:00

API/Bottom UWI State/Province Surface Legal Location N/S Dist (ft) E/W Dist (ft) County E/W Ref 300453161300 **NEW MEXICO** NMPM-32N-09W-22-F 1,600.00 San Juan 1,725.00 Ground Elevation (ft) Latitude (DMS) Longitude (DMS) Spud Date Rig Release Date 5/29/2003

6,871.00

36° 58' 22" N

107° 46' 10" W

6/3/2003

2/20/2006 05:30 - 2/20/2006 17:00

Last 24hr Summary

Road rig from S.J.32 FED 22 #1A to S.J. 32 FED 22 #2A.

Spot rig to well head. Spot equipment on location. RU equipment.

Raise derrick. Run guylines & tighten.

Load tubing w/ 2% KCL water. Pressure test tubing to 1000 psi. Good test. Bleed down pressure

RD polish rod stuffing box. LD posilsh rod & stuffing box.

RU to TOOH w/ rods & pump.

TOOH w/ rod pump & rods.

NDWH. NUBOP. Change BOP tubing rams. Hookup 3"flow line. Hookup 2" kill line.

RU floor & power tongs. Change slip dies in tubing slips. RU block to pull tubing. BDW.

Function test & pressure test BOP as per COPC requirments. GOOD TEST.

Unseat tubing hanger. PU to floor. Remove tubing hanger. RIH to tag for fill. Tag fill @ 3763' (15' of fill).

TOOH w/ tubing. Strap out of hole.

Tubing unloading fluid & blowing gas. Install TIW valve & close. Call for SL crew to set pressure plug in tubing. Not available until morning.

Drain all pumps & lines for cold weather. Secure well, rig & location. SDFN.

2/21/2006 05:30 - 2/21/2006 17:00

Last 24hr Summary

Casing pressure @ 610 psi. Tubing pressure @ 520 psi. BDW.

RUSL. Set pressure plug in "F" nipple. RDSL.

TOOH w/ tubing. Strap out of hole.

OOH. LD old BHA. PU new BHA.

TiH w/ New BHA & production tubing consisting of:

2-1/16" Notched collar. EOT @ 3692"

2-1/16" :"F" nipple (1.95" I.D.).

2-1/16" X 2-3/8" X-OVER.

1 JT - NEW 2-3/8", 4.7#, J-55, EUE8rd Tubing w/ 1/4" hole drilled just below upset.

1 ea - "F" nipple w/ 1.78 I.D. SET @ 3656'

117 JTS - 2-3/8", 4.7#, J-55, EUE8rd Tubing.

1 EA - Tubing hanger.

LAND TUBING @ 3692'.

Install tubing hanger. Land tubing.

RD power tongs, floor & 3" flow line. NDBOP. NUWH. RU to run rods.

Load tubing w/ 6 bbls of 2% KCL water. RUSL. Retreive pressure plug from tubing.

PU rod pump. Bucket test pump. GOOD TEST. RIH w/ pump & rods. RAN;

1 ea - 2" X 1-1/4" X 12' RHAC Z Pump #CP087.

1 EA- -2' pony rod.

3 ea - K-bar (sinker bars)

143 ea - 3/4", Class D rods.

1 ea - 22' X 1-1/4" polish rod w/ stuffing box.

Space out & seat rod pump.

Load tubing w/ 2% KCL water. Test tubing to 500 psi. GOOD TEST. Bleed pressure to 250 psi. Long stroke pump w/ blocks. Pump pressure to 500 psi in 6 strokes. GOOD TEST. Bleed tubing down to 250 psi.

Hang HH, RU PJ.

RD to move. Return well to production. NO FURTHER ACTIVITY ON THIS JOB. Rig released @ 17;30 on 2/21/2006. FINAL REPORT. Secure well, rig & location, SDFN.