Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No. 1004-0137

BUREAU OF LAND MANAGEMENT					Expires: July 31, 2010		
					5. Lease Serial No.		
CIII	NDRY NOTICES AND RE	DODTS (N WEI Farmin	aton F	S (CYCLOR Alleman on Table)	SF-078740	
Do not us	se this form for proposals	e to drill	Bureau of	Land	Management	Name	
	well. Use Form 3160-3			411			
					7. If Unit of CA/Agreement, N	Jame and/or No	
SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well					San Juan 30-5 Unit		
Oil Well Sas Well Other					8. Well Name and No.		
					San Juan 30-5 Unit 48M		
2. Name of Operator					9. API Well No.		
ConocoPhillips Company			30-039-26367				
			ne No. (include area code)		10. Field and Pool or Exploratory Area		
PO Box 4289, Farmington, NM 87499			(505) 326-9700		Basin Dakota / Blanco MV		
4. Location of Well (Footage, Sec., T.,		FEL Coo	20 T20N D0	EVAL	11. Country or Parish, State	New Meyles	
Surface Unit I (N	ESE), 1780' FSL & 1185'	ret, sec	. 20, 130N, RU	OVV	Rio Arriba	, New Mexico	
12 CHECK	THE ADDRODDIATE DOV/E	C) TO IND	ICATE NATURE	OF N	OTICE DEPORT OF OTH	IED DATA	
	THE APPROPRIATE BOX(E	S) 10 IND				ER DATA	
TYPE OF SUBMISSION			TYPE OF ACTION				
Notice of Intent	Acidize	Deep	en		Production (Start/Resume)	Water Shut-Off	
	Alter Casing	Fract	ure Treat		Reclamation	Well Integrity	
X Subsequent Report	Casing Repair	New	Construction		Recomplete	X Other Remedial	
BP	Change Plans	Plug	and Abandon		Temporarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug	Back		Water Disposal		
determined that the site is ready fo	ny requests permission						
			OIL CONS. DIV DIST. 3 MAY 2 3 2017				
14. I hereby certify that the foregoing is	true and correct Name (Printed/To	ined)					
14. Thereby certify that the foregoing is	true and correct. Name (17maew 1)	уреа)					
Christine Brock			Title Regula	atory S	Specialist		
Signature UMista	rie Broc	K	Date 5/c	221	117		
1	THIS SPACE F	OR FEDE	RAL OR STAT	TE OF	FICE USE		
Approved by							

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Title

Office

entitle the applicant to conduct operations thereon.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would

ConocoPhillips SAN JUAN 30-5 UNIT 48M Expense - Repair Bradenhead

Lat 36° 47' 44.192" N

Long 107° 22' 30.713" W

PROCEDURE

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COP safety and environmental regulations. Test rig anchors prior to moving in rig. Before RU, run slickline to check for and remove any downhole equipment. If an obstruction is found and cannot be recovered, set a locking 3-slip-stop above the obstruction in the tubing.
- 2. MIRU workover rig. Check casing, tubing, and bradenhead pressures and record them in WellView. If there is pressure on the BH, contact Wells Engineer.
- 3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCl water as necessary. Ensure well is dead or on vacuum.
- 4. ND wellhead and NU BOPE. Pressure and function test BOP to 250 psi low and 1,000 psi over SICP high to a maximum of 2,000 psi held and charted for 10 minutes per COP Well Control Manual. PU and remove tubing hanger. Tag for fill, adding additional joints as needed. Record pressure test and fill depth in WellView.
- 5. POOH 3 joints of TBG, PU a 4-1/2" tension packer and set 5-15' below the WH. Load the hole and pressure test the WH. Contact the Wells Engineer with the test results before proceeding. If the wellhead fails the pressure test, remove and make repairs to the tubing head seals, with the packer in place monitor the intermediate and BH for pressure. If no pressure is observed on the intermediate or BH with the packer in place, contact the wells engineer and plan to land the TBG string back and return the well to production. If intermediate or BH pressure is observed after the TBG head repair proceed with the procedure steps 6 thru 8.
- 6. PU 3-3/4" string mill and bit and CO to top perforations at 4,227' using the air package. TOOH. LD mill and bit. PU a RBP and set at 4,177'. Load the hole with fresh water and pressure test the CSG to 500 psi. Notify the wells engineer of the test results. If the CSG and the wellhead pressure tested, chart the 560psi pressure test for 30 minutes on a 2 hour chart with 1000lb spring. Contact the wells engineer with the test results and discuss plan forward. May need to cut and pull the 4-1/2" CSG to squeeze CMT to surface on the 7" CSG to shut off the BH pressure. Contact wells engineer to discuss this option after testing the wellhead and the CSG. After repairs are made clean the well out to PBTD with the air package, If unable to CO to PBTD, contact Wells Engineer to inform how much fill was left and confirm/adjust landing depth.

Publica and BUA Description

7. TIH with tubing using Tubing Drift Procedure (detail below).

		Tubing and BHA Description		
Tubing Wt./Grade:	4.7#, J-55	1	2-3/8" Expendable Check	
Tubing Drift ID:	1.901"	1	2-3/8" (1.78" ID) F-Nipple	
		1	2-3/8" Tubing Joint	
Land Tubing At:	7,876'	1	2-3/8" Pup Joint (2' or 4')	
KB:	13'	+/- 249	2-3/8" Tubing Joints	
		As Needed	2-3/8" Pup Joints	
		1	2-3/8" Tubing Joint	

8. Ensure barriers are holding. ND BOPE, NU Wellhead. Pressure test tubing slowly with an air package as follows: pump 3 bbl. pad, drop steel ball, pressure tubing up to 500 psi, and bypass air. Monitor pressure for 15 min., then complete the operation by pumping off the expendable check. Note in WellView the pressure in which the check pumped off. Purge air as necessary. Notify the MSO that the well is ready to be turned over to Production Operations. RDMO.

Tubing Drift Procedure

- 1. Set flow control in tubing. With air, on location, use expendable check. With no air on location, use wire line plug.
- 2. RU drift tool to a minimum 70' line. Drift tool will have an OD of at least the API drift specification of the drift diameter of the tubing to be drifted, and will be at least 15" long. The tool will not weigh more than 10# and will have an ID bore the length of the tool, so fluids may be pumped through the tool if it becomes stuck.
- 3. Drop the tool into the tubing string and retrieve it after every 2 joints of tubing ran in hole. If any resistance to the tool movement is noticed, going in or out, that joint will be replaced.

NOTE: All equipment must be kept clean and free of debris. The drift tool will be measured with calipers before each job, to ensure the OD is the correct size for the tubing being checked. The maximum allowable wear of the tool is 0.003".

