

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well  
GAS

2. Name of Operator

**BURLINGTON**  
**RESOURCES**

OIL & GAS COMPANY LP

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1500' FNL, 960' FWL, Sec. 14, T-28-N, R-5-W, NME

5. Lease Number  
NMSF-079250

6. If Indian, All. or  
Tribe Name

7. Unit Agreement Name

San Juan 28-5 Unit

8. Well Name & Number

San Juan 28-5 U #91M

9. API Well No.

30-039-23846

10. Field and Pool

Blanco MV/Basin DK

11. County and State

Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment

Type of Action

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other - Temporarily abandon lower Dakota

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

It is intended to temporarily abandon the lower Dakota formation in the subject well according to the attached procedure. The well will then be returned to production as a Mesaverde/Dakota commingle.

RECEIVED  
2003 JUL -1 PM 1:39  
070 Farmington, NM

14. I hereby certify that the foregoing is true and correct.

Signed Stephen Mason Title Regulatory Supervisor Date 6/30/03  
no

(This space for Federal or State Office use)

APPROVED BY Original Signed: Stephen Mason Title \_\_\_\_\_ Date JUL 07 2003  
CONDITION OF APPROVAL, if any:

**SAN JUAN 28-5 UNIT #91M****Mesaverde/Dakota Commingle, AIN: 5433401/02****1500' FNL & 960' FWL****Unit E, Section 14, T28N, R05W****Latitude / Longitude: N36° 39.852' / W107° 20.064'****Tubing Repair Procedure - 6/25/2003**

**Project Summary:** The San Juan 28-5 Unit #91M was drilled and completed in 1985 as a single DK producer. In 1998 the MV was completed and commingled with the DK. The tubing was round tripped and the well was cleaned out to bottom 2000. We will set a CIBP to isolate the lower Dakota interval; it is suspected as the source of unmanageable water production.

1. Hold safety meeting. Comply with all NMOC, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Cole 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCl water if necessary. ND wellhead and NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
3. The tubing is 2-3/8", 4.7#, J-55 set at 8227' (SN @ 8223'). Release donut and strap out of the hole standing back the tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer/Senior Rig Supervisor.
4. TIH with CIBP and packer for 4-1/2" 11.6# N-80 casing on 2-3/8" tubing. Set CIBP at 8280'; trip up hole 30' and set packer. Test CIBP to 500psi for 30min.
5. Trip up hole and set packer at 8200'. Pitot test upper Dakota perforations. Make a swab run to the packer if necessary to kick the Dakota off. Notify Operations Engineer/Senior Rig Supervisor of flow testing results. TOOH and stand back tubing; lay down packer.
6. TIH with an expendable check, a seating nipple, 1 jt 2-3/8", a 2' x 2-3/8" sub and 1/2 of the 2-3/8" production string. Run a broach on sandline to insure that the tubing is clear. TIH with remaining tubing and broach this tubing. Replace any bad joints. Land tubing at approximately 8255'. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow on its own, make swab run to SN. During cleanout operations the reservoir may be charged with air. As a result of excess oxygen levels that may be in the reservoir and/or wellbore, contact the Lease Operator to discuss the need for determining oxygen levels prior to returning the well to production. RD and MOL. Return well to production.

Recommended:

  
 Operations Engineer

Approved:

  
 Drilling Manager

Operations Engineer:

 Mike Wardinsky  
 Office: 599-4045  
 Cell: 320-5113

Sundry Required:

YES NO

Approved:

  
 Regulatory

Production Foreman:

Ken Johnson

Office: 326-9819

Cell: 320-2567 Pager: 324-7676

Specialist:

Garry Nelson

Cell: 320-2565 Pager: 326-8597

Lease Operator:

Bobby Heinen

Cell: 320-2615 Pager: 949-4253

MHW/clc