

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other2. Name of Operator
ConocoPhillips Company3a. Address
PO BOX 4289 Farmington NM 87499

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1840 SOUTH 1730 EAST
UL: J, Sec: 33, T: 30N, R: 5W3b. Phone No. (include area code)
(505) 326-9597

5. Lease Serial No.

SF078739

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SAN JUAN 30-5 UNIT

8. Well Name and No.

SAN JUAN 30-5 UNIT 84

9. API Well No.

30-039-23019

10. Field and Pool, or Exploratory Area

Blanco Mesaverde/Gobernador PC

11. County or Parish, State

RIO ARRIBA
NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other DHC
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Conocophillips proposes to downhole commingle existing Blanco Mesaverde and Gobernador Pictured Cliffs. Attached is our procedure and application to the NMOCD for DHC.

This will not require a pit.

DHC 23 88 AZ

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Juanita Farrell

Title Regulatory Specialist

Signature

Date 08/19/2006

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOCD



San Juan Workover Procedure

'Our work is never so urgent or important that we cannot take time to do it safely.'

WELL: San Juan 30-5 # 84 (MV/PC)

Objective: DHC and install plunger lift system

WELL DATA

API #: 3003923019

Location: Sec/Tn/Rg: Sec 33(J), T-30N, R-5W
Lat: 36deg 46' 0.48"N Long: 107deg 21' 32.4036" W

Elevation: GLM: 6638' KBM: 6651'

TD: 5982'

PBTD: 5959'

Perforations: PC – (3484' – 3690') MV – (5542' – 5940')

Existing Casing, Tubing and Packer Information

	OD (in)	Depth (ft)	ID (inches)	Weight (#/ft)	Grade	Burst (psi)	Collapse (psi)	Cmt top
Surface	9-5/8	231	9.001	32.30	H-40	2270	1400	Surface
Intermediate	7	3920	6.456	20	K-55	3740	2270	2100(TS)
Production								
Production Liner	4-1/2	5982	4.052	10.5	K-55	4790	4010	3732
Tubing	2-3/8	5843	1.995	4.7	J-55	7700	8100	
Tubing	1-1/4	3647	1.380	2.3	J-55 IJ	8120	8490	
Packer	6.456	3710top	2.98	26	85-40			



San Juan Workover Procedure

San Juan 30-5 # 84

PROCEDURE:

All plunger lift equipment will be removed from the tubing, before the scheduled rig arrival. If plunger lift equipment cannot be removed, a wireline slip stop will be set above equipment, to make sure equipment cannot come to surface, while working tubing string.

Ensure that well is shut in, energy isolated, locked and tagged out; Cathodic protection disconnected. Record SI tbg; SI csg: Braidenhead pressures.

1. Hold pre-job Safety Meeting. Check anchors for recent inspection.
2. MI RU workover rig
3. Set appropriate control barrier in Long string.
4. If necessary, kill well w/ 2% KCL water (contingent on Category designation of well; refer to COPC well control manual). ND wellhead and NU BOPE. (refer to COPC well control manual, Sec 6.13).
5. PC string - Unseat Short String tbg hanger & LD. X-over 1-1/4", 10 rd to 2-3/8" 8rd. Hook up Air package and RIH w/ tbg. to clean out to top of packer @ 3710'. When returns are clean, POOH w/ 1-1/4" string, laying down.
6. MV string – Unseat and LD tubing hanger. POOH w/ 2-3/8" long string, standing back and inspecting for holes, corrosion, crimps, and scale. Save sample of scale. Replace all bad joints. LD Mod "G" locator assembly.
7. Hook up air package to clean out MV to PBTD.
8. Run mule shoe on bottom, 1.81" Baker "F" Seating Nipple, TIH 2.375", 4.7#, tubing, clean out with air/foam to PBTD @ 5959' KB. When returns are clean, pull up hole & land tubing @ 5741' + or -. ** NOTE – Production tubing will be landed through the packer bore. (Pkr bore = 4" ID) Slow down near top of packer @ 3710' and at top of liner, @ 3732'. Take care, not to land tubing collar in Pkr. bore 3710' – 3715'. Rabbit tubing with 1.901" diameter drift bar – adhere to attached Tubing Drift Check Procedure.
9. ND BOP. NU WH.
10. RU and swab well in. ** Do not extend rig stay more than 1 day, for swabbing.
11. RD MO rig. Turn well over to production. Notify Operator. Bruce Chism 505-486 1904. Operator will coordinate plunger lift system installation.
12. Notify cathodic protection personnel after job is complete so cathodic protection equipment can be re-activated. Ensure pit closures done.