submitted in lieu of Form 3160-5 UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Sundry Notices and Reports on Wells			
_		2007 <u>UIM - 4 PM 3:</u>	<u>53</u> 5.	Lease Number
1.	Type of Well GAS	RECEIVED BLH 210 FARWURD CHE	6.	NMSF-07820 6 If Indian, All. or Tribe Name
			7.	Unit Agreement Name
•	Name of Operator Burlington Resources Oil & Gas, LP			
_	Adding a Dham No of On make		8.	Well Name & Numbe
•	Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700		9.	Sunray B #1C API Well No.
_	Location of Well, Footage, Sec., T, R, M			30-045-30068
	Location of wen, rootage, sec., 1, K, M		10.	Field and Pool
	Unit K (NFCW) 1720' FCI & 1665' FWI Sec 15 T30	N DIGW NMPM		Blanco MV / Basin Dl
Unit K (NESW), 1720' FSL & 1665' FWL, Sec. 15, T30N, R10W, NMPM				County and State San Juan, NM
	Subsequent Report Plugging No Casing Repair W	w Construction n-Routine Fracturing ater Shut off onversion to Injection		
ee	Describe Proposed or Completed Operations the attached procedure Burlington plans on using to committee the work proceeds.	ngle the subject well. The DI	HC applica	RCUD JUN7'07
				OIL CONS. DIV. DIST. 3
_	I hereby certify that the foregoing is true and correct. ned Patsy Clugston	Title Sr. Regulatory Special	ist Date	e <u>05/29/07</u> .
AP CO	is space for Federal or State Office use) PROVED BY Original Signed: Stephen Mason Title NDITION OF APPROVAL, if any: 8 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any depar inted States any false, fictitious or fraudulent statements or representations as to any matter within it			Date JUN 0'5 2007

Sunray B 1C (MV/DK dual) **Downhole Commingle**

Prepared By:

Mike Megorden

Date: 5/3/07

Lead Engr. Peer review/approved By:

Dennis Wilson

Date:

Project Lead peer reviewed By:

Date:

Objective:

Downhole commingle the MV and DK zones.

Summary:

The MV is unable to produce, and the DK is showing signs of inhibited production (liquid loading or otherwise). The job involves pulling the two 1.5" tubing strings. plucking the packer, running 2-3/8" tubing, and cleaning out to PBTD.

A PIT IS REQUIRED

API:

30-045-30068

Location:

1720' FSL & 1665' FWL, K-15-30N-10W

Lat/Long:

36.80974° N & 107.87455°

Elevation:

GLM 6204'

KBM 6219' (KB 15')

PBTD:

7648'

Perforations: 3852'-4438', 4594'-5181', 5273'-5436' (MV), 7478'-7622' (DK)

Casing:

<u>OD(in)</u>	<u>Wt., Grade</u>	Connection	<u>ID/Drift(in)</u>	<u>Depth</u>
13-3/8°°	48#, H-40	ST&C	12.715/12.559	241'
8-5/8"	32#, J-55	ST&C	7.921/7.796	3253'
5-1/2"	15.5#, K-55	ST&C	4.950/4.825	7729'

PROCEDURE:

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU workover rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. If necessary, kill well w/ 2% KCL water (contingent on Category designation of well; refer to COPC well control manual). ND wellhead and NU BOPE. (refer to COPC well control manual, Sec 6.13). This well is a Class 2, Category 1 well. Leave BPV set in longstring while working with shortstring.
- 4. Unseat 1-1/2" shortstring tubing hanger. Add joints and drop down to tag for any fill above Model D packer at 5800'. If fill is encountered, RU air package and clean out fill to top of packer. POOH and lay down 1-1/2" IJ production tubing.
- 5. Unseat 1-1/2" longstring tubing hanger and Model D packer seal assembly. POOH 1-1/2" production tubing. LD tubing. Measure the OD on the seal assembly to verify the ID of the seal bore.
- 6. PU mill, plucker for a 5-1/2" Model D packer (sized for the existing seal bore), and 2-3/8" 4.7# J-55 EUE tubing. RIH, mill out packer, and pluck it.

- 7. RIH w/ mule shoe collar, expendable check, 2-3/8" (1.78" ID) F-nipple, 2-3/8" yellow-band 4.7# J-55 EUE tubing and clean out to PBTD at 7648', descending in increments no greater than 500' once a fluid level is encountered, unloading the well with air and mist. Drift tubing slowly with a 1.901"x24" diameter drift bar, replicating a plunger run, according to attached tubing drift procedure. This well is to be operated with plunger lift and it is imperative to have good tubing drift.
- 8. PU and land tubing approximately at +/-7510°. A new tubing hanger will be required to land 2-3/8" tubing. ND BOP and NU wellhead. Drop ball and blow out expendable check. RDMO rig.
- 9. Turn well over to production. Notify Chad Dunn, MSO. Cell # 505-860-1154.
- 10. Notify cathodic protection personnel after job is complete so cathodic protection equipment can be re-activated. Ensure pit closures done.

Production Engineers:

Primary Contact: Mike Megorden

Office Phone: 505-324-5142 Cell Phone: 505-947-4315

Alternate Contact: Allan Rambur

Office Phone: 505-324-5163 Cell Phone: 505-320-1402

