F	orm	9-331
(	May	1963)

## **UNITED STATES**

SUBMIT IN TRIPLICATE.

-	,	Form	appr	oved.			
		Búdge	t Ru	reau	Nο.	42-K	142
. L	EASE	DESIG	NATIO	XX AN	0 81	RIAT	ž.

DEPARTMENT OF THE INTERIOR (Other Instructions o	Budget Bureau No. 42-R1424  5. LEASE DESIGNATION AND SERIAL NO.
GEOLOGICAL SURVEY	NM-081208
SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not use this form for proposals to drill or to deepen or plus back to a different reservoir.  Use "APPLICATION FOR PERMIT" for such proposals.)	
	7.000
OIL WELL OTHER OTHER	7. UNIT AGREEMENT NAME
WELL WELL OTHER	8. FABM OR LEASE NAME
Tonnoco Oil Company	Hospah & AAda
3 ADDRESS OF OPERATOR	9. WELL NO.
1860 Lincoln St., Suite 1200, Denver, Colorado 80295	្រុំ គ្នាប់ខ្ញុំ គ្នាប់ខ្ញុំ ខ្ញុំ គ្នាប់ខ្ញុំ ខ្ញុំ
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface	Dakota/Gallup
990' FNL and 2300' FWL ,X	11. BEC., T., B., M., OR BLK. AND
1, July C	BURVEY OR AREA
	Beg 12; Tian, R9W
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
7034' GR McKinle	cy San Juan New Mexi
16. Check Appropriate Box To Indicate Nature of Notice, Report,	or Other Data
NOTICE OF INTENTION TO:	BSEQUENT REPORT OF
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	BEPAIRING WELL
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE X ABANDON* SHOOTING OR ACIDIZING	ABANDONMENT
REPAIR WELL CHANGE PLANS (Other)	esults of multiple completion on Well
(Other)   Completion or Re	completion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent of proposed work. If well is directionally drilled, give subsurface locations and measured and true venet to this work.)*	nates, including estimated date of starting any vertical depths for all markers and zones perti-
We propose to reperforate the Gallup zone in this well as t	follows the state of the state
We propose to reperiorate the darrap zone in onto herr as i	
'1. MIRUPU. Pull rods & 2 X $1\frac{1}{2}$ X 10' insert pump from shor	rt strings Tag packer
& tally 2-3/8" out. Lay down seating nipple and TIH to	o 1650] Tagay 1657 g g
2. Spot 200 gallons 15% HCL. Pull to +1570' & land & pack	
3. Rig up McClullough and run 1-9/16" Omega scallop gun or	n electromagnetic orienting
tool. Check collars off Schlumberger BCL-GR-CCL log da	ated 3-2-6/. TUSE 14
lubricator w/mechanical packing. 4. Perforate the interval 1632' - 1662' with 4 S.P.F. Rig	a down McCullough
5. Bullhead 500 gallons 15% HCL down tubing. Do not exceed	ed 1900 psia.
6. Swab back load	그는 왕독교병학 - 결국원원육합
7. POH. PU 2½ X 2¼ X 10' tubing pump & RIH on 2-3/8" tub	ing ta £1630's Runfrods.
8. RDMOPU. Put well on production & test.	ON DEZA
9. Clean location of all debris.	
the second secon	
A faces and	Tipe of the second
SEP 1 6 1977	SEP COM
SET 1	TONE TONE
-modical such	OF WELL
U. S. Carlotte and the second	
	THE REPORT OF THE PARTY OF THE
18. I hereby certify that the foregoing is true and correct	그 얼룩하셨다. 사람 한국사를

Div. Production Manager The state of the s (This space for Federal or State office use) APPROVED BY \_\_\_\_\_\_\_CONDITIONS OF APPROVAL, IF ANY: TITLE .

