submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SEP 2 5 ZUU8 Bureau of Land Management Farmington Field Office

Sundry Notices and Reports on Wells	Fairin	
	5.	Lease Number NMSF-077764
. Type of Well GAS	6.	If Indian, All. or Tribe Name
. Name of Operator	7.	Unit Agreement Nan
BURLINGTON RESOURCES OIL & GAS COMPANY LP		
Address & Phone No. of Operator	 8.	Well Name & Number Schumacher 1A
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.
Location of Well, Footage, Sec., T, R, M		30-045-26639
Unit C (NENW), 870' FNL & 1430' FWL, Section 17, T30N, R10W, NMPM	10.	Field and Pool Blanco Mesaverde
÷	11.	County and State San Juan Co., NM
Type of Submission Type of Action Notice of Intent Abandonment Change of Plans X Recompletion New Construction X Subsequent Report Plugging Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection	Other – Wet Cl	iffhouse Casing Squeeze
3. Describe Proposed or Completed Operations	RCVD SEP 29'08	
		ot cors. Div.
ee attached for squeeze detail		DIST. 3
4. I hereby certify that the foregoing is true and correct.		
igned Mucly V. Mentice Tracey N. Monroe Title Staff Regula	atory Technic	<u>Date 9/24/08</u>
This space for Federal or State Office use) PPROVED BY		Date
ONDITION OF APPROVAL, if any: le 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of United States any talse, fictitious or fraudulent statements or representations as to any matter within its jurisdiction		,
	AZZEP	TED FOR FEOORD
• •		≈ 2 6 2008

NMOCD



PARIMINGTON FIELD OFFICE

9/2/08 MIRU AWS 746. (Pretreated for H2S On 9/1/08). Tested for H2S @ WH. H2S @ 14 ppm. Retreated w/20 gals of H2S Scavenger. RU H2S monitoring equip. SICP 535#. Blow down csg. O ppm H2S @ flowback tank.

9/3/08 PT tbg prior to unseating pump – no test. Set back horses head. TOOH w/rods and pump. ND tree. NU BOP. RU Floor. PU 2 3/8" handling tools. PU and LD hanger. GIH tag fill @ 5679' – 15' fill. TOOH w/2 3/8" tbg. LD 176 jts tbg.

9/4/08 MIRU Bluejet W/L. Ran 4 ½" GR to 5250'. Set CBP @ 5200'. RD W/L. Tally, PU, TIH w/4 ½" CST packer to 5190'. Set Packer. Load tbg w/2% KCl H2O test CBP to 1500# 15/min – good test. PU to 4480', set packer. Est injec rate, pumped 4 bpm @ 550#, unseat packer & TOOH.

9/5/08 TIH w/4 ½" CST Packer to 4480". Load hole w/2% KCL H2O. PT csg to 500# 30/min- good test. TOOH. LD packer. PU TIH w/cement retainer to top of liner.

9/8/08 Blow down well. Monitor for H2S (2 ppm). GIH set retainer @ 4145'. Load backside w/2% KCL H2O. RU Halliburton Cement to squeeze CH. Loaded tbg. Est rate w/fresh water pad. Formation on vacuum. Pumped 196 sx(280 cf-50bbbls) 50/50 POZ Cement. Cement in place @ 12:30 hrs. Sting out of retainer. Pump down tbg to clear cement. RD Halliburton. TOOH. LD tools. ND BOP. X-O ring gasket. NU BOP.

9/9/08 ND BOP. Clean cement out of ring grove. X-O ring gasket. NU test BOP to 1000# - held OK. PU TIH w/3 7/8" bit to cement Stringer @ 3122'. TIH to 3122' RU swivel. D/O cement stringers from 3122' - 3643'.

9/10/08 D/O cement from 3643' to retainer @ 4145'.

9/11/08 D/O retainer, Drilling cement to 4168'. Circ clean. Pull & LD tbg to top of liner. TIH to TOC @ 4168'. Drilled 2' cement. Plugged bit. TIH to TOL.

9/12/08 Monitor well for H2S (0 ppm). TIH to 4168'. PU swivel, break circ. D/O cement from 4168' - 4365'. D/O cement from 4365' To 4496'.

9/13/08 Monitor well for H2S (0ppm). D/O cement from 4496' - 4511'. Plugged bit. TIH to TOC. Drill cement to 4539'.

9/15/08 Monitor well for H2S (0ppm). Circ hole w/clean water. MIRU Riley Industrial to C/O rig pit. TOOH w/X-O bits. TIH to TOC @ 4539'.

9/16/08 Monitor well for H2S (0 ppm). TIH w/3 7/8" cement bit. BS on 2 3/8" tbg to TOC @ 4539'. Drill cement from 4539' – 4621'. Drilled cement to 4899'.

9/17/08 Monitor well for H2S (0ppm). D/O cement from 4899' - 5162'. Btm perf @ 5155'. Circ csg. Tested squeeze to 500# 30 min On 2 hr Chart. Pull 30 STDs to TOL. Unload csg w/air mist.

9/18/08 Monitor well for H2S (0ppm). TIH to 5162'. Unload csg w/air mist. D/O cement stringers to CBP @ 5200'. D/O CBP. C/O to 5544'. H2S increased to 16 ppm. RU NALCO. Treat well w/60 gals H2S Scavenger. Wait for H2S to dissipate. GIH. Tagged fill @ 5565'. Wash out sand to PBTD @ 5694'. TOOH w/tbg. LD drill collars and bit.

9/19/08 Monitor well for H2S (2ppm). Drift, TIH w/2 3/8" production string. RU Sandline. Set SV in F-Nipple. Load tbg w/2% KCL H2O. PT tbg to 1000# 10/min – good test. RIH w/170 jts 2 3/8" 4.7# J-55 EUE 8RD tbg set @ 5632' F-Nipple @ 5599'. RD floor. ND BOP, NU tree. TIH w/pump & rods, space out rods. Load tbg w/2% KCL H2O. PT tbg w/rig pump to 500# 10/min – good test. Long stroked pump, pressured up to 500# - good test.

9/22/08 Check pump, RU horse head. Hang off rods. RD rig and equipment.

