UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



OCT 3 0 2008

	Sundry Notices and Reports on Wells	Familyton Field Office		
			5.	Lease Number
1.	Type of Well GAS		6.	SF-080133 If Indian, All. or Tribe Name
2.	Name of Operator		7.	Unit Agreement Nam San Juan 32-9 Unit
	BURLINGTON RESCURCES OIL & GAS COMPANY LE	2		
3.	Address & Phone No. of Operator		- 8.	Well Name & Number San Juan 32-9 Unit 35
	PO Box 4289, Farmington, NM 87499 (505) 326-9700	•	9.	API Well No.
_ 1	Location of Well, Footage, Sec., T, R, M		-	30-045-10929
*. /	Unit G (SWNE), 1560' FNL & 1600' FEL, Section 10	, T31N, R09W, NMPM	10.	Field and Pool Blanco Mesaverde
			11.	County and State San Juan Co., NM
	Casing Repair	Ion-Routine Fracturing Water Shut off Conversion to Injection		
•				
13.	Describe Proposed or Completed Operations			
	Describe Proposed or Completed Operations lington Resources wishes to plug & abandon this well accompleted.	cording to the attached procedures	and well	bore schematics.
		cording to the attached procedures	and well	RCUD NOV 3 'OI OIL CONS. DIV
3ur			and well	RCAD NOA 3 ,01
Bur	I hereby certify that the foregoing is true and correct			RCVD NOV 3 '01 OIL CONS. DIV DIST. 3

NMOCD

P6 1/4/08

ConocoPhillips San Juan 32-9 Unit #35 (MV) Plug and Abandon Wellbore

Lat 36° 54' 54.60" N Long 107° 45' 49.32" W

Prepared By: Karen Work PE Peer review/approved By:

Engineer

Date: 10/27/2008

Date: / /

Scope of work: P&A Wellbore

Est. Cost:

Est. Rig Days: 4

WELL DATA:

API: 30-045-10929

Location: 1560' FNL & 1600' FEL, (G), 010– T31N – R009W

PBTD: 6127' **TD**: 6140'

Perforations: 5,630-5,715' (CH); 5,745-5,760' (UM); 5,775-5,815' (LM); 5,886-6,048' (PL)

Casing:	<u>OD</u>	Wt., Grade	Connection	ID/Drift (in)	<u>Depth</u>	
	9-5 /8"	25.4#, Armco	ST&C	? / ?	173.9'	
	7"	20.0#, J-55	-	6.456/6.331	4197.1'	
	7"	23.0#, J-55	-	6.366/6.241	5195.0	
Liner:	5-1/2"	15.5#, J-55	-	4.950/4.825	4997' – 5837'	
Liner(2):	3-1/2"	7.7#, J-55	-	3.068/2.943	5825' - 6140'	
Tubing:	2-3/8"	4.70#, J-55	EUE	1.995/1.901	5340.9'	
F Nipple:	2-3/8"	4.70#, J-55	-	1.780	5307.0'	
Notched Collar:2-3/8"						

Well History: The San Juan 32-9 #35 was spud in 1955 in the Cliffhouse and Menefee zones of the Mesaverde (MV), A payadd was performed in May of 1996 which drilled the hole deeper, ran 3-1/2" casing and perf'd and frac'd the Point Lookout of the MV. The Cliffhouse/Menefee zone was refrac'd at this same time. A tubing repair was performed in May of 2007 which replaced a 2-3/8" x 1-1/4" tapered string with a 2-1/16" string, 71' of fill was also cleaned out which uncovered 19' of perfs. The well could not be swabbed onto production due to the internal upsets of the 2-1/16" flush joint tubing. An economizer pump utilizing co-rod was installed in April of 2008. The system pumped 80 BWPD for three weeks. Fluid level shots indicated a casing event at approximately 1450'. A rig moved on the well in August of 2008 which isolated leaks in both the 5-1/2" and 7" casings. A casing inspection log was run in the 7" casing. After several attempts to squeeze the leaks, the 5-1/2" was successful (utilizing PSI 300 the last time) but the 7" was not repaired. A 5-1/2" tie-back liner was run in the well to fix the problem in the 7" casing. It was set utilizing a Baker Model-D liner hanger/packer. Halliburton cemented the liner tie-back with 80 bbls of cement with no returns to surface. The float collar and fiber glass baffle were drilled out and cement tagged @ 5364'. It was determined the liner hanger/packer had failed and cement went into the perfs. A CBL was run and there was no cement behind the liner tie-back. The well economics do not support attempting to clean the cement from the perfs and it was decided to P&A the well. An attempt was made to release the packer to salvage the tie-back liner but failed. The tie-back liner was then chemically cut @ 4997" and most of it pulled from the wellbore.

The well has not produced since July of 2007 (produced minimally in 2006) and is currently on the demand list at 14 months of no production. Due to the casing integrity issues with the 7" liner, this well has no potential for uphole recompletes. Therefore, it is Production Engineering's recommendation to P&A the entire wellbore.

Note: This well is on the demand list and goes into Big Game restrictions 12/01.

B2 Adapters are required on all wells other than pumping wells.

Artificial lift on well (type): None

Est. Reservoir Pressure (psig): 600 psig (MV)

Well Failure Date: 07/01/2007

Current Rate (Mcfd): Zero Est. Rate Post Remedial (Mcfd): N/A

Pit Required: Yes

Special Requirements: (2) 7" cement retainers, P&A marker, 400 sacks of cement

Production Engineer: Karen Work, Office: 505.324.5158, Cell: 505.320.3753

PE Backup: Kassadie Gastgeb, Office: 505.324.5145, Cell: 505.793.6312

MSO: Matt Valdez Cell: 505.330.3358

Specialist: Jay Wendeborn Cell: 505.320.0455

Area Foreman: Jim Kennedy Cell: 505.486.1915

Check all anchors prior to moving in rig. A rig was last on this well in 10/15/2008, so the anchors do not require testing (one year requirement).

ConocoPhillips San Juan 32-9 Unit #35 (MV) Plug and Abandon Wellbore

Lat 36° 54' 54.60" N Long 107° 45' 49.32" W

PROCEDURE:

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 14.8 ppg with a 1.18 cf/sx yield.

- This project requires the Operator to obtain an approved NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
- 2. Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
- 3. Rods: Yes ____, No __X_, Unknown _____

 Tubing: Yes __X_, No ____, Unknown _____, Size __2.375"_, Length ___5340'__.

 Packer: Yes ____, No __X_, Unknown _____, Type _____.

 If well has rods or a packer, then modify the work sequence in Step #2 as appropriate.
- 4. Plug #1 (7" casing shoe, 5.5" liner top and Mesaverde top: 5233' 4913': Load casing and circulate well clean. Do not pressure test due to possible casing leaks in the 7" casing. Mix 68 sxs cement and spot a balanced plug inside casing to cover 7" casing shoe, 5.5" liner top and Mesaverde top. PUH.
- 5. Plug #2 (Pictured Cliffs and Fruitland tops, 3284' 2904'): Mix 83 sxs cement and spot a balanced plug inside the casing to cover through the Fruitland top. TOH with tubing.
- 6. Plug #3 (Kirtland and Ojo Alamo tops, 2122' 1975'): Perforate 3 HSC holes at 2122'. If casing tested, then establish injection rate into squeeze holes. TIH with cement retainer and set at 2072'. Pressure test tubing to 1000 PSI. Mix and pump 76 sxs cement, squeeze 38 sxs outside casing and leave 38 sxs inside. TOH with tubing.

 562' 462'
- 7. Plug #4 (Nacimiento top, 1/100' 1900'): Perforate 3 HSC holes at 1100'. Establish injection rate into squeeze holes. TIH and set cement retainer at 1050'. Mix and pump 55 sxs cement, squeeze 26 sxs outside casing and leave 29 sxs inside. TOH and LD tubing.
- 8. **Plug #5 (Surface plug, 212' Surface)**: Perforate 3 HSC holes at 212'. Mix and pump approximately 95 sxs cement down the 7" casing until good cement returns out bradenhead. Shut in well and WOC.
- 9. ND BOP and cut off wellhead below surface casing flange. Install P&A marker with cement to comply with regulations. RD, MOL and cut off anchors. Restore location per BLM stipulations.

CURRENT SCHEMATIC CanocoPhillips SAN JUAN 32-9 UNIT #35 NORTH BLANCO MV (PRO #0078 3004510929 SAN JUAN NEW MÉXICO Original Spud Date Surface Legal Location E/W Dist (ft) N/S Dist (ft) 8/15/1955 1560'FNL, 1600'FEL, 10-031N-009W 1,600,00 F 1,560.00 Well Config - Original Hole 10/29/2008 2:52:50 PM (MD) Surface Casing Cement, 12,174,.8/15/1955 12 Cemented w/ 125 sx regular cement. Cement 173 circulated to surface. Surface, 9 5/8in, 25,40lbs/ft, Armco, 12 ftKB, 174 174 ftKB 180 Cement Squeeze, 1,429-1,433, 9/8/2008; Tubing, 2 3/8in, 4.70lbs/ft, J-55 Spot balance plug across holes from 2,525 KIRTLAND, 2,525 1429'-1433' w/ 5 bbis Type III cement. 12 ftKB, 5,307 ftKB 2,955 FRUITLAND, 2,955 Cement Squeeze, 1,429-1,584, 9/5/2008; Spot balance plug across holes from 3,234 PICTURED CLIFFS, 3,234 1429'-1584' w/ 8 bbls cement. 3,285 LEWIS, 3,285 -Cement Squeeze, 1,429-1,725, 9/4/2008, 1,197 Squeezed holes from 1429'-1725' w/ 40 bbls cement 1.948 Liner Cement, 4,995, 10/8/2008, Attempted to 1,948 cement tie back liner w/ Class G 50/50 poz cement but no cement went behind 5-1/2" Profile Nipple, 2 3/8in, 5,307 ftKB, 1,992 5,308 ftKB 1,997 Liner/TIE-BACK, 5 1/2in; 17:00lbs/ft, J-55, -Tubing, 2 3/8in, 4.70lbs/ft, J-55. 4,997 ftKB, 4,998 ftKB, Liner was chemical cut 1.998 5,308 ftKB, 5,341 ftKB @ 4997' and 1' of the liner packer remains in Hydraulic Fracture, 9/17/1955, 5,002 the hale Frac'd w/ 20,086 gals water; Cement Squeeze, 4,997-5,002, 9/9/1955, 5,046 30,000# sand. Squeez'd TOL w/ 100 sx regular cement 5,194 Notched collar, 2 3/8in, 5,341 Intermediate Casing Cement, 2,930-5,195; ftKB, 5,341 ftKB 8/31/1955, Cemented w/ 250 sx regular 5.195 cement followed by 250 sx poz cement. TOC Hydraulic Fracture, 6/5/1996, 5,220 CLIFF HOUSE, 5,220 187 2930' by TS 8/31/1955. Refrac'd perfs from 5290'-5530 Intermediate, 7 in, 20.00 lbs/ft, J-55, 12 ftKB, 5,290 w/85,000# 20/40 AZ sand; 5,195 ftKB 10,000# 20/40 resin coated sand; 5,307 Mesaverde, 5,290-5,380, 9/16/1955 699 bbls 35# crosslink gel; 7,000 5,308 Mesaverde, 5,430-5,530, 9/15/1955 scf/min N2. Cement Squeeze, 5,182-5,534, 9/22/2008, 5,341 Hydraulic Fracture, 9/15/1955, Squeezed 75 bbis Class G cement from Frac'd w/ 26,430 gals water, 5,341 5182'-5534'. 30,000# sand. Cement Squeeze, 5,257-5,557, 9/2/2008, 5,353 MENEFEE, 5,353 Hydraulic Fracture, 9/14/1955 Squeezed holes from 5257'-5557' (perforations Frac'd w/ 28,000 gals water; 5,380 from 5290'-5530') w/ 59 bbls light cement. 24,000# sand. Cement Squeeze, 5,257-5,557, 9/3/2008, 5,430 Hydraulic Fracture, 6/5/1996, Spot 3 bbis cement across holes from 5,530 Refrac'd perfs from 5830'-5815' 5257'-5557' (perforations from 5290'-5530') Mesaverde, 5,630-5,718, 9/14/1955 . w/.82,000#.20/40 AZ; 10,000# 5,630 20/40 resin coated sand; 689 bbls Mesaverde, 5,745-5,815, 9/12/1955 5,650 POINT LOOKOUT, 5,650 Cement Squeeze, 5,630-5,815, 10/8/2008, 35# crosslink gel; 7,000 scf/min Cement covering perfs from 5630'-5815'. 5,716 Cement plug, 5,364-5,825, 10/8/2008 Hydraulic Fracture, 9/12/1955, 5,745 Casing cement, 4,997-5,837, 9/6/1955, Frac'd w/ 12,100 gals water; Cemented w/ 62 sx neat cement, TOC @ TO 5,810 MANCOS, 5,810 14.000# sand. by TS 9/8/1955. 5,815 Liner 1, 5 1/2in, 15.50lbs/ft, J-55, 4,997 ftkB, 5,837 ftKB 5,825 Point Lockout, 5,886-6,048, 6/4/1996 5,830 Cement Plug, 5,825-6,100, 10/8/2008. Hydraulic Fracture, 6/4/1996, 5,836 Cement from 5364'-6100' per a 75% eff. Frac'd w/8,000# 40/70 AZ sand: calculation and by tag. 5,837 53,000# 20/40 AZ sand; 10,000# Liner 2 cement., 5,825-6,140, 6/3/1996, 20/40 resin coated sand, 675 bbls. 5,886 Cemented w/ 13 sx Class B 50/50 poz cement. 35# crosslink gel; 7,000 scf/min TOC @ 5840' by CBL 6/3/1966, TOC now at 3,048 5824' TOL from cement being squeezed 3,100 PBTD, 6,100, Original downhole. Plugback, 6,100-6,140, 6/3/1996 3,139 Liner 2, 3 1/2 in, 7.70 lbs/ft, J-55, 5,825 ftKB, TD, 6,140 3,140 6,140 ftKB Report Printed: \$10/29/2008

San Juan 32-9 Unit #35

Current

Bianco Mesaverde

1560' FNL, 1600' FEL, Section 10, T-31-N, R-9-W, San Juan County, NM

Lat: 36°54'54.9" N / Lat: 107° 45' 49.32" W, API #30-045-10929 Today's Date: 10/23/08 Spud: 8/15/55 Completion: 9/19/55 Elevation: 6526' GL 9.625", 25.4#, H-40 Casing set @ 162' 6536' KB Cement with 125 sxs. circulate to surface 12.25" hole Nacimiento @ 1050' *est Sqz #3: 1429' - 1724' w/40 bbls of cement (2008) Sqz #4: 1429' - 1584' w/8 bbls of cement (2008) Sqz #5: 1429' - 1433' 2.375" Tubing @ 5340' w/5 bbls of cement (2008) (164 joints, 4.7#, J-55, F nipple @ 5306') Ojo Alamo @ 2025' Kirtland @ 2072' TOC @ 2930' (T.S.) Fruitland @ 2954' 8.75" Hole Pictured Cliffs @ 3234' Cut 2nd 5.5" liner at 4997' Sqz'd TOL w/100 sxs (1955) Set 2nd 5.5" liner and 5.5" TOL @ 4997' cement w/ 60 bbls cement. TOC @ 5824' (1996) Cement did not go behind Mesaverde @ 4963' liner. Cut liner and LD. 7" 20#, J-55 Casing set @ 5183' Cement with 500 sxs Tagged cmt at 4986,' drill out to 5364'.(2008) U. Mesaverde Perforations: Sqz #1: 5257' - 5557' 5290' - 5380', 5430' - 5530' w/59 bbls of cement (2008) 3.5" TOL @ 5826' Sqz #2: 5257' - 5557' L. Mesaverde Perforations: w/3 bbls of cement (2008) 5630' -5716', 5745' - 5760', 5775' - 5815', 5886' - 6022' Sqz #6: 5182' - 5534' 5886' - 6048' (added 1996) w/ 75 bbls of cement (2008) 5.5" 15.5#, J-55 casing liner set @ 4997' - 5837' Cemented with 62 sxs

> TD 6140' **PBTD**

6.25" Hole

3.5" liner set @ 5826' - 6140'

Cemented with 13 sxs

San Juan 32-9 Unit #35

Proposed P&A

Blanco Mesaverde

1560' FNL, 1600' FEL, Section 10, T-31-N, R-9-W, San Juan County, NM Lat: 36°54'54.9" N / Lat: 107° 45' 49.32" W, API #30-045-10929

Today's Date: 10/23/08

Spud: 8/15/55 Completion: 9/19/55 Elevation: 6526' GL

6536' KB

Nacimiento @ 1050' *est

Saz #3: 1429' - 1724' w/40 bbls of cement (2008) Sqz #4: 1429' - 1584' w/8 bbls of cement (2008) Sqz #5: 1429' - 1433' w/5 bbls of cement (2008)

12.25" hole

Ojo Alamo @ 2025'

Kirtland @ 2072'

Fruitland @ 2954'

Pictured Cliffs @ 3234'

Mesaverde @ 4963'

Set 2nd 5.5" liner and Cement did not go behind liner. Cut liner and LD. Tagged cmt at 4986,' drill out to 5364'.(2008)

Sqz #1: 5257' - 5557'

Sqz #2: 5257' - 5557'

Sqz #6: 5182' - 5534' w/75 bbls of cement (2008)

6.25" Hole

Circulate cement to surface per Sundry Notice

9.625", 25.4#, H-40 Casing set @ 162' Cement with 125 sxs, circulate to surface

Perforate @ 212'

Plua #5: 212' - 0' Class B Cement, 95 sxs

Cmt Retainer @ 1050'

Perforate @ 1100'

Plug #4: 1100' - 1000' Class B Cement, 55 sxs: 29 in and 26 outside

Cmt Retainer @ 2072'

Plug #3: 2122' - 1975' Class B Cement, 76 sxs: 38 in and 38 outside

Perforate @ 2122'

TOC @ 2930' (T.S.)

Plug #2: 3284' - 2904' Class B Cement, 83 sxs

Plug #1: 5233' - 4913'

Class B Cement, 68 sxs

Cut 2nd 5.5" liner at 4997"

Sqz'd TOL w/100 sxs (1955)

5.5" TOL @ 4997'

TOC @ 5824' (1996)


7" 20#, J-55 Casing set @ 5183' Cement with 500 sxs

U. Mesaverde Perforations: 5290' - 5380', 5430' - 5530' 3.5" TOL @ 5826'

L. Mesaverde Perforations: 5630' -5716', 5745' - 5760', 5775' - 5815', 5886' - 6022' 5886' - 6048' (added 1996)

5.5" 15.5#, J-55 casing liner set @ 4997' – 5837' Cemented with 62 sxs

3.5" liner set @ 5826' - 6140' Cemented with 13 sxs



PBTD

8.75" Hole

cement w/ 60 bbls cement.

w/59 bbls of cement (2008)

w/3 bbls of cement (2008)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: 35 San Juan 32-9 Unit

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made:
- a) Spot a cement plug from 4175' 4075' to cover the Chacra top.
- b) Place the Nacimiento plug from 562' 462' inside and outside the 7" casing

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.