, submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Conden Nations and D		-11/-11	
Sundry Notices and R	eports on well		
1. Type of Well	203 °CT -	6 PM 1:51	5. Lease Number NMSF-080668 6. If Indian, All.
GAS	070 Farm	ington, NM	Tribe Name
2. Name of Operator			7. Unit Agreement No
BURLINGTON RESCURCES OIL & GAS COMPANY LE			San Juan 27-4 Un
3. Address & Phone No. of Operator			8. Well Name & Number San Juan 27-4 U
PO Box 4289, Farmington, NM 87499 (5	05) 326-9700		9. API Well No . 30-039-07171
4. Location of Well, Footage, Sec., T, R,			10. Field and Pool
1096'FSL, 860'FWL, Sec.4, T-27-N, R-4-	W, NMPM		Blanco Mesaverde 11. County and State Rio Arriba Co, N
12. CHECK APPROPRIATE BOX TO INDICATE NAT			THER DATA
Type of Submission X Notice of Intent Aban	Type of Act donment	c ion Change of	F Plans
Reco	mpletion $\overline{}$	New Const	truction
	ging Back ng Repair	Non-Routi Water Shu	ine Fracturing ut off
	ring Casing _		on to Injection
13. Describe Proposed or Completed Oper	ations		
It is intended to repair the casing procedure and wellbore diagrams.			2151 1 Substitute of the state
14. I hereby certify that the foregoing Signed Vancy Oltmanns Title	is true and o		Date 10/6/03
(This space for Federal or State Office u			Service and the service and th
APPROVED BY /2/ Im Loveto Tite of CONDITION OF APPROVAL, if any:		Date	e NOV 1 7 2003
Title 18 U.S.C. Section 1001, makes it a crime for any person knowin	gly and willfully to ma	ike any department o	NOV 1 7 2003
the United States any false, fictitious or fraudulent statements or	representations as to a	my matter within it	ts jurisdiction.

NMOCD

SAN JUAN 27-4 UNIT #18

Mesaverde AIN: 5207701
Unit M, Section 04, T27N, R04W
1096' FSL & 860' FWL
Latitude -- N36° 35.88' Longitude -- W107° 15.684'
9/29/2003 Casing Repair Procedure

Summary/Recommendation:

The San Juan 27-4 Unit #18 Mesaverde well was drilled and completed in 1958. A casing leak was detected in 1981 at 3591'. It was squeezed and pressure tested successfully. In 1996, casing leak was detected at 3127'-3327'. It was squeezed and pressure tested to 500 psi unsuccessfully and was resqueezed from 3000'-3347'. After being tested to 500 psi, 100 psi bled off in 15 minutes. Approval was given to run in with a production packer. In July 1996, a Model 'R3' packer was run in the hole & tested. After being tested to 500 psi, 20 psi bled off in 15 minutes. We recommend setting a plug above the Mesaverde interval to test the integrity of the casing. The casing will be tested back to surface and remediated if necessary.

- 1. Comply with all BLM, and BROG regulations. Conduct daily safety meetings for all personnel on location. Notify BROG Regulatory (Nancy Oltmanns 326-9891) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document the approval in DIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well
 down and kill with 2% KCl water if necessary. NU BOP with stripping head. Test and record
 operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and
 replace/install as necessary.
- 3. The tubing is 2-3/8", 4.7#, J-55 set at 6311', and a Baker Model 'R3' packer is set at 4197'. Packer is a straight-pull release packer. Release donut; pick up additional joints of tubing and tag bottom (record depth.) PBTD should be at +/- 6365'. TOOH and stand back tubing. Visually inspect tubing for corrosion or scale and replace any bad joints -- notify Implementation Engineer/Senior Rig Supervisor.
- 4. TIH with CIBP and packer. Set CIBP at 5779' (50' above Mesaverde perforations 5829-6362'). Pressure test CIBP to 500psi. Pressure test casing back to surface isolating bad intervals. Notify Implementation Engineer/Senior Rig Supervisor of casing hole severity. At this time we will determine the best method of remediation. WOC overnight after squeeze work. (TOC IS ESTIMATED AT 4150'from CBL run 04/1996. POSSIBLE WATER SOURCE IS THE OJO ALAMO (previous squeezes 3000'-3591').
- 5. TIH with 4-3/4" bit and bit sub on 2-3/8" tubing. Drill out cement and pressure test to 500 psi for 30min. Record leak-off if any. If pressure test holds TIH to CIBP at 5779' mill out CIBP. Clean out to PBTD (6365') with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary. TOOH with tubing and lay down bit. NOTE: When using air/mist, minimum mist rate is 12 bph; try to maintain an air rate at 1,400 cfm.
- 6. Make up production tubing with an expendable check, seating nipple, 1 jt 2-3/8", a 2' x 2-3/8" sub and ½ of the 2-3/8" production string. Run a broach on sand line to ensure that the tubing is clear. TIH with remaining tubing, broach remaining tubing. Replace any bad joints. Land tubing at

approximately 6310' and pump off expendable check. Connect to casing and circulate air to assure that the expendable check has pumped off. ND BOP and NU WH. Obtain pitot gauge up the tubing. If well will not flow on its own, make swab run to SN. During cleanout operations the reservoir may be charged with air. As a result of excess oxygen levels that may be in the reservoir and/or wellbore, contact the Lease Operator to discuss the need for determining oxygen levels prior to returning the well to production. RD and MOL. Return well to production.

Recommended!

Darla Acosta

Approved:

Sundry Required:

YES NO

Approved:

Nancy Oltmanns

Implementation:

Jay Paul McWilliams

324-6146 (Office)

Sundry needed

Lease Operator:

Mike McKinney

320-2533 (Cell)

326-8365 (Pager)

Specialist:

Richard Lopez

320-9539 (Cell)

326-8681 (Pager)

Foreman:

Ward Arnold

326-9846 (Office)

320-1689 (Cell)

DLA

SJ 27-4 #18 1096 S, 860' W M - 04 - 27N - 04W

Rio Arriba, NM

LAT: 36 DEG 35.88

LONG: 107 DEG 15.684

GL = 7,167' KB= 7,175'

