Submit S Copies To Appropriate District Office	State of New Mex	State of New Mexico Form C		Form C-103		
District I	Energy, Minerals and Natural Resources		June 19, 2008			
1625 N French Dr , Hobbs, NM 88240 District II			WELL API NO. 30-04	3-32/1/		
1301 W Grand Ave., Artesia, NM 88210	OIL CONSERVATION I		5. Indicate Type of Le	ase		
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Franc		STATE	FEE 🛛		
District IV	Santa Fe, NM 875	005	6. State Oil & Gas Lea	ise No.		
1220 S. St Francis Dr, Santa Fe, NM 87505						
	CES AND REPORTS ON WELLS	2 2 4 2 4 2 4	7. Lease Name or Unit	Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Canania Cas Cam			
PROPOSALS)			Caneple Gas Com 8. Well Number 1			
1. Type of Well: Oil Well Gas Well Other				70		
2. Name of Operator BP America Production Compan	S./		9. OGRID Number 7	/8		
3. Address of Operator			10. Pool name or Wild	lcat		
P.O. Box 3092 Houston, Tx 77253-3092			Blanco Mesaverde			
4. Well Location						
Unit Letter O :	960 feet from the South	line and 2245	feet from the _l	Eastline		
Section 18	Township 31N	Range 0W	NMPM San Juan	County		
	11. Elevation (Show whether DR, I					
	5910' (GR				
		227 1 -				
12. Check A	Appropriate Box to Indicate Na	ture of Notice, I	Report or Other Data	ı		
NOTICE OF IN	TENTION TO:	SUBS	SEQUENT REPOR	RT OF:		
PERFORM REMEDIAL WORK ☑		REMEDIAL WORK		ERING CASING		
TEMPORARILY ABANDON	CHANGE PL'ANS	COMMENCE DRIL	LING OPNS. P AN	ND A		
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB 🔲			
DOWNHOLE COMMINGLE						
OTHER:	_	OTHER:		П		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date						
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion						
or recompletion.	•	•	U			
DD						
	ests permission to set a CIBP @	$9/300^\circ$ in the DI	k perts to shut off w	ater production		
from lower perferations.						
DI 41 44 1 1 1	10 1 1	11 4 55	6 1 0 201 266	0.610		
Please see the attached proced	ure. If you have questions plea	ise call Anne Ha	instord @ 281-366-	8619		
			PM 24.8 DW	. with an an are-		
				JUL 14'09 CONS. DIV.		
			VII.			
Smud Data: 6/2/2005	p: p1 p.			DIST. 3		
Spud Date: 6/2/2005	Rig Release Date	e:				
I hereby certify that the information	above is true and complete to the bes	t of my knowledge	and belief			
Thereby certify that the information	above is true and complete to the bes	it of my knowledge	una cener.			
SIGNATURE Cherry Hla	wa _TITLE Regulatory Analyst	n	ATE <u>07/13/2009</u>			
Significant Showing of the	711 DD Regulatory Analyst		01/13/2009			
Type or print name Cherry Hlav	7a F-mail add	ress: Hlavacl@hn	com PHONE:28	1-366-4081		
For State Use Only				500 1001		
	≥0 0	uty Oil & Gas District #	inspector,	JUL 2 2 2009		
APPROVED BY: Zally G.	TITLE		DATE '	10F % % F003		
Conditions of Approval (if any):						

SJ Basin Well Work Procedure

Well Name: Caneple GC 1N-MV/DK

Date: July 10, 2009 Repair Type: Well Servicing

Pertinent Information: Gas BTU content for this well is 1116 on 1/4/2009; specific gravity is 0.6514. Venting and Flaring document needs to be followed if BTU content is above 950.

Location:	T31N-R10W-Sec18	API#:	30-045-32717	
County:	San Juan			
State:	New Mexico	Engr:	Anne Hansford	
Horizon:	MV/DK	Ph:	281-366-8619	~
CO2:	1.87%	Cell:	713-540-3386	
H2S:	NO			

Procedure:


1. MIRU workover rig.

- 2. Hook up casing and tubing valves. Blow down well.
- 3. RU slickline unit or wireline unit. Pressure test lubricator and equipment. Install 2-way check valve with lubricator in tubing hanger as second barrier. (will not be able to set second barrier due to junk in hole.
- 4. RU slickline unit or wireline unit. Pressure test lubricator and equipment.
- 5. RIH with gauge ring and tag junk. Then RIH with tubing broach to ensure no tight spots to 3500'.
- 6. TIH with G-pack off tubing plug assembly and set at 2000' (follow Best Practice procedure outlined by BP). Do not kill well with 2% KCL if possible.
- 7. NU BOPs and diversion spool with 3" outlets and 3" pipe to the blow tank. Pressure test BOPs. Monitor flowing casing pressure with gauge (with casing flowing to blow tank) throughout workover.
- Pull tubing hanger and shut pipe rams. Pick up and install lubricator and pull 2-way check valve, remove tubing hanger, screw on tubing collar, then install stripping rubber.
- 9. TOH with 2-3/8" production tubing currently set at **7362'** using approved "Under Balance Well Control Tripping Procedure". (Note why swab tools are stuck and remove tools.)
- 10. RIH with CIBP and set at 7300' (+/-). Ensure plug is not set opposite a casing collar. Next set of perforations start at 7317' 7373' (want to isolate these sets of perfs)

Perforations

- i. 7148' 7194'
- ii. 7200' 7258'
- iii. 7270' 7297'
- iv. SET CIBP
- v. 7317' 7373'

- 11. TIH with existing 2-3/8" tubing. Reference "Under Balanced Well Control Tripping Procedure".
- 12. Land 2-3/8" production tubing at +/- 7270'. Lock down hanger.




PROPOSED SCHEMATIC

Caneple GC 1N

Sec. 18, T31N R10W UNIT O

API: 30-045-32717



Updated: 6/17/09 AH