Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

DECEMA: 1)

FORM APPROVED OMB NO. 1004-0137 Expires July 31, 2010

REGENTER					5. Lease Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS				SF-079483		
Do not use this form for proposals to drill or to re-entenুঞ্জন 1 5 2009 abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2005 Continues. 1. Type of Well Oil Well X Gas Well Other				7. If Unit or CA/Agreement, Name and/or N 8. Well Name and No. San Juan 30-4 Unit 11		
						2. Name of Operator
ENERGEN RESOURCES CORPORATION						
3a. Address	· ·	o. Phone No. (include area code)		30-039-07875		
2010 Afton Place, Farmington, NM 8 4. Location of Well (Footage, Sec., T., R., M., or Survey)	505.325.6800	505.325.6800		10. Field and Pool, or Exploratory Area Pictured Cliffs		
1650' FSL, 1840' FEl Section 08, T30N, R04W, Unit J				Pictured Ci	ITTS	
1030 T3E, 1040 TET 3ECCTON 00, T	SON, ROAW, OHIC	U		11. County or F	Parish, State	
				NM		
12. CHECK APPROPRIATE	F BOX(FS) TO INI	NCATE NATURE OF	NOTICE DEPO	Rio Arriba		
	L BOX(LS) TO INL			K1, OK OTTIER	- TOATA	
TYPE OF SUBMISSION TYPE OF ACTION			YPE OF ACTION			
X Notice of Intent	Acidize	Deepen Deepen	Production	(Start/Resume)	Water Shut-Off	
Subsequent Report	Alter Casing	Fracture Treat	Reclamatio	on L	Well Integrity	
	Casing Repair	New Construction	Recomplete	e [Other	
Final Abandonment Notice	Change Plans	X Plug and Abandon	Temporaril	y Abandon		
	Convert to Injection	on Plug Back	Water Disp	oosal		
If the proposal is to deepen directionally or recomp Attach the Bond under which the work will be per following completion of the involved operations. I testing has been completed. Final Abandonment N determined that the final site is ready for final inspe Energen Resources plans to Plug a procedure.	formed or provide the B if the operation results in Notices shall be filed on ection.)	ond No. on file with BLM a multiple completion or ly after all requirements, in	I/BIA. Required surecompletion in a necluding reclamation	ubsequent reports new interval, a For on, have been con	shall be filed within 30 day rm 3160-4 shall be filed onc appleted, and the operator ha	
				OILC	OCT 21'09 ONS. DIV.	
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Martin Cabrera Signature		Title Dist	trict Enginee 2009		IST. 3	
THIS	SPACE FOR FED	ERAL OR STATE OF	FICE USE			
Approved by Original Signed: Stephen	Mason	Title		Day	ET 1 6 2009	
Conditions of approval, if any, are attached. Approval of this noti- the applicant holds legal or equitable title to those rights in the sub- entitle the applicant to conduct operations thereon.	ce does not warrant or certif	fy that Office				
спане не аррисані ю сонцист ореганові шегеон.		1				

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person kill by the willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Recommended Plugging Procedure San Juan 30-4 Unit #11 SE/4 Section 8, T30N, R04W DP# 3149819A AFE# SJ09-271

- 1. MIRU. ND wellhead. NU BOP.
- 2. Release Packer and TOH w/ 2-3/8" tbg and packer, inspect and tally.
- 3. TIH w/ CIBP and set @ 4431'. Pressure test casing to 500 psi for 15 minutes. TOH w/ tbg.

4. TIH w/ tbg to 4026'. Set a cement plug across Pictured Cliffs top f/ 4031'-4131' w/ 18 sks of neat cement (50% excess). Pull tbg above cement. Wait 4 hrs and tag cement.

- 5. Pull tbg up to 3916'. Set a balanced cement plug across the Fruitland top f/ 3816'-3916' w/ 18 sks of neat cement (50% excess). Pull tbg above cement. Wait 4 hrs and tag cement.
- 6. Pull tbg up to 3670'. Set a balanced cement plug across the Kirtland top f/ 3570'-3670' w/ 18 sks of neat cement (50% excess). Pull tbg above cement. Wait 4 hrs and tag cement.
- 7. Pull tbg up to 3455'. Set a balanced cement plug across the Ojo Alamo top f/ 3355'-3455' w/ 18 sks of neat cement (50% excess). Pull tbg above cement. Wait 4 hrs and tag cement.
- 8. ND BOP and cut off casing below surface casing flange. Install P&A marker w/cement to comply w/ regulations. RDMO, cut off anchors and restore location.

- Plug Nuciments from 2308'-2208' inside + ourside to 5/2 costs

Plug Surface trum 182' to Surface inside + ourside do 5/2 costs

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: 11 San Juan 30-4 Unit

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made:
- a) Place the Pictured Cliffs plug from 4030' 3930' since the Pictured Cliffs perforations extent up to 4054'.
- b) Place a cement plug from 2308' 2208' inside and outside the 5 $\frac{1}{2}$ " casing to cover the Nacimiento top.
- c) Place the Surface plug from 182' to surface inside and outside the 5 1/2" casing.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.