

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENTFORM APPROVED  
OMB NO. 1004-0137  
Expires July 31, 2010

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 8

RECEIVED

MAR 26 2010

Bureau of Land Management  
Huntington Field Office

505-333-3100

1. Type of Well  
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

XTO ENERGY INC.

3a. Address  
382 CR 3100 AZTEC, NM 874104. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
990' FSL & 990' FEL SESE SEC 30 (P) - T27N-R11W

5. Lease Serial No.

NMNM-0359211

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No

8. Well Name and No  
FEDERAL 30 #44

9. API Well No.

30-045-24814

10. Field and Pool, or Exploratory Area

BASIN FRUITLAND COAL

W. KUTZ PICTURED CLIFF

11. County or Parish, State

SAN JUAN

NM

## 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

## TYPE OF SUBMISSION

- ☒
- Notice of Intent
- 
- ☐
- Subsequent Report
- 
- ☐
- Final Abandonment Notice

## TYPE OF ACTION

- |   |  |  |   |
|---|--|--|---|
| <input type="checkbox"/> Acidize              | <input type="checkbox"/> Deepen                      | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input type="checkbox"/> Alter Casing         | <input type="checkbox"/> Fracture Treat              | <input type="checkbox"/> Reclamation               | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Casing Repair        | <input type="checkbox"/> New Construction            | <input type="checkbox"/> Recomplete                | <input type="checkbox"/> Other _____    |
| <input type="checkbox"/> Change Plans         | <input checked="" type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon       |   |
| <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back                   | <input type="checkbox"/> Water Disposal            |   |

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

XTO Energy Inc. proposes to plug &amp; abandon this well per the attached procedure.

RCVD APR 5 '10

OIL CONS. DIV.

DIST. 3

Notify NMOCD 24 hrs  
prior to beginning  
operations

14. I hereby certify that the foregoing is true and correct
- 
- Name (Printed/Typed)

BARBARA A. NICOL

Title REGULATORY COMPLIANCE TECHNICIAN

Signature

Barbara A. Nicol

Date 03/24/2010

## THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by Original Signed: Stephen Mason

Title

Date

APR 02 2010

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

NMOCD

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

WFL\_\_\_\_

TJF\_\_\_\_

## Federal 30 #44 – Pictured Cliffs PLUG AND ABANDONMENT PROCEDURE

October 1, 2009

990' FSL & 990' FEL  
Unit P, Section 30, T27N, R11W  
San Juan County, NM API #30-045-24814  
Latitude: N \_\_\_\_\_ Longitude: W \_\_\_\_\_

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1 18 cf/sx yield.

1. This project requires the Operator to obtain an approved NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an approved steel tank to handle waste fluids circulated from the well and cement wash up.
2. Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
3. Rods: Yes ☒, No \_\_\_\_\_, Unknown \_\_\_\_\_;  
Tubing: Yes ☒, No \_\_\_\_\_, Unknown \_\_\_\_\_, Size 2-3/8", Length 1,734' Unknown \_\_\_\_\_;  
Packer: Yes \_\_\_\_\_, No ☒, Unknown \_\_\_\_\_, Type \_\_\_\_\_.
4. Round trip a 4.5" casing scraper to 1,600'; not a wireline gauge ring.
5. **Plug #1 (Pictured Cliffs & Fruitland Coal, 1,750' – <sup>1248</sup>1,550')**: TIH and set cement retainer at 1,600'. Mix ~~19~~ sxs cement and spot a balanced plug inside the casing to cover the Pictured Cliff and Fruitland Coal intervals. TOH.
6. **Plug #2 (Kirtland & Ojo Alamo, 770' – 500')**: TIH and set cement retainer at 700'. Mix 25 sxs cement and spot a balanced plug inside the casing to cover the Kirtland and Ojo Alamo intervals. TOH.
7. **Plug #3 (8 5/8" casing shoe, 198' – Surface)**: Mix approximately 19 sxs and pump cement inside the 4.5" casing to the surface. Shut in well and WOC.
8. ND BOP and cut off casing below surface casing flange. Install P&A marker with cement to comply with regulations. RD, move off location, cut off anchors and restore location.

**UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
FARMINGTON DISTRICT OFFICE  
1235 LA PLATA HIGHWAY  
FARMINGTON, NEW MEXICO 87401**

Attachment to notice of  
Intention to Abandon:

Re: Permanent Abandonment  
Well: 44 Federal 30

**CONDITIONS OF APPROVAL**

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
3. The following modifications to your plugging program are to be made:
  - a) Bring the top of the Pictured Cliffs/Fruitland plug to 1248'.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.