Form 3160-5

	August 2007)	SUNDRY Do not use th	UNITED STATEPARTMENT OF THIS BUREAU OF LAND MAD NOTICES AND REI is form for proposals ell. Use form 3160-3 (A	E INTE NAGEN PORTS to drill	MENT S ON WELLS Tor to re-enter an		OMBN	APPROVED 10. 1004-0135 : July 31, 2010 or Tribe Name		
		SUBMIT IN TR	IPLICATE - Other instr	ruction	s on reverse side.		7. If Unit or CA/Agre	ement, Name and/or h		
	<u>=</u>	⊠ Gas Well □ Ot	MUDGE A 40							
	Name of Operate BP AMERICA	or A PRODUCTION	9. API Well No. 30-045-21023-(00-S1						
3a. Address 200 ENERGY COURT FARMINGTON, NM 87401					Phone No. (include area code : 281-366-4081)		10. Field and Pool, or Exploratory BLANCO PICTURED CLIFFS		
	4. Location of Well (Footage, Sec., T., R., M., or Survey Description, Sec. 10 T31N R11W NWSW 1670FSL 0800FWL 36.91007 N Lat, 107.98341 W Lon						1	11. County or Parish, and State SAN JUAN COUNTY, NM		
	12	. CHECK APPI	ROPRIATE BOX(ES)	TO INI	DICATE NATURE OF N	OTICE	, REPORT, OR OTHER	R DATA		
	TYPE OF SUBMISSION				TYPE OF ACTION					
- -	Notice of Intent ☐ Subsequent Report ☐ Final Abandonment Notice		☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection		☑ Plug and Abandon		duction (Start/Resume) clamation complete nporarily Abandon ter Disposal	☐ Water Shut-O☐ Well Integrity☐ Other		
13	Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration the If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zo Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 day following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed of testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator had determined that the site is ready for final inspection.)									
	BP finds no further uphole potential for said well and respectfully request permission to plug the entire wellbore.									
	Please see the attached P8		A procedure.		H ₂ S POTENTIAL EXIST		RCVD APR	20'10		
							OIL CONS	i. DIV.		

DIST. 3

14. I hereby certify that the	ne foregoing is true and correct. Electronic Submission #84869 verified For BP AMERICA PRODUCTIO Committed to AFMSS for processing by STI	N ĆO.,	sent to the Farmings	ton		
Name (Printed/Typed)	CHERRY HLAVA	Title	REGULATORY A	NALYST		
Signature	(Electronic Submission)	Date	04/15/2010			
	THIS SPACE FOR FEDERA	AL OR	STATE OFFICE	USE		
Approved By STEPHE	N MASON	TitleF	PETROLEUM ENGI	NEER	Date 04/16/20	
certify that the applicant hol	ry, are attached. Approval of this notice does not warrant or ds legal or equitable title to those rights in the subject lease icant to conduct operations thereon.	Office Farmington				
Title 18 U.S.C. Section 1001	and Title 43 U.S.C. Section 1212, make it a crime for any po	rson kno	wingly and willfully to	make to any department of	or agency of the United	

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Mudge A 40 – PC PxA Procedure (Version 1)

General Information: Formation: PC Job Objective: Plug and Abandon Project #: 4/14/2010 Date: Engineer: Anne Hansford **p.** 281.366.8619 **c**. 713-540-3386 **Production Contact:** Rocky Deromedi **p.** 505.326.9471 **c.** 505.486.0942 Optimizer: Mike Mcmahen **p.** 505.326.9231 Backup Engineer:

Well Information:

Production Data:

API Number:	30-045-21023	Tubing Pressure:	172 psi
BP WI:	50%	Casing Pressure:	N/A
Run #:		Line Pressure:	156 psi
Surface Location:	Sec. 10, T31N, R11W	Pre-rig Gas Rate:	8 MCFD
Meter Number:	87539	Anticipated Uplift:	None
Well FLAC:		Water Rate:	
Cost Center:		CO2 (%):	0.5%
Lease FLAC:		H2S (PPM):	N/A
Restrictions:	N/A	Gas BTU:	1170
Regulatory Agency:	BLM	Artificial Lift Type:	1" CT
Compressed (Y/N):	N		

Basic Job Procedure:

Coil Tubing unit

- **1.** POOH 1", coil tubing @ 2716'
- 2. Set CIBP @ 2666'
- 3. Pressure test 2-7/8" casing
- **4.** Cement 2666' to 350' (CBL done in 1992 and bradenhead repair with returns to surface)
- 5. Pump a 242' cement surface plug from 242' to surface inside.

Safety and Operational Details:

ALL work shall comply with DWOP E&P Defined Operating Practice.

Well History:

The Mudge A 40- PC was completed as a 2-7/8" slimhole completion in 1972. A Bradenhead repair was done in 1992. In 1994 1" coil tubing was installed. In 1995 a clean out was done through the coil tubing.

The well has had a name change (Mudge LS 40 → Mudge A 40).

Standard Location Work:

 Perform pre-rig site inspection, size of location, gas taps, other wells, other operators, running equipment, wetlands, wash, H2S barriers if needed for equipment. Landowner issues, buried lines in pits, raptor nesting, critical location, check anchors. Check ID wellhead, determine if equipment is acceptable or obsolete and replace if necessary, if digging is required have One Call made 48 hours. Follow ground disturbance policy.

Created by Neevia Document Converter trial version http://www.neevia.com

- 2. Perform second site visit, checking anchors and barriers if needed. Ensure lines are marked so that they clearly designate pit locations. Discuss and turnover handover sheet with someone from operations team and wells team. LOTO all necessary equipment including but not limited to: meter run, automation, separator, and water line.
- 3. Notify BLM and NMOCD 24 hours prior to performing the work.
- 4. Hold pre-job safety meeting and discuss JSA with everyone on location. JSA should cover: heavy lifts, pinch points, location hazards, pressure hazards, proper PPE and 8 golden rules of safety/IFF. Make sure everyone has preformed their LOTO and knows they have the right to stop the job.
- Check and record casing pressure, intermediate, and Bradenhead pressures. Record all
 pressures into DIMS. <u>Notify engineer if Bradenhead pressures exist</u>. Check gas H2S
 content and treat if the concentration is > or equal to 10 ppm.
- 6. Insure double casing valves are installed. Spot and lay 3" line and tank to blow down well, record pressures while blowing well down if possible.
- 7. Blow down backside to flow back tank. Record the amount of time that it takes to blow down well.
- 8. RU pump truck and perform temporary kill.
 - a. TUBULAR VOLUME = 0.00107 bbl/ft
 - i. Tubing depth =2716'
 - ii. 3 bbls down tubing
 - b. CASING VOLUME 2-7/8" = 0.00579 bbl/ft
 - i. Depth = 2862' (perf at 2716')
 - ii. 23 bbls
 - c. TOTAL = 26 bbls.
- 9. Ensure well has gone on vacuum. Test that the well remains on vacuum for the amount of time that will be needed to ND wellhead and NU BOP (1 hour). Ensure extra kill fluid on location for ND of wellhead operation. The operations of removal of wellhead and installation of BOPS will be preformed under a dispensation SINCE NO MECHINCAL BARRIERS, ONLY KILL FLUID.
- 10. If well did not go on vacuum contact engineer for review of temporary kill step and permenant kill step.
- 11. Conduct a JSA and discuss the operation of ND wellhead and NU BOP with only kill fluid to ensure operation is as efficient as possible and exposure time is minimized during operation.
- 12. If well went on vacuum, perform permant kill.
 - a. TUBULAR VOLUME = 0.00107 bbl/ft
 - Tubing depth =2716'
 - ii. 3 bbls down tubing
 - b. CASING VOLUME 2-7/8" = 0.00579 bbl/ft
 - i. Depth = 2862' (perf at 2716')
 - ii. 23 bbls
 - c. TOTAL = 26 bbls.


- 13. RU CTU. If threaded tree flanges perform proper risk assessment for threaded connections. Use dual choke manifold or production choke for flow back. Fully function and pressure test BOP's to 250-psi low-pressure test, 1000-psi high-pressure test. If Shear Rams are not used in BOP stack, refer to local standard operating practice. Lubricator should be of adequate length to cover BHA. Dual flapper check valves should be run above BHA. If dual flapper check valves are not used a detailed and current assessment of risks, mitigations and contingency responses should be refer to, or a local standard operating practice.
- 14. RIH with coil-tubing to 2666' and set CIBP.
- 15. Pressure test 2-7/8" casing and ensure no issue with casing. 1992 CBL on file.
- 16. RIH with coil and spot **2316**' (75.27 cu ft) of G-Class cement inside 2-7/8" casing from **2666'-350**'. This will cover the Picture Cliff, Fruitland Coal interval, Kirtland and Ojo Formations.
- 17. POOH.
- 18. Rig down coil unit.
- 19. RU pump truck. Pump 7.8 cu ft cement from 200' to surface inside 2-7/8" casing. POOH.
- 20. Perform underground disturbance and hot work permits. Cut off tree.
- 21. If cement cannot be seen on all annulus and casing strings remedial cementing will be required from surface.
- 22. Release coil tubing unit.
- 23. Install well marker and identification plate per regulatory requirements. Dry hole marker should contain the following:

BP American Production Co. Mudge A 40 API 30-045-21023 Unit letter L, Sec 10, T31N, R11W 1670' FSL, 800 FWL San Juan, NM Picture Cliffs Formation Federal Lease number: SF 078040 P&A date - TBD

- 24. RD and release all equipment. Remove all LOTO equipment.
- 25. Ensure all reports are loaded into DIMS. Print out summary of work and place in Well file. Notify Sherri Bradshaw (326-9260) of completed P&A and Cherry Hlava.

Mudge A 40

Sec 10, T31N, R11W Unit L API #: 30-045-21023



Mudge A 40

Sec 10, T31N, R11W Unit L API#: 30-045-21023

