<u>ب</u>رځ

submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

KECEWED

MAY 18 2010

	Sundry Notices and Reports on Wells	···········		nton Field Office
	Sundry Notices and Reports on Wens		- Warnedua	All areas of the second
		5.		Number
	The CANAL III	,		F - 078640
۱.	Type of Well	6.		ian, All. or
	GAS		Tribe	Name
		7.		Agreement Name
2.	Name of Operator		San J	uan 28-7 Unit
	CONOCOPHILLIPS COMPANY	_		
		- 8.		Name & Number
3.	Address & Phone No. of Operator		San J	uan 28-7 Unit 217
	PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API V	Vell No.
-		-	30-03	9-20972
4.	Location of Well, Footage, Sec., T, R, M			
		10.	Field	and Pool
	Surf: Unit B (NWNE), 1120' FNL & 1740' FEL, Section 28, T27N, R7W, NMPM		Char	ca/Mesaverde
	2 2	11.		ty and State
		-		rriba Co., NM
	X Notice of Intent Abandonment Change of Plans Recompletion New Construction Subsequent Report Plugging Non-Routine Fracturing			Remove Fish/Isolate water/test csg HOY 21 '10
	Casing Repair Water Shut off		M í	ONS. DIV.
	Final Abandonment Altering Casing Conversion to Injection			NGT 9
Conec	Describe Proposed or Completed Operations nocoPhillips wishes to retrieve fish in the hole, isolate water producing zone, clean out to PB tessary & perform a casing test. Current Schematic and procedures are attached. I hereby certify that the foregoing is true and correct. Interest of the proposed or Completed Operations I have been described in the procedure of the producing zone, clean out to PB tessary & perform a casing test. Current Schematic and procedures are attached. I hereby certify that the foregoing is true and correct. I have been described in the procedure of the procedure			bad jts as 05/14/2010
(Tł AP	nis space for Federal or State Office use) PROVED BY Original Signed: Stephen Mason Title		Date	MAY 1 9 2010
			- Date _	
	PROVED BY Crightal Original Stephen Made I Itle NDITION OF APPROVAL, if any: 18 U S C Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of		_ Date _	

Notify NMOCD 24 hrs prior to beginning operations

ConocoPhillips SAN JUAN 28-7 UNIT 217

Expense - Repair Tubing

Lat 36° 32' 53.801" N

Long 107° 34' 37.812" W

PROCEDURE

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCl, if necessary.
- 4. ND wellhead and NU BOPE. PU and remove tubing hanger and tag for fill, adding additional joints as needed (tubing currently landed @ 5182', PBTD @ 6263') . Record fill depth in Wellview.
- 5. TOOH with tubing (details below).

	Number	Description
•	1	2-3/8" Tubing joint (31')
	3	2-3/8" pup joint (34')
	165	2-3/8" tubing joints
	1	2-3/8" F nipple (ID 1.78")
	1	1-1/2" Mule shoe guide

Use Tuboscope Unit to inspect tubing and record findings in Wellview. Make note of corrosion or scale. LD and replace any bad joints. If needed, contact Rig Superintendent or engineer for acid, volume, concentration, and displacement volume.

- 6. If fill is tagged, utilize the air package and CO to PBTD (6263'). If fill could not be CO to PBTD call Production Engineer to inform how much fill was left and confirm/adjust landing depth.
- 7. TIH with packer and RBP, set the RBP 50' above top MV perfs 5115', set the packer and test RBP 500 PSI for 5 min, unset packer and perform MIT for 30 min at 560 PSI in a 2 hrs chart. if water source is from this interval, find the leak and fix it, If the water source is not from 5115' to surface, unset RBP and set the packer 50 below bottom MV perfs at 5385', perform MIT from 5385' to CR, for 30 min at 560 PSI in 2 hrs chart. If water is not source from this interval then perform 5 hrs flow test to determine the accurate water production of MV, if water production is less than 6 barrels per day go to step 8, if water production is more than 7 barrels per day P&A the well. Notify Production Engineer. Note: Inform 24 hrs before regulatory agency, any Squeeze, cement plug or CIBP to isolate water source.
- 8. TIH with tubing using Tubing Drift Procedure. (detail below).

Recommended

	
Tubing Drift ID:	1.5011
Land Tubing At:	S182'
Land F-Nipple At:	5181

Number	Description
1	1-1/2" Mule shoe guide
1	2-3/8" F nipple (ID 1.78")
169	2-3/8" tubing joints

- 9. If there is an air package on location, skip to the next step. Run standing valve on shear tool, load tubing, and pressure test to 500#. Monitor pressure for 15 mins, and make a swab run to remove the fluid from the tubing. Retrieve standing valve.
- 10. ND BOPE, NU Wellhead. Pressure test tubing slowly with an air package as follows: pump 3 bbls pad, drop steel ball, pressure tubing up to 500 psi, and bypass air. Monitor pressure for 15 mins., then complete the operation by pumping off the expendable check. Note in Wellview the pressure in which the check pumped off. Notify the MSO that the well is ready to be turned over to Production Operations. Make swab run to kick-off the well, if necessary, then RDMO.

Tubing Drift Check

Procedure

- 1. Set flow control in tubing. With air, on location, use expendable check. With no air on location, use wire line plug.
- 2. RU drift tool to a minimum 70' line. Drift tool will have an OD of at least the API drift specification of 1.901" for the 2 3/8",4.7# tubing, and will be at least 15" long. The tool will not weigh more than 10# and will have an ID bore the length of the tool, so fluids may be pumped through the tool if it becomes stuck.
- 3. Drop the tool into the tubing string and retrieve it after every 2 joints of tubing ran in hole. If any resistance to the tool movement is noticed, going in or out, that joint will be replaced.
- 4. In order to stimulate the plunger lift operation, all equipment must be kept clean and free of debris.

The drift tool should be measured with calipers before each job, to ensure the OD is the correct size for the tubing being checked. The maximum allowable wear of the tool is .003".

