

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

RECEIVED

AUG 03 2010

Sundry Notices and Reports on Wells

Farmington Field Office
Bureau of Land Management1. Type of Well
GAS5. Lease Number
SF - 0784216. If Indian, All. or
Tribe Name

7. Unit Agreement Name

2. Name of Operator

BURLINGTON

RESOURCES OIL & GAS COMPANY LP

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

8. Well Name & Number
McAdams A 1S

9. API Well No.

30-045-34357

4. Location of Well, Footage, Sec., T, R, M

Surf: Unit D (NWNW), 910' FNL & 950' FWL, Section 20, T27N, R9W, NMPM

10. Field and Pool

Basin FC

11. County and State
San Juan Co., NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☒ Notice of Intent☐ Abandonment☐ Change of Plans☒

Other -

Retrieve Fish/C/O to
PBTD☐ Subsequent Report☐ Recompletion☐ New Construction☐ Plugging☐ Non-Routine Fracturing☐ Casing Repair☐ Water Shut off☐ Final Abandonment☐ Altering Casing☐ Conversion to Injection

13. Describe Proposed or Completed Operations

Burlington Resources wishes to C/O to PBTD, retrieve stuck equipment and replace any bad jts as necessary per attached Procedures and well bore schematic.

RCVD AUG 5 '10

OIL CONS. DIV.

DIST. 3

14. I hereby certify that the foregoing is true and correct.

Signed

Jamie Goodwin

Jamie Goodwin Title

Regulatory Technician

Date

8/3/10

(This space for Federal or State Office use)

APPROVED BY Original Signed: Stephen Mason Title

Date

AUG 04 2010

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

NMOC

ConocoPhillips
MCADAMS A 1S
Expense - Repair Tubing

Lat 36° 33' 54.439" N

Long 107° 48' 59.774" W

PROCEDURE

Prior to pulling tubing install locking 3 slip stop above obstruction.

1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
3. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCl, if necessary.
4. ND wellhead and NU BOPE. PU and remove tubing hanger and tag for fill, adding additional joints as needed (tubing currently landed @ ', PBTD @ 2428') . Record fill depth in Wellview.

5. TOOH with tubing (details below).

Number	Description
70	2-3/8" Tubing joints
1	2-3/8" pup joint (2')
1	2-3/8" tubing joint
1	2-3/8" F nipple (ID 1.78")
1	Expandable Check

Use Tuboscope Unit to inspect tubing and record findings in Wellview. Make note of corrosion or scale. LD and replace any bad joints. If needed, contact Rig Superintendent or engineer for acid, volume, concentration, and displacement volume.

6. If fill is tagged, PU bailer and CO to PBTD (2428'). If fill is too hard or too much to bail, utilize the air package. If fill could not be CO to PBTD call Production Engineer to inform how much fill was left and confirm/adjust landing depth.

7. TIH with tubing using Tubing Drift Procedure. (detail below).

Recommended

Tubing Drift ID:	1.901"
Land Tubing At:	2230'
Land F-Nipple At:	2228'

Number	Description
1	Expandable Check
1	2-3/8" F-nipple
1	2-3/8" full tubing joint
1	2-3/8" pup joint (4.1')
70	2-3/8" tubing joints

8. If there is an air package on location, skip to the next step. Run standing valve on shear tool, load tubing, and pressure test to 500#. Monitor pressure for 15 mins, and make a swab run to remove the fluid from the tubing. Retrieve standing valve.

9. ND BOPE, NU Wellhead. Pressure test tubing slowly with an air package as follows: pump 3 bbls pad, drop steel ball, pressure tubing up to 500 psi, and bypass air. Monitor pressure for 15 mins., then complete the operation by pumping off the expendable check. Note in Wellview the pressure in which the check pumped off. Notify the MSO that the well is ready to be turned over to Production Operations. Make swab run to kick-off the well, if necessary, then RDMO.

