# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCT 01 2010

	Sundry Notices and Reports on Wells	1	Bureau of	gton Field Office Land Manageme
	·	5.		Number
۱.	Type of Well	6.	JIC 10 If India	4 an, All. or
	GAS		Tribe N	Vame
		7		Apache
2.	Name of Operator	7.	Unit A	greement Name
	ConocoPhillips			
		0	Wall N	ama C. Nisambas
3.	Address & Phone No. of Operator	- 8.	Jicarill	ame & Number a E 9
	PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	. API W	ell No.
		-	30-039-	-20103
1.	Location of Well, Footage, Sec., T, R, M	10.	Field a	nd Pool
	Unit B (NWNE), 1135' FNL & 1605' FEL, Section 16, T26N, R4W, NMPM	10.		PC / Blanco M
		11.		and State riba, NM
•	Type of Submission  X Notice of Intent Abandonment Recompletion Subsequent Report Plugging Casing Repair Change of Plans New Construction Non-Routine Fracturing Water Shut off	<u>X</u>	Other -	Commingle
	Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection			
3.	Describe Proposed or Completed Operations			
	ocoPhillips Company requests permission to remove the packer in the subject well in order averde per the attached procedure and current wellbore schematic. The DHC will be filed.	to com	RCVD DIL C	Pictured Cliffs : OCT 7'10 DNS. DIV.
			Ē.,	. Ware E. H. E. T.
	hereby certify that the foregoing is true and correct.	34 C	7110	<b>&gt;</b>
4.		2/ Q	1146	
<b>4.</b> I		- 1		Date _10/1/6

## ConocoPhillips JICARILLA E 9

### **Rig Uplift - Commingles**

Lat 36° 29' 27.056" N

Long 107° 15' 10.728" W

NOTE: Install a locking three-slip stop in the Mesaverde tubing above 5936'. There are tools stuck in the tubing.

#### **PROCEDURE**

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCl, if necessary.
- 4. ND dual wellhead. PU and remove Pictured Cliffs tubing hanger. TOOH with tubing (details below).

Number	Description
120	2-3/8" 4.7# J-55 Tubing Joints
1	2-3/8" OD (1.78" ID) Seat Nipple
1	2-3/8" Muleshoe

Use Tuboscope Unit to inspect tubing and record findings in Wellview. Make note of corrosion or scale. LD any bad joints. If needed, contact Rig Superintendent or engineer for acid, volume, concentration, and displacement volume.

- 5. ND wellhead and NU BOPE. PU and remove tubing hanger. Release packer and tag for fill, adding additional joints as needed (tubing currently landed @ 6019', PBTD @ 7833') . Record fill depth in Wellview.
- 6. TOOH with Mesaverde tubing (details below).

Number	Description
126	2-3/8" 4.7# J-55 Tubing Joints
1	4" OD Baker Model "R" Packer
65	2-3/8" 4.7# J-55 Tubing Joints
1	2-3/8" OD (1.78" ID) Seat Nipple
1	2-3/8" Muleshoe

Use Tuboscope Unit to inspect tubing and record findings in Wellview. Make note of corrosion or scale. LD and replace any bad joints. If needed, contact Rig Superintendent or engineer for acid, volume, concentration, and displacement volume.

- 7. If fill is tagged, PU bailer and CO to PBTD (7833'). If fill is too hard or too much to bail, utilize the air package. If fill could not be CO to PBTD call Production Engineer to inform how much fill was left and confirm/adjust landing depth.
- 8. TIH with tubing using Tubing Drift Procedure. (detail below).

# Recommended Tubing Drift ID: 1.901" Land Tubing At: 6012' Land F-Nipple At: 6010'

Number	Description
1	2-3/8" Muleshoe
1	2-3/8" OD (1.78" ID) F-Nipple
1	2-3/8" 4.7" J-55 Tubing Joint
1	2-3/8" 4.7# J-55 Pup Joint (4')
188	2-3/8" 4.7" J-55 Tubing Joints
As Needed	2-3/8" 4.7# J-55 Pup Joints
1	2-3/8" 4.7" J-55 Tubing Joint

- 8. If there is an air package on location, skip to the next step. Run standing valve on shear tool, load tubing, and pressure test to 500#. Monitor pressure for 15 mins, and make a swab run to remove the fluid from the tubing. Retrieve standing valve.
- 9. ND BOPE, NU Wellhead. Pressure test tubing slowly with an air package as follows: pump 3 bbls pad, drop steel ball, pressure tubing up to 500 psi, and bypass air. Monitor pressure for 15 mins., then complete the operation by pumping off the expendable check. Note in Wellview the pressure in which the check pumped off. Notify the MSO that the well is ready to be turned over to Production Operations. Make swab run to kick-off the well, if necessary, then RDMO.

### **Tubing Drift Check**

### **Procedure**


- 1. Set flow control in tubing. With air, on location, use expendable check. With no air on location, use wire line plug.
- 2. RU drift tool to a minimum 70' line. Drift tool will have an OD of at least the API drift specification of 1.901" for the 2 3/8",4.7# tubing, and will be at least 15" long. The tool will not weigh more than 10# and will have an ID bore the length of the tool, so fluids may be pumped through the tool if it becomes stuck.
- 3. Drop the tool into the tubing string and retrieve it after every 2 joints of tubing ran in hole. If any resistance to the tool movement is noticed, going in or out, that joint will be replaced.
- 4. In order to stimulate the plunger lift operation, all equipment must be kept clean and free of debris.

The drift tool should be measured with calipers before each job, to ensure the OD is the correct size for the tubing being checked. The maximum allowable wear of the tool is .003".

### Current Schematic

### ConocoPhillips

Well Name: JICARILLA E 009



Page 1/1

Report Printed: 9/13/2010