Form 3160-5 (August 2007)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.  SUBMIT IN TRIPLICATE - Other instructions on reverse side.  1. Type of Well  Gas Well  Other						Lease Serial No.     JIC109     If Indian, Allottee or Tribe Name		
						7. If Unit or CA/Agreement, Name and/or No.		
						8. Well Name and No. JICARILLA B 3M		
-	Name of Operator ENERVEST OPERATING, L.	Contact:	BRIDGET HELFRICH @enervest.net			9. API Well No. 30-039-29638		
_	3a. Address 1001 FANNIN STREET SUIT HOUSTON, TX 77002	3b. Phone No. (include area code) Ph: 713-495-6537 Fx: 713-615-1429			10. Field and Pool, or Exploratory BASIN DAKOTA			
-	4. Location of Well (Footage, Sec.,	n)			11. County or Parish.	and State		
	Sec 15 T26N R5W NWSE 19				RIO ARRIBA COUNTY, NM			
	12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
	TYPE OF SUBMISSION	TYPE OF ACTION						
	Nation of Intent	☐ Acidize	Acidize Deepen Pro		☐ Producti	on (Start/Resume)	☐ Water Shut-Off	
	Notice of Intent  Notice of Intent	Alter Casing	☐ Fracture	Treat	☐ Reclama	tion	☐ Well Integrity	
	☐ Subsequent Report	Casing Repair	☐ New Con		Recomp		Other	
_	☐ Final Abandonment Notice	Change Plans	Plug and		_	rily Abandon		
(	<b>–</b>	Convert to Injection	_	Plug Back				
	testing has been completed. Final Aldetermined that the site is ready for f	inal inspection.)	ed only after all requir	ements, inclu	ding reclamation	, have been completed,	and the operator has	
		CONDIT	IONS OF ADE	POWI				
	Notify NMOCD 24 hrs	Notify NMOCD as Inc.  CONDITIONS OF APPROVAL Adhere to previously issued stipulations.				RCVD OCT 28'10		
	prior to beginning	reviously issued supulations.			OIL CONS. DIV.			
	operations							
				٠		DE	ī. 3	
							·	
丁	4. Thereby certify that the foregoing is	Electronic Submission #9	94905 verified by the PERATING, L.L.C.	ne BLM Wel , sent to the	I Information S e Rio Puerco	System		
	Name (Printed/Typed) BRIDGET	Title	Title REGULATORY TEC					
	Signature (Electronic S	ubmission)	, Date	10/14/2	010			
		THIS SPACE FO	R FEDERAL OF	RSTATE	OFFICE USI			
A	pproved By	m m	Title	÷	PE	·	Dat OCT 2 5 20	
cer	nditions of approval, if any, are attached tify that the applicant holds legal or equ ich would entitle the applicant to condu-	itable title to those rights in the		ce	Fau			
Titl S	e 18 U.S.C. Section 1001 and Title 43 tates any false, fictitious or fraudulent st	J.S.C. Section 1212, make it a clatements or representations as t	rime for any person k o any matter within it	nowingly and sjurisdiction.	willfully to mak	e to any department or	ngency of the United	

\*\* OPERATOR OURMITTER \*\* OPERATOR CURMITTER \*\*

# PLUG AND ABANDONMENT PROCEDURE

# Jicarilla B #3M

Basin Dakota / Blanco Mesaverde
1900' FSL, 2300' FEL, Section 15, T26N, R5W, Rio Arriba County, New Mexico
API 30-039-29638/ Lat: 36.485142 N Long: -107.344987 W

All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.
 Install and test location rig anchors. Prepare a blow pit. Comply with all State, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the

	tubing. ND wellhead and NU BOP. Function test BOP.					
2.	Rods: Yes, NoX, Unknown Tubing: Yes, NoX, Unknown, Size, Length Packer: Yes, NoX, Unknown, Type If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.					
	TIH with open ended tubing.					
	7311					
3.	Plug #1 (Dakota top, 7510' - 7410'): Attempt to pressure test casing to 800 PSI. If casing does not test, then spot or tag subsequent plugs as appropriate. Mix 1/2 sxs Class B cement and spot a					

4. Plug #2 (Gallup top, 6388' – 6288'): Perforate 3 HSC holes at 6388'. If casing tested, then establish injection rate into squeeze holes. TIH with cement retainer and set at 6338'. Pressure test tubing to 1000 PSI. Mix and pump 30 sxs cement, squeeze 18 sxs outside casing and leave 12 sxs inside to cover the Gallup top. TOH with tubing.

balanced plug inside the casing to cover the Dakota top. TOH with tubing.

- 5. Plug #3 (Mesaverde top, 4887' 4787'): Perforate 3 HSC holes at 4887'. If casing tested, then establish injection rate into squeeze holes. TIH with cement retainer and set at 4837'. Mix and pump 30 sxs cement, squeeze 18 sxs outside casing and leave 12 sxs inside to cover the Mesaverde top. TOH with tubing.
- 6. Plug #4 (Chacra top, 4110' 4010'): Perforate 3 HSC holes at 4110'. If casing tested, then establish injection rate into squeeze holes. TIH with cement retainer and set at 4060'. Mix and pump 30 sxs cement, squeeze 18 sxs outside casing and leave 12 sxs inside to cover the Chacra top. TOH with tubing.

# PLUG AND ABANDONMENT PROCEDURE

#### Jicarilla B #3M

# Continued:

Page 2 of 2

- 7. Plug #5 (7" casing shoe and 4.5" liner top, 3550' 3193'): Perforate 3 HSC holes at 3550'. If casing tested, then establish injection rate into squeeze holes. Mix and pump 84 sxs cement, queeze 47 sxs outside casing and leave 37 sxs inside to cover the 7" casing shoe and 4.5" liner top. PUH.
- 8. Plug #6 (Pictured Cliffs, Fruitland, Kirtland and Ojo Alamo tops, 3142' 2466'): Mix 133 sxs Class B cement and spot a balanced plug inside casing to cover the Pictured Cliffs, Fruitland, Kirtland and Ojo Alamo tops. PUH.

1264 1164

- 9. Plug #4 (Nacimiento top, 1496' 1396'): Mix 28 sxs Class B cement and spot a balanced plug inside casing to cover Nacimiento top. PUH.
- 10. Plug #5 (9.625" casing shoe, 366' 0'): Connect the pump line to the bradenhead valve and attempt to pressure test the BH annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 70 sxs Class B cement and spot a balanced plug inside the casing from 366' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the 7" casing and BH annulus from 366' to surface. Shut well in and WOC.
- 11. ND BOP and cut off wellhead below surface casing flange. Install P&A marker with cement to comply with regulations. RD, MOL and cut off anchors. Restore location per BLM stipulations.