

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)


1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR
Getty Oil Company
3. ADDRESS OF OPERATOR
P.O. Box 3360, Casper, WY 82602-3360
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FSL & 1980' FWL of Sec 27
AT TOP PROD. INTERVAL: same
AT TOTAL DEPTH: same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☒
(other) ☐

SUBSEQUENT REPORT OF:

- ☐
☐
☐
☐
☐
☐
☐
☐
☐
☐




5. LEASE
Contract #34
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache
7. UNIT AGREEMENT NAME
-
8. FARM OR LEASE NAME
Jicarilla "C"
9. WELL NO.
23
10. FIELD OR WILDCAT NAME
Otero Gallup
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
N, Section 27-T25N-R5W
12. COUNTY OR PARISH
Rio Arriba
13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
6593' DF

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Getty Oil Company proposes to plug and abandon this well according to the attached procedure.



Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Mr. A. H. H. H. TITLE Superintendent DATE _____


(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

John F.

NMOCC

*See Instructions on Reverse Side



PLUG AND ABANDONMENT PROCEDURE

Jicarilla "C" No. 23

RECEIVED

JUL 13 1983

OIL CON. DIV.
DIST. 3

1. Move in and rig up workover unit.
2. Nipple down wellhead, nipple up BOP.
3. Trip out of hole with tubing. If tubing will not come free rig up a wireline unit and run a freepoint on the tubing. Back the tubing off above the freepoint. Trip out of hole with the free tubing. Trip in hole with jars and try to pull tubing loose with jars. If jars do not work, use washover pipe to remove the tubing.
4. Trip in hole with tubing. Circulate out the mud in the casing with 9.2 ppg mud to PBTD (6251').
5. Spot 26 sacks of Class "B" cement from 6251' to 6020'.
6. Trip out of hole with tubing.
7. Move in rig up wireline unit. Run in hole with perforating gun to 4293'. Perforate the casing with 4 spf and 0.50" EHD at 4293'. Pull out of hole with perforating gun. Run in hole with cement retainer. Set cement retainer at 4285'.
8. Trip in with tubing. Sting into cement retainer, establish injection rate with water. Sting out of cement retainer. Spot cement at end of tubing. Sting into cement retainer.
9. Squeeze 30 sacks of Class "B" cement into perfs.
10. Spot 12 sacks of Class "B" cement from 4285' to 4179'.
11. Spot Class "B" cement plugs with 9.2 ppg mud in between plugs at the following intervals:

<u>Formation</u>	<u>Interval</u>	<u>No. of Sacks</u>
Chacra	3635' - 3529'	12
Pictured Cliffs	2762' - 2656'	12
Ojo Alamo	2372' - 2213'	18

12. Move in rig up wireline unit. Run freepoint on 5 1/2" production casing. Cut off casing above freepoint. Trip out of hole with casing.
13. Spot 24 sacks of Class "B" cement with 50' inside the casing stub and 50' on top of casing stub.
14. Spot 42 sacks of Class "B" cement from 354' to 254'.
15. Trip out of hole with tubing. Wait on cement 24 hours.

Jicarilla "C" No. 23
Plug and Abandonment Procedure

16. Trip in hole with tubing. Tag cement with work string to check plugs.
17. Spot 25 sacks Class "B" cement from 56' to 4'.
18. Cut all casing off 4' below restored surface.
19. Set dry hole marker. Dry hole marker will be minimum of 4" diameter, 10' long and must be embedded in cement. It will have welded on it or permanently inscribed the following information:

Jicarilla "C" No. 23
Unit N, Sec. 27-T25N-R5W
Rio Arriba County, New Mexico

20. Restore location to BIA requirements.

RECEIVED
JUL 17 1963
OIL COR. DIV.
DIST. 3