

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☐ OTHER <u>SWD</u>	2. NAME OF OPERATOR <u>CONOCO INC.</u>	3. ADDRESS OF OPERATOR <u>P. O. Box 460, Hobbs, N.M. 88240</u>	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>Unit A</u> <u>915' ENL & 330' FEL</u>	5. LEASE DESIGNATION AND SERIAL NO. <u>Contract No. 41</u>	6. IF INDIAN, ALLOTTEE OR TRIBE NAME <u>Jicarilla Apache</u>	7. UNIT AGREEMENT NAME	8. FARM OR LEASE NAME <u>Jicarilla 30</u>	9. WELL NO. <u>1</u>	10. FIELD AND POOL, OR WILDCAT <u>Undesignated Mesaverde</u>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 30 - 25N - 4W</u>	12. COUNTY OR PARISH <u>Rio Arriba</u>	13. STATE <u>NM</u>
14. PERMIT NO. <u>30-039-05828</u>	15. ELEVATIONS (Show whether DF, RT, GR, etc.)											

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐				
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐				
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐				
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐					
(Other) <u>RPC CSG</u>							

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- ① MIRU
- ② Install lubricator and run GR-CBL-VDL-CCL from 5450' to 4500'
- ③ Determine depth to set CIBP for sqz operations.
- ④ RIH w/ CIBP & sqz pkr. Pull pkr 200' above leak and set.
- ⑤ Sqz csg leak as follows:
 - a. load backside w/ 1000 psi surface pressure
 - b. Estab. pump-in rate
 - c. Follow w/ 30 bbls of 10 ppg brme
 - d. Pump 100 sx5 Class "B" neat down tubing
 - e. Displace cmt 50 ft. below pkr.
 - f. hesitation sqz remaining 2.3 bbls of slurry until sqz press is obtained (not to exceed 1000 psi surf press.)
 - g. Shut well in for 24 hrs.
- ⑥ Drill out cmt to a depth 20' below sqz hole
- ⑦ Close casing valve & press. test to 1300 psi and hold for 15 min. (cont.)

18. I hereby certify that the foregoing is true and correct

SIGNED <u>[Signature]</u>	TITLE <u>Administrative Supervisor</u>	DATE <u>11-19-85</u>
(This space for Federal or State office use)		

APPROVED BY _____	TITLE _____	DATE <u>NOV 22 1985</u>
CONDITIONS OF APPROVAL, IF ANY:		

*See Instructions on Reverse Side

- ⑧ If pressure holds, drill through CIBP. If not resqueeze if necessary.
- ⑨ Set pkr @ 5120' and return to injection
- ⑩ Verbal app'l of this procedure given by Ernie Busch w/NMOC on 11/18/85 and Jim Lovato w/BLM on 11/18/85.