Form 3160-5 Budget Bureau No. 1004-0135 UNITED STATES SUBMIT IN TRIPLICATE. (November 1983) Expires August 31, 1985 DEPARTMENT OF THE INTERIOR (Other in instructions (Formerly 9-331) 5. LEASE DESIGNATION AND SERIAL NO BUREAU OF LAND MANAGEMENT SF 079601 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.) ī 7. UNIT AGREEMENT NAME GAS Well OTHER 8. FARM OR LEASE NAME NAME OF OPERATOR Texaco, Inc. (505)325-4397Lydia Rentz ADDRESS OF OPERATOR 9. WELL NO. 3300 N. Butler, Farmington, NM 87401 #6 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) 10. FIELD AND POOL, OR WILDCAT At surface Basin Fruitland 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA 1190' FSL and 1450' FWL of Sec. 20 N-Sec 20 PACH R3W 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR. etc.) 12. COUNTY OR PARISE | 13. STATE 7366' DF Rio Arriba NM 16 Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO SUBSEQUENT REPORT OF: BEPAIRING WELL TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF FRACTURE TREAT MULTIPLE COMPLETE PRACTURE TREATMENT ALTERING CASING SHOOT OR ACIDIZE ABANDON' REPAIR WELL CHANGE PLANS NOTE: Report result of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) Recomplete X 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) * Texaco Producing Inc. proposes the following workover to recomplete in the Basin Fruitland formation. The following procedure will be followed: Install BOP w/pipes and blind rams. RIH w/cement retainer on 2-3/8", workstring. Set retainer @ 3740'. Establish injection rate and squeeze Pictured Cliffs perforation 3. w/150 sks low fluid loss cmt. Pull up and spot 2 sks on top of Reverse out excess out excess cmt. 4. RU wireline service and run GR/CNL. Perforate Basin Fruitland w/ 2 JSPF (intervals to be picked after logging). .6. w/treating packer and SN and acidize w/200 gal. 7.5% HCl, NEFe acid per foot of pay. Flush w/fresh water to bottom of perf. Shut in for 45 minutes. Flow/swab back load. Test well. If frac job is necessary, kill well and pull production tbg. RIH w/treating pkr on 3-1/2" frac tbg and set 50' above perfs. 10. Frac w/60,000 gal. X-link gel carrying 192,500 lbs. 20/40 brady sand. Immediately flush back. 11. Release packer and reverse out frac sand. POH w/treating equip. 12. Run production equipment and test. y/that the soregoing is true and correct

SIGNED TITLE _ DATE _ Area Manager 5-21-90 (This space for Federal or State office use) APPROVED BY TITLE APPROVED NMOCO CONDITIONS OF APPROVAL, IF ANY: BLM-Farm(6), NMOGCC(4), RSL, AAK, MLK, MAG

*See Instructions on Reverse Side

TEHEN MASON AREA MANAGER