## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

-	ices and Reports on Wel		
		5.	Lease Number SF-078885
Type of Well		6.	If Indian, All. o
GAS		_	
Name of Orangham		7.	Unit Agreement Na
Name of Operator			
RESOURCES OU			
1ESCOTTOES OIL	& GAS COMPANY	٥	Canyon Largo Unit . <b>Well Name &amp; Numbe</b>
Address & Phone No. of Opera	tor	O	Canyon Largo U #2
PO Box 4289, Farmington, NM		9	. API Well No.
		_	30-039-20805
Location of Well, Footage, Sec., T, R, M 1150'FNL, 800'FEL, Sec.3, T-25-N, R-6-W, NMPM		O. Field and Pool	
1150'FNL, 800'FEL, Sec.3, T-	25-N, R-6-W, NMPM	1	Basin Dakota  1. County and State
		_	Rio Arriba Co, N
. CHECK APPROPRIATE BOX TO IN	DICATE NATURE OF NOTICE	, REPORT, OTH	ER DATA
Type of Submission	Type of Ac	tion	
$_{ m X}_{ m }$ Notice of Intent	Abandonment _	Change of	Plans
Colora month. Dans and	Recompletion	New Constr	uction o Eracturina
Subsequent Report	Plugging Back Casing Repair		C 5:
Final Abandonment	Casing Repair _ Altering Casing _	— Conversion	to Injection
	X Other - Tubing re	pair	,
It is intended to repair	the tubing in the subje		
It is intended to repair	_		
It is intended to repair	the tubing in the subje		
It is intended to repair	the tubing in the subje		
It is intended to repair	the tubing in the subje		
It is intended to repair	the tubing in the subje		
It is intended to repair	the tubing in the subje		
It is intended to repair	the tubing in the subje		
It is intended to repair	the tubing in the subje		
It is intended to repair	the tubing in the subje		
It is intended to repair	the tubing in the subje		
It is intended to repair	the tubing in the subje		
It is intended to repair	the tubing in the subje		
It is intended to repair	the tubing in the subje		
It is intended to repair	the tubing in the subje		
It is intended to repair attached procedure	the tubing in the subje	ce stipulation	
It is intended to repair attached procedure	the tubing in the subject. Please provide surfa	correct.	ns.
It is intended to repair attached procedure  4. I hereby certify that the igned	the tubing in the subject Please provide surfa	correct.	ns.
It is intended to repair attached procedure attached procedure igned to repair attached procedure attached p	the tubing in the subject. Please provide surfa	correct.	ns.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## Canyon Largo Unit 252

## Dakota

## 1150' FNL & 800' FEL

Unit A Section 03, T25N, R06W

Latitude / Longitude: 36° 25.944' / 107° 26.8782'

DPNO: 4479301 **Tubing Repair Procedure** 

Project Summary: The Canyon Largo Unit 252 was drilled in 1974. The tubing has not been pulled since originally drilled. The wireline report indicates there is a hole in the tubing, and it is not lifting liquid (see attached report). We propose to replace the 1-1/2" tubing with 2-3/8" tubing. Three month average production is 85 MCFD. Estimated uplift is 45 MCFD gross. Cumulative production is 1,585 MMCF.

- Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental 1. regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- 2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCl water if necessary. ND wellhead and NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- The Dakota tubing is 1-1/2", 2.9#, Cl "A" set at 7350'. Release donut, pick up additional joints of tubing 3. and tag bottom (record depth.) PBTD should at +/- 7453'. TOOH with 1-1/2" tubing. Lay down the 1-1/2" tubing. Visually inspect tubing for corrosion and scale build up. Notify Operations Engineer with findings.
- Pick up 2-3/8", 4.7#, J-55 EUE tubing (new or yellow banded). If fill is encountered TIH with 3-7/8" bit 4. and a watermelon mill with tubing to below perforations, cleaning out with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary. TOOH with tubing. NOTE: When using air/mist, minimum mist rate is 12 bph.
- TIH with an expendable check, a seating nipple, 1 jt 2-3/8", a 2' x 2-3/8" sub and ½ of the 2-3/8" 5. production string. Run a broach on sandline to insure that the tubing is clear. TIH with remaining tubing and broach this tubing. Replace any bad joints. Land tubing at approximately 7300'. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow on its own, make swab run to SN. During cleanout operations the reservoir may be charged with air. As a result of excess oxygen levels that may be in the reservoir and/or wellbore, contact the Lease Operator to discuss the need for determining oxygen levels prior to returning the well to production. RD and MOL. Return well to production.

Approved: Bruce D. Bowy 21-04
Drilling Superintendent

Sundry Required: VESINO Surgishing

Approved: May Cale 2-1-01 Recommended: Tim Friesenhahn Operations Engineer

326-9539 (Office) 326-8113 (Pager)

326-8303 (Pager) Production Foreman Ward Arnold 326-9846 (Office) Richard Lopez 320-6573 (Cell) 326-8681 (Pager) Specialist: 320-2585 (Cell) 326-8147 (Pager) Lease Operator: Ed Goodwin